

AVN NAVSAFECEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CODED

REVISED

REASON

POSITION

VERIFIED

17 JUL 1968

RECORD IDENTIFICATION											Aircraft Model										AIRCRAFT BUREAU NUMBER										Time of Mishap									
Date			Type Report	Log Line Number	Aircraft Number	Source	Don't Count	Enemy Action	Mission Modif.	Basic Mission	Design Number	Series Symbol	Model Code	Reporting Custodian	Type Duty	Major Command	CONDITION	LOCAL TIME																						
Cal. Yr.	Mo.	Day																37	38	39	40	41																		
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
6	9	9	5	0	7	1	0	3	0	1																														

Location										FAC. RWAY DESCRIP.										FAC. SHIP DESCRIP.										Card Number																													
NAME CODE										WAS DUTY RWAY USED?										LOC'N										Trans. Code																													
Kind of Flight										Ship Type										Ship Course										Ship Speed										Initial Contact										Final Rest									
42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																					
A	A	A	A																																																								

RELATIVE WIND										Alt. of Emergency										Aircraft Injury Summary										Card Number									
Direction		Velocity		Density Altitude		Above Terrain		Pressure Altitude		Acft. Gross Weight		Fiscal Year		Fleets and Rows		TOTAL INJURIES "A" "U" "L"		"A" Injuries		"U" Injuries		"L" Injuries		Trans. Code		Card Number													
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49		
2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2		

PROPERTY DAMAGE COST										Aircraft Injury Summary										Card Number																
Gov't					Non Gov't					TOTAL INJURIES "A" "U" "L"					"A" Injuries					"U" Injuries					"L" Injuries					Trans. Code		Card Number				
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80						
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

AIRCRAFT 1 OF 1

COPY SHEET 1 OF 2

7/11

AVN NAVSAFEEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CORRECTED: ly REVIEWED: _____

LOGGED: _____

PUNCHED: _____

VALIDATED: _____

RECORD IDENTIFICATION											Aircraft Injury Summary (cont'd)																	No. Occupants All Acft. Involved													
Date			Type Report	Log Line Number	Aircraft Number	"B" Injuries		"C" Injuries		"D" Injuries		"E" Injuries		"F" Injuries		"G" Injuries		Total Injuries																							
Cal. Yr.	Mo.	Day				Navy	Non Navy	Navy	Non Navy	Navy	Non Navy	Navy	Non Navy	Navy	Non Navy	Navy	Non Navy	Navy	Non Navy	Navy	Non Navy																				
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42
6	9	9	5	0	7	1	0	3	0	1																															

ESCAPE SYS. DATA											Component Separated From Aircraft	Pri Acft. Type	Pri Phase of Operation	1st Acft. Type	1st Phase of Operation	2nd Acft. Type	2nd Phase of Operation	Trans. Code	Card No.																				
Sys.	Comp- onent	Spec. Data																																					
43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80		

Contributing Causes											Pilot Error Causal Fac.			Other Personnel Causal Factor			Inv. Mat. Comp.																					
											First	Second	Third	Pilot Error After Fact.	First	Second	Third	Other Pers. Factor After Fact.	1st Causal Factor																			
																			Cross Ref.	Compo- nent	Ass'y.	Sub Ass'y.																
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	

Involved Mat. Comp. (cont'd.)						Material Fact. After Fact.			Acft. Design Comp. Causal Factor			DESIGN C.F.		Trans. Code	Card No.																							
2nd Causal Factor			3rd Causal Factor			Cross Ref.	Compo- nent	Ass'y.	Sub Ass'y.	Cross Ref.	Compo- nent	Ass'y.	Sub Ass'y.			Special Equipment Pilot Equipment																						
Cross Ref.	Compo- nent	Ass'y.	Cross Ref.	Compo- nent	Ass'y.									Cross Ref.	Compo- nent		Ass'y.	Sub Ass'y.	Cross Ref.	Compo- nent	Ass'y.	Sub Ass'y.	Special Equipment Pilot Equipment															
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80								

AIRCRAFT 1 OF 1ONE SHEET 2 OF 7

VERIFIED:

CARD 6CAMD 8CODE SHEET OF

NAVSAFECEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CODED: _____ REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

CARD 9

RECORD IDENTIFICATION											Aircraft Data										Power Plant Model Number																				
Date						Type Report	Log Line Number	Aircraft Number	1st Flight After Maint. D.I.R.	Tour	Hours Since Acceptance	Since Last Insp.			Since Last Par/O'Haul																										
Col. Yr.	Mo.	Day	Type	Hours	Days							Activity	Hours	Months																											
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39			
6	9	0	5	0	7	1	0	3	0	1								C	8	5			5		2	1	1	0	5												
Power Plant Serial Number											Primary Involved Material Component																		Trans. Code	Card Number											
											Manufacturers Part Number										Total Hours		Since Last Par/O'Haul																		
																																Activity	Number	Hours							
40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	
																																						A	8	9	8

CARD 10

Pri. Inv. Mat. Comp. (cont'd)							Possible or Secondary Involved Material Component																																	
Since Last Check Perf.							Manufacturers Part Number																	Total Hours		Since Last Par/O'Haul			Since Last Check Perf.											
Type	Hours	Days	Activity	Number	Hours	Type																				Hours	Days													
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49			
																	Trans. Code	Card Number																						
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80										
																																					1	8	8	

AIRCRAFT 1 OF 1CODE SHEET 4 OF 7

NAVSAFECEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CODED: 1 REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

CARD 11

RECORD IDENTIFICATION											Controlling LSO's Carrier Pass Description																											
Date						Type Report	Log Line Number	Aircraft Number	Start							Middle							In-Close							Ramp								
Cal. Yr.	Mo.	Day							Alt.	Speed	Speed Modif.	Line-Up	Line-Up Modif.	Power	Nose Position	Alt.	Speed	Speed Modif.	Line-Up	Line-Up Modif.	Power	Nose Position	Alt.	Speed	Speed Modif.	Line-Up	Line-Up Modif.	Power	Nose Position	Alt.	Speed	Speed Modif.	Line-Up	Line-Up Modif.	Power	Nose Position		
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39
6	9	0	5	0	7	1	0	3	0	1																												

CLCPD (cont'd)																												Trans. Code	Card Number												
TOUCH-DOWN																																									
Alt.	Speed	Speed Modif.	Line-Up	Line-Up Modif.	Power	Nose Position																																			
40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	

CARD 12

12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49										

File or Serial Number (Pilot)											Rank/Rate	Br. of Service	Age	Yrs. D.N.A.	Status	Position	Inj. to Indiv.	Abandon A/C	Trans. Code	Card Number																					
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80											

AIRCRAFT 1 OF 1CODE SHEET 5 OF 7

NAVSAFECEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CODED: 12 REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

CARD 13

RECORD IDENTIFICATION											Pilot Factor Inv.	Service Tour Instrument Card	Emerg. Syst. Train.		Instrument Trainer		Time All Models		Time This Model		Inst. Hours Last 3 Months	Nite Hours Last 3 Months	Total Jet or Helo Time	Number of →																
Cal. Yr.	Date			Type Report	Log Line Number	Aircraft Number	Last 6 Months	Last 12 Months	Last 6 Months	Last 12 Months			Total	Last 3 Months	Total	Last 3 Months	Total	Day	Nite	Total Day This Model																				
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
6	9	0	5	0	7	1	0	3	0	1	T	2			10			0	1	4	7	7	0	0	6	0	6	1	6	3	7	1	1						0	0
Carrier Landings											File or Serial Number (Co-Pilot)											Rank/Rate Br. of Service Age Yrs. D.N.A. Status Position Inj. to Indiv. Abandon A/C Pilot Factor Involved Service Tour Instr. Card Trans. Code Card Number																		
Total Nite This Model	This Model Day Last 30 Days			This Model Nite Last 30 Days																																				
42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80		
0	0	0	0	0	0																																			

CARD 14

Emerg. Syst. Train.		Instrument Trainer		Time All Models		Time This Model		Number of Carrier Landings																													
Last 6 Months	Last 12 Months	Last 6 Months	Last 12 Months	Total	Last 3 Months	Total	Last 3 Months	Inst. Hours Last 3 Months	Nite Hours Last 3 Months	Total Jet or Helo Time	Total	Day	Nite	Total Day This Model	Total Nite This Model	This Model Day Last 30 Days	This Model Nite Last 30 Days																				
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49
File or Serial Number (Instr. Plt. in Other A/C)											Rank/Rate Br. of Service Age Yrs. D.N.A. Status Position Inj. to Indiv. Abandon A/C Pilot Factor Involved Service Tour Instr. Card Trans. Code Card Number																										
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80							

AIRCRAFT 1 OF 1CODE SHEET 6 OF 7

AVN NAVSAFECEN MISHAP CODE SHEET

(COMMON TO BOTH CARDS)

CODEN: 10 REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

CARD 15

RECORD IDENTIFICATION											Emerg. Syst. Train.		Instrument Trainer		Time All Models		Time This Model												Number of Carrier →											
Date			Type Report	Log Line Number	Aircraft Number	Last 6 Months	Last 12 Months	Last 6 Months	Last 12 Months	Total	Last 3 Months	Total	Last 3 Months	Inst. Hours Last 3 Months	Nite Hours Last 3 Months	Total Jet or Helo Time	Total	Day	Nite	Total Day This Model	Total Nite This Model																			
Cal. Yr.	Mo.	Day																																						
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	
6	9	0	5	0	7	1	0	3	0	1																														
Landings				This Individual in Acft.	Name (Instr. Plt. in Other Acft.)																Number of Personnel Records	Trans. Code	Card Number																	
This Model Day Last 30 Days	This Model Nite Last 30 Days																																							
41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	
																																						1	5	8

CARD 16

P		File or Serial Number (All Persons)																Name																Rank/Rate		Br. of Service		Age		Yrs. Exper.		Status		Position		Inj. to Indiv.		Abandon A/C		Card Code	
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49														
P								(b) (6)																																											
				Equip 1				Equip 2				Equip 3				Equip 4																																			
Basic Equip.	Spec. Equip.	Problem or Condition	Phase Existed Special Data	Basic Equip.	Spec. Equip.	Problem or Condition	Phase Existed Special Data	Basic Equip.	Spec. Equip.	Problem or Condition	Phase Existed Special Data	Basic Equip.	Spec. Equip.	Problem or Condition	Phase Existed Special Data	Basic Equip.	Spec. Equip.	Problem or Condition	Phase Existed Special Data	Person Sequence Number	Trans. Code	Card Number																													
50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																					

PERSONNEL 1 OF 1AIRCRAFT 1 OF 1CODE SHEET 7 OF 7

REQUEST FOR DELETION OF RECORD
OR CODING MODIFICATION FORMFROM: RECORDS DEPTDATE 12 AUG 1969TO: (1) CODING SECT
(2) REC CONT BRANCH Ps 9-5-69
(3) ADPE DIV SC
(4) REC CONT BRANCH 8 SEP 1969

TRANSACTION CODES

D-Deletion of the entire MISHAP Master Record (use only cc 1-11 and code D in cc 77).

M-Modifying contents of any Master Record field. Use "00" in Person Seq No. field, if field to be modified is in the Gen Data Sect of the Master Record. Otherwise use Person Seq No. for the individual for which the change is to be made. These changes must be in Person Seq No. order.

IDENTIFICATION NO.										AIRCRAFT NUMBER	
YEAR		MONTH		DAY		TYP-RPT	LOG NUMBER				
01	02	03	04	05	06	07	08	09	10	11	
6	9	0	5	0	7	1	0	3	0	1	

Backman

	FIELD NAME	CARD NUMBER	CARD COL OF FLD START ADD.	DATA TO BE INSERTED (LEFT JUSTIFIED)																										TAPE REC DIV NO.	TRANS CODE
				12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29										
1	SOURCE	01	12	01	02	00	00	01	1																						
2	CONTRIB CAUSES	04	21	02	18	00	00	01	2																						
3	PLT ERR CAUS FACT.	04	28	02	25	00	00	06																							

NOTE: (1) For deletions of codes in a given field, leave the "DATA TO BE INSERTED" field blank and use "TRANS CODE" M in cc 77.

(2) Only corrections applying to personnel in one TAPE RECORD DIV may be shown on a single CHANGE REQUEST form.

(b) (6)

ORIGINATOR'S SIGNATURE

REQUEST FOR DELETION OF RECORD
OR CODING MODIFICATION FORMFROM: RECORDS DEPTDATE 12 AUG 1969

TO: (1) CODING SECT *Chg in recd*
 (2) REC CONT BRANCH *PS 9/2/69*
 (3) ADPE DIV *Ja*
 (4) REC CONT BRANCH *8 SEP 1969*

TRANSACTION CODES

D-Deletion of the entire MISHAP Master Record (use only cc 1-11 and code D in cc 77).

M-Modifying contents of any Master Record field. Use "00" in Person Seq No. field, if field to be modified is in the Gen Data Sect of the Master Record. Otherwise use Person Seq No. for the individual for which the change is to be made. These changes must be in Person Seq No. order.

IDENTIFICATION NO.										AIRCRAFT NUMBER	
YEAR		MONTH		DAY		TYP-RPT	LOG NUMBER				
01	02	03	04	05	06	07	08	09	10		
6	9	0	5	0	7	1	0	3	0	1	

FIELD NAME	CARD NUMBER	CARD COL OF FLD START ADD.	FIELD'S STARTING ADDRESS				PERSON SEQ NUMBER	FIELD LENGTH	DATA TO BE INSERTED (LEFT JUSTIFIED)																				TAPE REC DIV NO.	TRANS CODE																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
									12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31			32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
PLT FACTOR INV.	13	12																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												

NOTE: (1) For deletions of codes in a given field, leave the "DATA TO BE INSERTED" field blank and use "TRANS CODE" M in cc 77.

(2) Only corrections applying to personnel in one TAPE RECORD DIV may be shown on a single CHANGE REQUEST form.

(b) (6)

ORIGINATOR'S SIGNATURE

GENERAL DATA SECTION NARRATIVE BRIEF

I.D. Number	690507103	1	NNN	1	14	A
1-2 Ys.	1-4 Mo.	5-6 Day	7 Yr	8-9 Log	10 Typ. Brief	11-15 Main File I.D.
16-19 CL	20-21 Orig. Use	22-23 Tel-Cds	24-25 Trans. Code			

Common Fields to All Cards

CLASS

CODE

1 - Non-Class

2 - Conf

CARD NO. CODED 690507103 REVIEWED 690 KEY PUNCHED _____ VERIFIED _____

11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

01 COLL GND AFTER LIFT OFF NIGHT FMLP. REPL PLT ON 1ST N

02 IGT FMLP FLT TOOK OWN W/D ON 1ST PASS, MADE TOUCH &

03 GO 2ND PASS. WHILE IN FINAL SECONDS OF 3RD APPR, 2 A7

04 ACFT ENTERED BREAK OVERHEAD WHILE TOUCH & GO LAN MAD

05 E. PWR APPLIED, ROTATION & CLB NORM WITH TWR ADVISING

06 TAKE INTERVAL ON BREAKING ACFT. NO ACKNOWLEDGMENT BY

07 PLT. ACFT OBSR TO TRANSITION FROM CLB @ 265 FT AGL T

08 O DIVE WITH IMPACT GND WINGS LEVEL & EXPLO. NO EJT AT

09 TEMPT OBSR. INVETS OF ENG, CONTROLS & ELEC SYS REVLD N

10 O DISCREP. PLT CONTINUOUSLY AWAKE 15 $\frac{1}{2}$ HRS PRIOR ACFT

11 & HAD COMPLETED 2.2 HR HOODED LOW LEVEL NAV FLT WITH

12 MAL ADI 6.6 HRS PRIOR ACFT. PRI- PLT- BREAKDOWN OF IN

13 ST SCAN. CONTRIB- PLT- FATIGUE, FAILURE TO RECOGNIZE

14 DANGEROUS SITUATION.

15 MAL ADI 6.6 HRS PRIOR TO ACFT. PRI- UNDET. FROM PLT-

16 BREAKDOWN OF INST SCAN. FROM PLT- FATIGUE. FROM OTHER

17 PERS- SUPV- SCD SCHEDULING.

18

19

20

11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

CARD NO.

1/12

Bachmeiler

CODED:

REVIEWED: 24

LOGGED:

PUNCHED

B.R

VERIFIED

E.P.

28 AUG 1969

[illegible]

AIRCRAFT _____

OF 1

CODE SHEET 1

OF 9

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 1(ACFT)

NAVSAFECEN 3750-1/21 (New 3/69)

(COMMON TO BOTH CARDS)

CODING: 100 REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

Card 1

RECORD IDENTIFICATION											Format No.		Trans Code		Card Number		Reporting Custodian		Aircraft Damage		Total Pers. This Act		Model Act				Aircraft Bureau Number								
Date			Type Report	Log Line Number	Aircraft Number													Mission Modif.	Basic Mission	Design No.	Serial Symbol														
Cal. Yr.	Mo.	Day																																	
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
6	9	4	5	4	7	1	4	3	4	1	1	A	8	1		3	4	9	A	4	1				A	4	4	7	A	1	3	2	6	6	4
Altitude of Emergency											Time At Alt.											DURATION OF FLIGHT													
Terrain Clearance			Cabin Altitude			Ambient Altitude			At Cabin Altitude		At Ambient Altitude		Place in Formation	Cloud Condition	Horizon	Condition																			
36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63								
					4	4	2	3	5	4	4	2	3	5							9	1	3	2	4	4	3								

Card 2

Format No.		Trans Code		Card Number		Kind of Flight		Narrative Identification														Combat Environment		Primary Cause		Enemy Action		
								Safety and Survival							Bio-Med													
12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34						
1	A	8	2		3	A	3	Y						4	C	2	C				Z							

AIRCRAFT 1 OF 1

CODE SHEET 2 OF 9

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2(LONG)

1

I.D. Number											2	A	41	21		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
Yr.			Mo.		Day		Typ		Log		A/C NO.		Formet No.		Transacn	
COMMON FIELDS TO ALL CARDS																

NAVSAFECEN STD 1-10 (REV 2/68)

CODE SHEET 3

OF 7

AIRCRAFT 1 OF 1

PERSONNEL 1

OF 1

CODED: _____ REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

CD NO. 16-17	CU. FWD	ADD	CU.	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 3		FILE/SERVICE NO. 01	0 0 2 2 0 7		(b) (6)
		1 3		NAME	0 0 2 9 0 7		01010101
		0 9		NAME (CONT)	0 0 3 6 0 3		01010101
		0 7		RANK/RATE	0 0 3 9 0 1		01010101
		0 7		BRANCH OF SERVICE 02	0 0 4 0 0 1		01010101
		0 7		STATUS	0 0 4 1 0 1		01010101
		0 7		INJURY	0 0 4 2 0 1		01010101
		0 7		DISPOSITION	0 0 4 3 0 1		01010101
		0 8		DAYS HOSPITALIZED	0 0 4 4 0 2		01010101
		0 8		DAYS QUARTERS	0 0 4 6 0 2		01010101
		0 8		DAYS GROUNDED	0 0 4 8 0 2		01010101
		0 9		UNCONSCIOUS	0 0 5 0 0 3		01010101
		0 8		AMNESIA	0 0 5 3 0 2		01010101
		0 8		EXPOSURE/SHOCK	0 0 5 5 0 2		01010101
		1 3		INJURY NO. 1 BODY PART 03	0 0 5 7 0 7		(b) (6)
		1 3		INJURY NO. 1 DIAGNOSIS	0 0 6 4 0 7		(b) (6)
		1 3		INJURY NO. 1 CAUSE	0 0 7 1 0 7		(b) (6)
		1 3		INJURY NO. 2 BODY PART	0 0 7 8 0 7		(b) (6)
		1 3		INJURY NO. 2 DIAGNOSIS 04	0 0 8 5 0 7		(b) (6)
		1 3		INJURY NO. 2 CAUSE	0 0 9 2 0 7		(b) (6)

CD NO. 16-17	CU. FWD	ADD	CU.	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 3		INJURY NO. 3 BODY PART	0 0 9 9 0 7		(b) (6)
		1 3		INJURY NO. 3 DIAGNOSIS	0 1 0 6 0 7		(b) (6)
		1 3		INJURY NO. 3 CAUSE	0 1 1 3 0 7		(b) (6)
		1 3		INJURY NO. 4 BODY PART	0 1 2 0 0 7		(b) (6)
		1 3		INJURY NO. 4 DIAGNOSIS	0 1 2 7 0 7		(b) (6)
		1 3		INJURY NO. 4 CAUSE	0 1 3 4 0 7		(b) (6)
		1 3		INJURY NO. 5 BODY PART	0 1 4 1 0 7		(b) (6)
		1 3		INJURY NO. 5 DIAGNOSIS	0 1 4 8 0 7		(b) (6)
		1 3		INJURY NO. 5 CAUSE	0 1 5 5 0 7		(b) (6)
		1 2		LABORATORY TEST NO. 1	0 1 6 2 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 2	0 1 6 8 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 3	0 1 7 4 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 4	0 1 8 0 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 5	0 1 8 6 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 6	0 1 9 2 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 7	0 1 9 8 0 6		(b) (6)
		1 2		LABORATORY TEST NO. 8	0 2 0 4 0 6		(b) (6)
		0 8		X-RAY	0 2 1 0 0 2		(b) (6)
		0 9		PRE-EXISTING DISEASE NO. 1	0 2 1 2 0 3		(b) (6)
		0 9		PRE-EXISTING DISEASE NO. 2	0 2 1 5 0 3		(b) (6)

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2(LONG)

2

I.D. Number												A/C NO.		Format No.		Transaction		Per Sequence		Tot. No. Cards	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	
6	9	0	5	0	7	1	0	3	0	1	2	A	0	1							
Yr Mo Day Typ Log												A/C NO.		Format No.		Transaction		Per Sequence		Tot. No. Cards	

NAVS-AFECEN 3750-1/11 (REV 2/88)

CODE SHEET 4 OF 9

AIRCRAFT 1 OF 1 PERSONNEL 1 OF 1

CODED: REVIEWED: LOGGED: PUNCHED: VERIFIED:

COMMON FIELDS TO ALL CARDS

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		0 9		PRE-EXISTING DISEASE NO. 3	0 2 1 8 0 3		
		0 8		AUTOPSY	0 2 2 1 0 2		
		1 0		MATERIAL TO AFIP	0 2 2 3 0 4		
		0 7		AFIP REPORT	0 2 2 7 0 1		
		1 1		ADDITIONAL INJURY NO. 1	0 2 2 8 0 5		
		1 1		ADDITIONAL INJURY NO. 2	0 2 3 3 0 5		
		1 1		ADDITIONAL INJURY NO. 3	0 2 3 8 0 5		
		1 1		ADDITIONAL INJURY NO. 4	0 2 4 3 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 1	0 2 4 8 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 2	0 2 5 3 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 3	0 2 5 8 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 4	0 2 6 3 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 5	0 2 6 8 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 6	0 2 7 3 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 7	0 2 7 8 0 5		
		1 1		PSYCHOPHYSIOLOGICAL FACTOR NO. 8	0 2 8 3 0 5		
		0 8		ROLE OF INDIVIDUAL	0 2 8 8 0 2		
		1 2		LEAVE INFO - DATE LAST LEAVE	0 2 9 0 0 6		
		0 9		LEAVE INFO - NO. OF DAYS/TYRE	0 2 9 6 0 3		
		1 2		DATE LAST PREV. FLIGHT	0 2 9 9 0 6		

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		0 9		HOURS FLOWN LAST 24	0 3 0 5 0 3		
		0 9		HOURS FLOWN LAST 48	0 3 0 8 0 3		
		1 0		MISSIONS FLOWN LAST 24 (2/48 (2)	0 3 1 1 0 4		
		1 2		HOURS WORKED LAST 24 (2/48 (2)	0 3 1 5 0 6		
		1 2		HOURS SLEPT LAST 24 (2/48 (2)	0 3 2 1 0 6		
		0 9		HOURS DUTY PRIOR TO MISHAP	0 3 2 7 0 3		
		0 9		HOURS AWAKE PRIOR TO MISHAP	0 3 3 0 0 3		
		0 9		HOURS DURATION LAST SLEEP	0 3 3 3 0 3		
		0 8		TIME IN COCKPIT PRIOR TO MISHAP	0 3 3 6 0 2		
		1 2		PHYSIOLOGICAL TRAINING NO. 1	0 3 3 8 0 6		
		1 2		PHYSIOLOGICAL TRAINING NO. 2	0 3 4 4 0 6		
		1 2		PHYSIOLOGICAL TRAINING NO. 3	0 3 5 0 0 6		
		1 2		PHYSIOLOGICAL TRAINING NO. 4	0 3 5 6 0 6		
		1 2		PHYSIOLOGICAL TRAINING NO. 5	0 3 6 2 0 6		
		1 2		PHYSIOLOGICAL TRAINING NO. 6	0 3 6 8 0 6		
		0 8		AGE	0 3 7 4 0 2		
		0 8		HEIGHT	0 3 7 6 0 2		
		0 9		WEIGHT	0 3 7 8 0 3		
		0 9		SITTING HEIGHT	0 3 8 1 0 3		
		0 9		TRUNK HEIGHT	0 3 8 4 0 3		

(b) (6)

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2(LONG)

3

I.D. Number: 69454716341												2	A	41						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
Yr.			Mo.		Day		Typ		Log		A/C NO		Formal No.		Transaction		Part Sequence		Tpn. No. Cards	

COMMON FIELDS TO ALL CARDS

NAVSAFECEN 3750-1/12 (REV 2/88)

CODE SHEET 5 OF 9

AIRCRAFT 1 OF 1 PERSONNEL 1 OF 1

CODED: REVIEWED: LOGGED: PUNCHED: VERIFIED:

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS	FLD SIZE	CODES	CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS	FLD SIZE	CODES
		0 9		FUNCTIONAL REACH	0 3 8 7	0 3	(b) (6)			1 2		EQUIPMENT NO. 6 CONTINUED	0 4 9 1	0 6	
		0 9		BUTTOCK KNEE LENGTH	0 3 9 0	0 3				1 0		EQUIPMENT NO. 6 CONTINUED	0 4 9 7	0 4	
		0 9		LEG LENGTH 13	0 3 9 3	0 3				1 3		EQUIPMENT NO. 7	0 5 0 1	0 7	
		0 9		SHOULDER WIDTH	0 3 9 6	0 3				1 2		EQUIPMENT NO. 7 CONTINUED	0 5 0 8	0 6	
		1 3		EQUIPMENT NO. 1	0 3 9 9	0 7	9 9 9 9 9 9 A			1 0		EQUIPMENT NO. 7 CONTINUED	0 5 1 4	0 4	
		1 2		EQUIPMENT NO. 1 CONTINUED	0 4 0 6	0 6				1 3		EQUIPMENT NO. 8	0 5 1 8	0 7	
		1 0		EQUIPMENT NO. 1 CONTINUED	0 4 1 2	0 4				1 2		EQUIPMENT NO. 8 CONTINUED	0 5 2 5	0 6	
		1 3		EQUIPMENT NO. 2	0 4 1 6	0 7				1 0		EQUIPMENT NO. 8 CONTINUED	0 5 3 1	0 4	
		1 2		EQUIPMENT NO. 2 CONTINUED	0 4 2 3	0 6				1 3		EQUIPMENT NO. 9	0 5 3 5	0 7	
		1 0		EQUIPMENT NO. 2 CONTINUED	0 4 2 9	0 4				1 2		EQUIPMENT NO. 9 CONTINUED	0 5 4 2	0 6	
		1 3		EQUIPMENT NO. 3	0 4 3 3	0 7				1 0		EQUIPMENT NO. 9 CONTINUED	0 5 4 8	0 4	
		1 2		EQUIPMENT NO. 3 CONTINUED	0 4 4 0	0 6				1 3		EQUIPMENT NO. 10	0 5 5 2	0 7	
		1 0		EQUIPMENT NO. 3 CONTINUED	0 4 4 6	0 4				1 2		EQUIPMENT NO. 10 CONTINUED	0 5 5 9	0 6	
		1 3		EQUIPMENT NO. 4	0 4 5 0	0 7				1 0		EQUIPMENT NO. 10 CONTINUED	0 5 6 5	0 4	
		1 2		EQUIPMENT NO. 4 CONTINUED	0 4 5 7	0 6				1 3		EQUIPMENT NO. 11	0 5 6 9	0 7	
		1 0		EQUIPMENT NO. 4 CONTINUED	0 4 6 3	0 4				1 2		EQUIPMENT NO. 11 CONTINUED	0 5 7 6	0 6	
		1 3		EQUIPMENT NO. 5	0 4 6 7	0 7				1 0		EQUIPMENT NO. 11 CONTINUED	0 5 8 2	0 4	
		1 2		EQUIPMENT NO. 5 CONTINUED	0 4 7 4	0 6				1 3		EQUIPMENT NO. 12	0 5 8 6	0 7	
		1 0		EQUIPMENT NO. 5 CONTINUED	0 4 8 0	0 4				1 2		EQUIPMENT NO. 12 CONTINUED	0 5 9 3	0 6	
		1 3		EQUIPMENT NO. 6	0 4 8 4	0 7				1 0		EQUIPMENT NO. 12 CONTINUED	0 5 9 9	0 4	

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2 (LONG)

4

NAVSAFECEN 3250-1/13 (REV 2/80)

CODE SHEET 6

OF 9

AIRCRAFT 1 OF 1

PERSONNEL 1

OF 1

CODED: _____ REVIEWED: _____ LOGGED: _____ PUNCHED: _____ VERIFIED: _____

I.D. Number												2		A		41				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
Yr.			Mo.		Day		Typ		Log		A/C NO.		Formal No.		Transaction		Perk Sequence		Tot. No. Cards	

COMMON FIELDS TO ALL CARDS

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 3		EQUIPMENT NO. 12	0 6 0 3 0 7		
		1 2		EQUIPMENT NO. 13 CONTINUED	0 6 1 0 0 6		
		1 0		EQUIPMENT NO. 13 CONTINUED	0 6 1 6 0 4		
		1 3		EQUIPMENT NO. 14	0 6 2 0 0 7		
		1 2		EQUIPMENT NO. 14 CONTINUED	0 6 2 7 0 6		
		1 0		EQUIPMENT NO. 14 CONTINUED	0 6 3 3 0 4		
		1 3		EQUIPMENT NO. 15	0 6 3 7 0 7		
		1 2		EQUIPMENT NO. 15 CONTINUED	0 6 4 4 0 6		
		1 0		EQUIPMENT NO. 15 CONTINUED	0 6 5 0 0 4		
		1 3		EQUIPMENT NO. 16	0 6 5 4 0 7		
		1 2		EQUIPMENT NO. 16 CONTINUED	0 6 6 1 0 6		
		1 0		EQUIPMENT NO. 16 CONTINUED	0 6 6 7 0 4		
		1 3		EQUIPMENT NO. 17	0 6 7 1 0 7		
		1 2		EQUIPMENT NO. 17 CONTINUED	0 6 7 8 0 6		
		1 0		EQUIPMENT NO. 17 CONTINUED	0 6 8 4 0 4		
		1 3		EQUIPMENT NO. 18	0 6 8 8 0 7		
		1 2		EQUIPMENT NO. 18 CONTINUED	0 6 9 5 0 6		
		1 0		EQUIPMENT NO. 18 CONTINUED	0 7 0 1 0 4		
		1 3		EQUIPMENT NO. 19	0 7 0 5 0 7		
		1 2		EQUIPMENT NO. 19 CONTINUED	0 7 1 2 0 6		

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 0		EQUIPMENT NO. 19 CONTINUED	0 7 1 8 0 4		
		1 3		EQUIPMENT NO. 20	0 7 2 2 0 7		
		1 2		EQUIPMENT NO. 20 CONTINUED	0 7 2 9 0 6		
		1 0		EQUIPMENT NO. 20 CONTINUED	0 7 3 5 0 4		
		1 0		EQUIPMENT NO. 21	0 7 3 9 0 4		
		1 0		EQUIPMENT NO. 22	0 7 4 3 0 4		
		1 0		EQUIPMENT NO. 23	0 7 4 7 0 4		
		1 0		EQUIPMENT NO. 24	0 7 5 1 0 4		
		1 0		EQUIPMENT NO. 25	0 7 5 5 0 4		
		1 0		EQUIPMENT NO. 26	0 7 5 9 0 4		
		1 0		EQUIPMENT NO. 27	0 7 6 3 0 4		
		1 0		EQUIPMENT NO. 28	0 7 6 7 0 4		
		1 0		EQUIPMENT NO. 28	0 7 7 1 0 4		
		1 0		EQUIPMENT NO. 29	0 7 7 5 0 4		
		1 0		EQUIPMENT NO. 31	0 7 7 9 0 4		
		1 0		EQUIPMENT NO. 32	0 7 8 3 0 4		
		1 0		EQUIPMENT NO. 33	0 7 8 7 0 4		
		1 0		EQUIPMENT NO. 34	0 7 9 1 0 4		
		1 0		EQUIPMENT NO. 35	0 7 9 5 0 4		
		1 0		EQUIPMENT NO. 36	0 7 9 9 0 4		

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO 2(LONG)

5

NAVSAFECEN 3750-1/14 (REV 2/88)

CODE SHEET

7

OF

9

AIRCRAFT

1

OF

1

PERSONNEL

1

OF

1

CODED

REVIEWED

LOGGED

PUNCHED

VERIFIED

I.D. Number												2		A		161	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	
Yr.			Mo.		Day		Typ		Log		A/C NO		Formal No		Transac		
COMMON FIELDS TO ALL CARDS																	

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS	FLD SIZE	CODES
		1 0		EQUIPMENT NO. 37	0 8 0 3 0 4		
		1 0		EQUIPMENT NO. 38	0 8 0 7 0 4		
		1 0		EQUIPMENT NO. 39	0 8 1 1 0 4		
		0		EQUIPMENT NO. 40	0 8 1 5 0 4		
		1 1		LOCATION IN AIRCRAFT	0 8 1 9 0 5		
		0 9		METHOD OF ESCAPE	0 8 2 4 0 3		
		0 7		INTENT FOR ESCAPE	18 0 8 2 7 0 1		
		0 7		EXIT USED	0 8 2 8 0 1		
		0 7		COCKPIT CONDITION	0 8 2 9 0 1		
		0 8		ORDER OF ESCAPE	0 8 3 0 0 2		
		0 9		REASON(S) FOR ESCAPE	0 8 3 2 0 3		
		0 8		COMMUNICATION PRIOR TO ESCAPE	0 8 3 5 0 2		
		1 0		NUMBER OF PREVIOUS ESCAPES	0 8 3 7 0 4		
		0 9		TERRAIN OF LANDING OR CRASH SITE	19 0 8 4 1 0 3		
		1 3		AIRCRAFT ATTITUDE	0 8 4 4 0 7		
		0 8		AIRCRAFT ATTITUDE CONTINUED	0 8 5 1 0 2		
		1 4		EJT. TRAINING/LECTURES	0 8 5 3 0 7		
		1 4		EJT. TRAINING/FILMS	20 0 8 5 0 0 7		
		1 4		EJT. TRAINING/UNARMED SEAT	0 8 6 7 0 7		
		1 4		EJT. TRAINING/ARMED SEAT	0 8 7 4 0 7		

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS	FLD SIZE	CODES
		0 9		JUMP/PARASAIL/OTHER SCHOOL ROLE	0 8 8 1 0 3		
		1 2		EGRESS DIFF. BEFORE PROB. 1 & 2	0 8 8 4 0 6		
		1 2		EGRESS DIFF. BEFORE PROB. 3 & 4	0 8 9 0 0 6		
		1 2		EGRESS DIFF. DURING PROB. 1 & 2	0 8 9 6 0 6		
		1 2		EGRESS DIFF. DURING PROB. 3 & 4	0 9 0 2 0 6		
		1 2		EGRESS DIFF. AFTER PROB. 1 & 2	0 9 0 8 0 6		
		1 2		EGRESS DIFF. AFTER PROB. 3 & 4	0 9 1 4 0 6		
		1 1		TIME FROM EMER. UNTIL ESCAPE ATTEM.	0 9 2 0 0 5		
		0 9		REASON FOR DELAY	0 9 2 5 0 3		
		1 1		TERRAIN CLEAR AT ESCAPE	0 9 2 8 0 5		
		1 1		TERRAIN CLEAR AT FRCHT. OPENING	0 9 3 3 0 5		
		0 9		AIR SPEED	0 9 3 8 0 3		
		0 9		GROUND SPEED	0 9 4 1 0 3		
		0 7		FRCHT. DID NOT OPEN	0 9 4 4 0 1		
		1 2		PROTECTIVE HELMET CHINSTRAP/VISOR	0 9 4 5 0 6		
		0 8		CHINSTRAP SAPE STRAP	0 9 5 1 0 2		
		0 8		ZERO LANYARD	0 9 5 3 0 2		
		0 7		AUTO LAP BELT RELEASE	0 9 5 5 0 1		
		1 0		ACFT. CANOPY REMOVAL	0 9 5 6 0 4		
		0 9		EJECTION	0 9 6 0 0 3		

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2(LONG)

6

NAVSAFECEN 3750-1/15 (REV 2/88)

CODE SHEET 8

OF 9

AIRCRAFT 1 OF 1

PERSONNEL 1

OF 1

CODED _____ REVIEWED _____ LOGGED _____ PUNCHED _____ VERIFIED _____

I.D. Number												2		A		01				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
Yr.			Mo.		Day		Typ		Log		A/C NO.		Formal No.		Transaction		Pers Sequence		Tot. No. Cards	

COMMON FIELDS TO ALL CARDS

CD. NO. 16 17	CU. FWD.	ADD	CU.	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 0		BODY POSITION	0 9 6 3 0 4		
		0 9		SEAT POSITION/SEPAR TYPE SEPARATION	0 9 6 7 0 3		
		1 2		Parachute Data Deploy/Open Shock/Decel	0 9 7 0 0 6		
		1 0		PARACHUTE DAMAGE	0 9 7 6 0 4		
		1 0		PARACHUTE DAMAGE CAUSE	0 9 8 0 0 4		
		0 7		DIRECTION FACED AT CHUTE LANDING	0 9 8 4 0 1		
		1 1		LANDING CONDITIONS (WEIGHT WINDS)	0 9 8 5 0 5		
		0 9		DROGGED BY CHUTE DISTANCE DROGGED	0 9 9 0 0 3		
		1 0		LANDING POSITION	0 9 9 3 0 4		
		0 9		DEPLOYED BEFORE LANDING	0 9 9 7 0 3		
		0 7		CANOPY DEFLATION ROCKETS	1 0 0 0 0 1		
		1 1		SURVIVAL TRAINING SWIM	1 0 0 1 0 5		
		1 1		SURVIVAL TRAINING OILBERT DUNK	1 0 0 6 0 5		
		1 1		PARACHUTE DRAG	1 0 1 1 0 5		
		1 1		SURVIVAL TRAIN IMMERSED COCKPIT	1 0 1 6 0 5		
		1 1		SURVIVAL TRAIN IMMERSED SEAT	1 0 2 1 0 5		
		1 1		SURVIVAL TRAIN JUNGLE	1 0 2 6 0 5		
		1 1		SURVIVAL TRAIN ARCTIC	1 0 3 1 0 5		
		1 1		SURVIVAL TRAIN DESERT	1 0 3 6 0 5		
		1 1		SURVIVAL TRAIN MOUNTAIN	1 0 4 1 0 5		

CD. NO. 16 17	CU. FWD.	ADD	CU.	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 1		SURVIVAL TRAINING GENERAL	1 0 4 6 0 5		
		1 3		CONDITIONS AT SURVIVAL/ RESCUE SITE (TEMP WINDS)	1 0 5 1 0 7		
		1 0		CONDITION AT SITE CONT. (WAVES)	1 0 5 8 0 4		
		1 0		CONDITION AT SITE CONT. (TERRAIN WEATHER)	1 0 6 2 0 4		
		1 1		TIME LAPSE MISHAP TO ALERT (RESCUE VEH)	1 0 6 6 0 5		
		1 0		TIME LAPSE OTHER ASSIST NO. 1	1 0 7 1 0 4		
		1 0		TIME LAPSE OTHER ASSIST NO. 2	1 0 7 5 0 4		
		1 1		TIME LAPSE ALERT TO DEPART (RESC VEH)	1 0 7 9 0 5		
		1 0		TIME LAPSE ALERT TO DEPART (ASSIST NO. 1)	1 0 8 4 0 4		
		1 0		TIME LAPSE ALERT TO DEPART (ASSIST NO. 2)	1 0 8 8 0 4		
		1 1		TIME LAPSE ALERT TO LOCATE (RESCUE VEH)	1 0 9 2 0 5		
		1 0		TIME LAPSE ALERT TO LOCATE (ASSIST NO. 1)	1 0 9 7 0 4		
		1 0		TIME LAPSE ALERT TO LOCATE (ASSIST NO. 2)	1 1 0 1 0 4		
		1 1		TIME LOCATE TO REACH (RESCUE VEHICLE)	1 1 0 5 0 5		
		1 0		LOCATE TO REACH (ASSIST NO. 1)	1 1 1 0 0 4		
		1 0		LOCATE TO REACH (ASSIST NO. 2)	1 1 1 4 0 4		
		1 1		TIME LAPSE MISHAP TO RESCUE/ABANDON	1 1 1 8 0 5		
		1 0		TIME LAPSE MISHAP TO RESCUE COMPLETE	1 1 2 3 0 4		
		1 0		TIME IN WATER	1 1 2 7 0 4		
		1 0		TIME IN RAFT	1 1 3 1 0 4		

AVN NAVSAFECEN MISHAP NARRATIVE CODESHEET PERSONNEL SECTION FORMAT NO. 3

I.D. Number										3		A		12	
1	2	3	4	5	6	7	8	9		12		13		18	19
Yr. Mo. Day Log									Format No.		Trans Code		Tot. No. Cards		

NAVSAFECEN 3750-1/19 (REV 2/88)

 CARD 9 OF 9

 CODED: 000 REVIEWED: _____

PUNCHED: _____ VERIFIED: _____

COMMON FIELDS TO ALL CARDS

CARD NO.

14 15 16

01

02

03

04

05

06

07

08

09

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71

FRP ON HIS 1ST NIGHT FMLP HAD COMPLETED TOUCH + GO

ACFT WAS OBSERVED TO GAIN APPROX 280 FT ALT AND

THEN DESCEND WING LEVEL INTO GND. THE FLT DIED IN

STANTLY FROM EXTREME IMPACT FORCE + (b) (6)

(b) (6) MORE INDICATES BREAKING INS

TRUMENT SCAM AT CRITICAL MOMENT WAS MOST PROBABLE

CAUSE OF ACFT. THE FLT SURGEON INDICATE FATIGUE IN

DUCKED BY A PRIOR 3.2 HR ADDDED LOW LEVEL NAV FLT +

IS HAS WITHOUT ADEQUATE REST CONTRIBUTED. IT IS CO

NSIDERED POSSIBLE THAT ACFT BREAKING OVERHEAD MAY

22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71

HAVE CAUSED EITHER VISUAL ILLUSION OR FLT DISTRACT

ION

22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71

11

12

13

14

15

16

17

18

19

20

21

22

23

24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71

AVN NAVSAFECEN MISHAP CODE SHEET PERSONNEL SECTION FORMAT NO. 2(LONG)

1

I.D. Number												2		C		2101													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17													
Yr.			Mo.			Day			Typ			Log			A/C NO			Format No.			Transaction			Fips Sequence			Tot. No. Cards		

COMMON FIELDS TO ALL CARDS

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 3		FILE/SERVICE NO.	0 0 2 2 0 7		
		1 3		NAME	0 0 2 9 0 7		
		0 9		NAME (CONT)	0 0 3 6 0 3		
		0 7		RANK/RATE	0 0 3 9 0 1		
		0 7		BRANCH OF SERVICE	0 0 4 0 0 1		
		0 7		STATUS	0 0 4 1 0 1		
		0 7		INJURY	0 0 4 2 0 1		
		0 7		DISPOSITION	0 0 4 3 0 1		
		0 8		DAYS HOSPITALIZED	0 0 4 4 0 2		
		0 8		DAYS QUARTERS	0 0 4 6 0 2		
		0 8		DAYS GROUND	0 0 4 8 0 2		
		0 9		UNCONSCIOUS	0 0 5 0 0 3		
		0 8		AMNESIA	0 0 5 3 0 2		
		0 8		EXPOSURE/SHOCK	0 0 5 5 0 2		
01		1 3		INJURY NO. 1 BODY PART	0 0 5 7 0 7		(b) (6)
		1 3		INJURY NO. 1 DIAGNOSIS	0 0 6 4 0 7		
		1 3		INJURY NO. 1 CAUSE	0 0 7 1 0 7		
		1 3		INJURY NO. 2 BODY PART	0 0 7 8 0 7		(b) (6)
		1 3		INJURY NO. 2 DIAGNOSIS	0 0 8 5 0 7		
		1 3		INJURY NO. 2 CAUSE	0 0 9 2 0 7		

CD NO. 16 17	CU FWD	ADD	CU	FIELD NAME	BEGIN TAPE POS.	FLD SIZE	CODES
		1 3		INJURY NO. 3 BODY PART	0 0 9 9 0 7		
		1 3		INJURY NO. 3 DIAGNOSIS	0 1 0 6 0 7		
		1 3		INJURY NO. 3 CAUSE	0 1 1 3 0 7		
		1 3		INJURY NO. 4 BODY PART	0 1 2 0 0 7		
		1 3		INJURY NO. 4 DIAGNOSIS	0 1 2 7 0 7		
		1 3		INJURY NO. 4 CAUSE	0 1 3 4 0 7		
		1 3		INJURY NO. 5 BODY PART	0 1 4 1 0 7		
		1 3		INJURY NO. 5 DIAGNOSIS	0 1 4 8 0 7		
		1 3		INJURY NO. 5 CAUSE	0 1 5 5 0 7		
		1 2		LABORATORY TEST NO. 1	0 1 6 2 0 6		
		1 2		LABORATORY TEST NO. 2	0 1 6 8 0 6		
		1 2		LABORATORY TEST NO. 3	0 1 7 4 0 6		
		1 2		LABORATORY TEST NO. 4	0 1 8 0 0 6		
		1 2		LABORATORY TEST NO. 5	0 1 8 6 0 6		
		1 2		LABORATORY TEST NO. 6	0 1 9 2 0 6		
		1 2		LABORATORY TEST NO. 7	0 1 9 8 0 6		
		1 2		LABORATORY TEST NO. 8	0 2 0 4 0 6		
		0 8		X RAY	0 2 1 0 0 2		
		0 9		PRE-EXISTING DISEASE NO. 1	0 2 1 2 0 3		
		0 9		PRE-EXISTING DISEASE NO. 2	0 2 1 5 0 3		

NAVSAFECEN 3765-1/10 (REV 2/89)

CODE SHEET

OF

AIRCRAFT

OF

PERSONNEL

OF

CODED

REVIEWED

LOGGED

PUNCHED

VERIFIED 06 AUG 1970

NAVAL SAFETY CENTER
NAVAL AIR STATION
NORFOLK, VIRGINIA 23511

134/we
13 June 1969

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6F

FOR OFFICIAL USE ONLY

NAVSAFECEN INVESTIGATION 65-69

1. INTRODUCTION

a. The Accident. A-7A, BUNO 152664, assigned to ATTACK SQUADRON ONE TWO TWO (VA-122), crashed on runway 32L at NAS Lemoore, California, at 0128(T) on 7 May 1969 and was destroyed (ALFA). The pilot, LTJG James F. BACHMEIER, USNR, (b) (6), died in the crash. There was no damage to private property.

b. Synopsis of Flight. The pilot was on a scheduled night field mirror landing practice flight. Takeoff was normal. The pilot had made three approaches and two landings. During takeoff from the last landing, the aircraft climbed to approximately 300 feet AGL and then nosed over into a shallow glide till impact with the ground. The aircraft exploded upon impact and the ensuing fire destroyed approximately 60 percent of the fuselage, including the cockpit area.

2. INVESTIGATION AND ANALYSIS

a. History

(1) The Pilot. LTJG BACHMEIER, age 24, was designated a Naval Aviator in August 1968 and had accumulated 397 flight hours, 370 in jet aircraft. He had flown a total of 80 hours in A-7 aircraft, 71 of these in the past three months.

(2) The Aircraft. A-7A, BUNO 152664, was accepted in October 1966. It had been through one progressive aircraft rework (PAR) at Naval Air Rework Facility (NAVAIREWORKFAC) Jacksonville in December 1968 and had since been flown 211 flight hours. A first calendar inspection was completed in April 1969 and the aircraft had since been flown 85 hours.

(3) The Engine. TF30-P-6 engine, serial number P651920, was accepted in February 1966 and had accumulated 443 operating hours. One overhaul was completed in September 1968 and it had since operated 233 hours. A major calendar inspection on the engine was completed in March 1969. Subsequently the engine was installed on this aircraft and it had since operated 85 hours.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6F

FOR OFFICIAL USE ONLY

Enclosure (1)

FOR OFFICIAL USE ONLY

NAVSAFECEN INVESTIGATION 65-69

- (4) Weather. Weather was not a factor in this accident.

b. Field Investigation

(1) The impact attitude was approximately 10 degrees nose down, slightly right wing down. The impact point was approximately 6000 feet from the approach end of the runway and 250 feet to the left of centerline.

(2) The engine indicated about 85 percent RPM at impact and is not considered a factor in the accident.

(3) There were external lights sighted by witnesses and instrument lights in the cockpit, indicating electrical power was present at impact.

(4) Witnesses concur that:

(a) There was one power reduction (from full to cruise power) approximately 10 seconds prior to impact. This reduction occurred as the aircraft reached the altitude of approximately 250 feet AGL.

(b) Other than the power reduction, there was no unusual noise or explosion prior to impact.

(c) The aircraft flight path was a smooth arc from takeoff to impact with no abrupt movements.

(5) A review of the tower tapes revealed there was no radio transmission from the pilot prior to impact.

(6) At the time of the accident there were six aircraft in the traffic pattern located as follows:

(a) One A-7 just past the 90-degree position in the night field mirror landing pattern (FMLP).

(b) One A-7 approximately abeam of the field LSO platform.

(c) One A-3 completing a deep, upwind turn.

(d) Two A-7s breaking into the pattern over the runway approximately abeam of the A-3 and passing over the aircraft that had the accident.

(7) There was no deviation from pertinent instructions, including LSO NATOPS, associated with this accident.

FOR OFFICIAL USE ONLY

NAVSAFECEN INVESTIGATION 65-69

(8) The accident aircraft, just lifting off from a touch-and-go landing, was directed to take interval on the two A-7s entering the landing pattern.

(9) At the time of the accident the runway lights were turned out, except for the lights outlining the field carrier deck which is located on the approach end of runway 32L.

(10) A review of past work orders and pilots discrepancy sheets did not indicate any malfunctions that would have been a cause factor.

(11) On the day of the accident the pilot had flown a 2.1 hour radar low-level navigation flight. The briefing started at 1500(T), takeoff was at 1615(T) and he returned to the field at approximately 1830(T). He left the squadron area at 1915(T) for dinner at his quarters. LTJG BACHMEIER returned to the squadron at 2300(T) for the night flight brief and took off at approximately 0100(T). He had not slept since arising at 0830(T) the previous morning.

(12) Discussion with other students in the squadron indicated that the low-level radar navigation flight flown by this pilot on the day of the accident is a rather strenuous, fatiguing flight. It requires several hours of preparation. The student briefs the instructor on the prescribed route which is then flown completely under the thermal shield simulating actual instrument conditions.

(13) Under controlled conditions, with all appropriate witnesses in their original positions, a VA-122 pilot duplicated the landing pattern of the fatal aircraft.

From the duplicated flight pattern it was concluded that it was easily possible for the pilot to actually fly the aircraft into the ground at the desired spot from the altitude he had obtained and in the attitude witnessed at impact.

c. Analysis. The initial premise of this investigation was that the cause of this accident was either a system malfunction or material failure. After a complete field investigation of all the hardware it was concluded that there was no evidence to support the initial premise, therefore, an investigation of possible human factors was the next logical step.

A review of the pilot's training records (both Training Command and VA-122) revealed that he was slightly above average in all flight phases

FOR OFFICIAL USE ONLY

NAVSAFECEN INVESTIGATION 65-69

except instruments, which was a bit below the average. The low-level radar navigation flight flown just prior to the fatal flight was considered by the instructor to be above average and the pilot was elated over the completion of this difficult flight in such a manner. The pilot's physical condition was considered good by the squadron flight surgeon.

d. Sequence of Events. Examination of the circumstances and known facts indicates the following sequence of events occurred. The pilot had in fact completed a good days flying upon completion of the low-level navigation flight. He probably did little to relax and rest in the interval from completion of the afternoon flight and the briefing for the night period. By the time he had briefed, manned the aircraft, taken off and joined the touch-and-go pattern he had been awake and active for a period of 17 hours (0830(T) 6 May to 0120(T) 7 May). The fact that this flight was at night must also be considered. The total time (17 hours) the pilot was awake coupled with the added strain of flying at night would certainly suggest a possible factor of fatigue. As the pilot completed his third pass two more aircraft joined the FMLP and he was directed to take interval on them. This necessitated transferring his scan from his instruments to the other two aircraft. As he lifted off these aircraft were estimated to be directly over his head and moving away from him. Upon reaching pattern altitude, a power reduction was made, he leveled off and set a nose attitude that was probably 4 to 6 degrees nose down. (In this attitude the aircraft would impact the ground in approximately 10 seconds, as in fact it did.) The pilot probably again fixed his eyes on these two additional aircraft after reducing power. Possibly due to mental and physical fatigue and the lack of outside references (runway lights were out) he never realized that he was in a fatal situation.

3. CONCLUSIONS

a. The cause of this accident was undetermined, however, a most probable cause was that the pilot inadvertently flew the aircraft into the ground.

b. A contributing cause was the probable fatigue of the pilot resulting from his long working day. This must be considered supervisory error, in that, this pilot had been scheduled for this type of working day.

4. ACTION COMPLETED. The Commanding Officer of VA-122 has directed that no student will be scheduled for more than 10 consecutive hours. All

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6F

FOR OFFICIAL USE ONLY

NAVSAFECEN INVESTIGATION 65-69

possible care will be taken not to schedule flights at either end of this period with a long middle period of inactivity.

Distribution:

List "A"

CNO (OP-05F)

CNO (OP-098)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6F

FOR OFFICIAL USE ONLY

NAVAL SAFETY CENTER
NAVAL AIR STATION
NORFOLK, VIRGINIA 23511

111B3/ck
3750/2
Ser 2235
13 Oct 1969

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6 SERIES
FOR OFFICIAL USE ONLY

From: Commander, Naval Safety Center
To: Commanding Officer, Attack Squadron ONE TWO TWO
Subj: VA-122 AAR ser 15-69A concerning A-7A BuNo 152664 accident
occurring 7 May 1969, pilot BACHMEIER

1. The subject report and all endorsements have been reviewed. Concur with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.

2. The cause of this accident has been recorded as UNDETERMINED with the following probable contributing factors:

a. PILOT:

- (1) Breakdown of instrument scan.
- (2) Fatigue.

b. OTHER PERSONNEL--SUPERVISORY (squadron scheduling).

3. Lack of visible horizon has been coded as an environmental factor in this mishap.

(b) (6)

By direction

Copy to:
NAVAIRSYSCOMHQ (AIR 09E) (2)
COMNAVAIRPAC
COMFAIRALAMEDA
COMRCVW-12
NAVPRO DALLAS
COMNAVAIRTESTCEN
DIR AFIP

FOR OFFICIAL USE ONLY

DEPARTMENTAL COMMENTS FOR "CLOSE OUT" LETTER
ON ORIGINAL REVIEW

- NOTE: 1. Negative report is required.
2. Positive comments will be in a format suitable for inclusion in the "close out" letter.
3. Attach additional sheets if more space is required.

M&M DEPARTMENT: *None*

OPTIONAL FORM NO. 10
5010-104

UNITED STATES GOVERNMENT

Memorandum

TO : Records via 80

DATE: 9.22.69

FROM : 82

SUBJECT: Comments for close out letter

No specific aeromedical comments are offered. However, the problem of taking interval on aircraft breaking overhead at night, has been a problem before in at least 2 similar cases that I can recall. This particluar area of operation might deserve closer scrutiny as a source of optical illusion to pilots at night.

*True!
DH/bo
see note.*

*VR
344*

COMPLETION SHEET

Action to: Correction to:	Action Required	Completed Code/Date
3750-1		/
DIR		/
Misc Items for Action or Correction		
To Code	From Code/Date	
		<i>Hard. coded 6-10-69 by</i>
	511 / 8-5-69	<i>Rough gig for 3rd End.</i> /
	/	<i>sent to Com Fair ALAMEDA.</i> /
	/	<i>EX</i> /
	511 / 8-11-69	ORIGINAL REC'D rdb /
511	512D / 7-2-70	<i>Final review completed</i> /
	/	<i>all documents ready for the</i> /
	/	<i>closed file. cur/Whils</i> /
	/	/
	/	/
	06 JUL 1970	/
	/	/
	/	/
	/	/
	/	/
	/	/
	/	/

CLOSED

AAR REVIEW ROUTING SHEET

UNIT VA-132
 MODEL H7A
 BUNO 152464

ADVANCE ROUTING

PRI	DEPT	DATE IN	DATE OUT	INIT	INTER-DEPT ROUTING:
	M&M		9-29-69		
	LSD	9/26/69	9/26/69	SP	DO NOT ROUTE

DEPARTMENT REPRESENTATIVES INITIALS FOR RECEIPT OF REPORTS:

REMARKS:

ORIGINAL ROUTING

DEADLINE DATE OUT OF NAVSAFECEN
 EXTENSIONS

10 Oct 1969
 26 SEP 1969

DEPT	DATE IN	DEPT DEADLINE	DATE OUT	INIT	INTER-DEPT ROUTING
111B3 AAD	29 Sep		10-7-69	RKC	

13 Oct LGG

NAVSAFECEN ENDORSEMENT ROUTING

PRI	DEPT	DATE IN	DATE OUT	INIT
1	R&DP			
2	M&M			
3	ADMIN			

10/30/69

ROUTING AFTER CLOSE-OUT

DEPT	DATE IN	DATE OUT	INIT	INTER-DEPT ROUTING
LSD				

NOTES: 1. No person other than those assigned to the Records Control Branch will remove any part of this document from the folder.

2. Departments will be fully responsible and accountable for documents in their custody until checked back into Records Control Branch.

3. Any department desiring to retain this report longer than five (5) working days must notify Records Control Branch of their need for extension.



COMMANDER FLEET AIR ALAMEDA

U. S. NAVAL AIR STATION
ALAMEDA, CALIFORNIA 94501

IN REPLY REFER TO:

FF7-2/3750

Ser 80/3109

15 AUG 1969

SPEEDLETTER

From: Commander Fleet Air Alameda
To: Commander, Naval Safety Center

Subj: VA-122 Aircraft Accident Report Serial 15-69A, concerning A-7A,
BUNO 152664, occurring 7 May 1969, Pilot BACHMEIER

Ref: (a) COMNAVSAFECEN ltr ser 1705 of 11 August 1969

Encl: (1) COMPAIRALAMEDA ltr ser 80/2766 of 17 July 1969

1. In accordance with reference (a) enclosure (1) is forwarded.
2. Commander Fleet Air Alameda records indicate that the subject mishap report was endorsed and forwarded on 17 July 1969. Informal liaison with Commander Naval Air Force, U. S. Pacific Fleet indicates that it was received, endorsed and forwarded to Commander, Naval Safety Center on 6 August 1969.

Copy to: (w/o encl)
COMNAVPAIRPAC
OO, ATRON 122

M. V. DAWKINS
Chief of Staff

USE FOR URGENT
LETTERS ONLY

NAVAL SPEED LETTER

DO NOT CLEAR THROUGH
COMMUNICATION OFFICE

(One box must be checked)

☐ REGULAR MAIL ☐ SPECIAL DELIVERY
☐ AIR MAIL ☐ REGISTERED MAIL

CLASSIFICATION

UNCLASSIFIED

IN REPLY REFER TO

311/el

Ser 1705

304
8/17/69

DATE:

11 Aug 1969

TO: [Commander Fleet Air, Alameda
Naval Air Station
Alameda, Calif. 94501]

NAVAL SPEEDLETTER-

Permits dispatch or informal language.

May be sent (1) with enclosures, (2) in a window envelope (size 8 1/4" x 3 1/4"), if contents are not classified as confidential or higher, (3) to both naval and nonnaval activities.

(Fold)

Subj: VA-122 Aircraft Accident Report serial 15-9A, concerning
A7A, BUHO 152664, occurring 7 May 1969, pilot RACHMEIER

Ref: (a) OPNAVINST 3750.67

Naval Safety Center records indicate that the subject mishap report was forwarded to your command for endorsement on 26 June 1969.

Paragraphs 33c and 40i of reference (a) direct endorsers to forward endorsements within five (5) working days from date of receipt with two (2) copies to the Naval Safety Center. This endorsement has not been received and is requested.

(b) (6)

By direction

COPY TO

COMNAVAIRPAC
CG, VA-122

ADDRESS:

[Commander
Naval Safety Center
Naval Air Station
Norfolk, Va. 23511]

SENDER'S MAILING ADDRESS

Address reply as shown at left; or reply hereon and return in window envelope (size 8 1/4" x 3 1/4"), if not classified as confidential or higher.

CLASSIFICATION

UNCLASSIFIED

6 - AUG 1969

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH OPNAVINST 3750.6 SERIES

FOURTH ENDORSEMENT on VA-122 AAR ser 15-69A concerning A-7A
BuNo 152664 accident occurring 7 May 69, pilot BACHMEIER

From: Commander Naval Air Force, U. S. Pacific Fleet
To: Commander, Naval Safety Center

Subj: VA-122 AAR ser 15-69A

Ref: (a) OPNAVINST 3750.6F

1. Forwarded, concurring with the conclusions and recommendations of the Aircraft Accident Board, as modified by the remarks contained in subsequent endorsements.
2. Based on the contents of the report, the cause of this accident is undetermined as proposed in the third endorsement. Considering the pilot's long work day, previous demanding flight, and the blackness of the evening, some degree of fatigue may have adversely influenced the pilot's flight instrument scan at a critical moment.
3. Recommendation two in part IX of the basic report is sound and is supported.
4. Since the change of a primary flight instrument was suspect in this mishap, the inclusion of a maintenance officer's statement, relative to the aircraft's recent maintenance history, as set forth in paragraph 36c of reference (a), would have aided reviewers in assessing all facts in this mishap.

(b) (6)

Force Safety Officer

Copy to:
NAVAIRSYSCOMHQ
COMREDAFKCARAIRWING TWELVE
COMFAIRALAMEDA
CO ATKRON ONE TWO TWO
NAVPLANTREPO DALLAS
DIR AFIP
COMNAVAIRTESTCEN

8-11-69

FF7-2/3750
Ser 80/2766
17 JUL 1969

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH OPNAVINST 3750.6 SERIES

THIRD ENDORSEMENT on VA-122, Accident, Serial 15-69A, concerning
A-7A, BUNO 152664, of 7 May 1969, Pilot RACHMEIER

From: Commander Fleet Air Alameda
To: Commander, Naval Safety Center
Via: Commander Naval Air Force, U. S. Pacific Fleet

Subj: ATRON 122 Aircraft Accident Report Serial 15-69A

1. Forwarded, concurring in the comments and recommendations of the
Aircraft Accident Board and subsequent endorsements with the following
exception:

a. The thorough investigation and meticulous analysis conducted by
the board is highly commendable. Despite exhaustive efforts, no material
failure or malfunction was detected as having contributed to or caused
the accident. Additionally, no positive pilot factor was uncovered as
a primary or contributing cause. It is the opinion of this endorser
that the primary cause be listed as undetermined, with the most probable
factor being the error of inattention/distraction by LTJG RACHMEIER.

2. The following administrative errors are noted:

- a. Second endorsement should be numbered page 15 vice 14.
- b. First endorsement should be numbered page 14 vice 13.
- c. First endorsement distribution list should include
"COMNAVSAPFECEN (2)" and "DIRECTOR ARMED FORCES INSTITUTE OF PATHOLOGY".
- d. Part I, Section A, block 3, insert "RAY" after DTG.
- e. Part I, Section C, block 1, insert first name "James".

Copy to:
COMNAVAIRSYSCOM (AIR-09E)
COMNAVSAPFECEN (2)
COMNAVAIRPAC
COMNAVAIRTESTCEN
DIRECTOR ARMED FORCES INSTITUTE OF PATHOLOGY
NAVPRO DALLAS
COMREDAIRCARPACTESTING 12
CO, ATRON 122


M. V. DAWKINS
Chief of Staff

ORIGINAL

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH OPNAVINST 3750.6 SERIES

COMRCVW-12:sn
3750
Ser 80/ 552

26 JUN 1969

SECOND ENDORSEMENT on VA-122 Accident serial 15-69A, concerning A7A BuNo
152664 of 7 May 1969, Pilot BACHMEIER

From: Commander Readiness Attack Carrier Air Wing TWELVE
To: Commander, Naval Safety Center
Via: (1) Commander Fleet Air, Alameda
(2) Commander Naval Air Force, U. S. Pacific Fleet

Subj: VA-122 Aircraft Accident Report serial 15-69A

1. Forwarded, concurring with the comments and recommendations of the
Aircraft Accident Board, and the remarks of the first endorser.

P. R. Craven
P. R. CRAVEN

Copy to:
NAVAIRSYSCOMHQ (AIR 09E)
COMNAVSATFECEN (2)
COMNAVAIRPAC
COMFAIRALAMEDA
NAVPLANTREPO, DALLAS
CO, VA-122
COMNAVAIRTESTCEN, PAX RIV
DIRECTOR ARMED FORCES INSTITUTE OF PATHOLOGY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES


VA122:00
3750
Ser:1028
3 JUNE 1969

FIRST ENDORSEMENT on VA-122 Mishap Serial 15-69A 7 May 1969,
A7A BUNO 152664, Pilot BACHMEIER

From: Commanding Officer, Attack Squadron 122
To: Commander, Naval Safety Center
Via: (1) Commander Readiness Attack Carrier Air Wing TWELVE
(2) Commander Fleet Air Alameda
(3) Commander Naval Air Force, U. S. Pacific Fleet

Subj: VA-122 Mishap Serial 15-69A 7 May 1969, A7A BUNO
152664, Pilot BACHMEIER

1. Forwarded, concurring in the conclusion that the primary cause of the accident was pilot error.
2. This command will more closely monitor scheduled activities of all pilots to guard against fatigue contributing to a recurrence of this tragic mishap.
3. Recommendations 2 and 3 have been implemented.
4. The latest safety survey was conducted in May 1969.


MARVIN M. QUAID, Jr.

Copy to:
NAVAIRSYS COMHQ (AIR ONE)
NAVPLANTREPO DALLAS
NAVAIRTESTCEN PAX RIVER

COMFAIRALAMEDA
COMNAVAIRPAC

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 1

SPECIAL HANDLING REQUIRED in accordance with

OPNAV REPORT 3750-1

Para. 66, OPNAV INSTRUCTION 3750.6, effective edition

PART 1 GENERAL

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY	2. SERIAL NO.	3. DTG (LOCAL) OF MISHAP	4. MODEL AIRCRAFT	5. BUREAU NUMBER
CO ATKRON 122	15-69A	07 0228T MAY	A7A	152664
6. TO: Commander, Naval Safety Center	9. LOCATION OF MISHAP	10. DAMAGE		
	NAS Lemoore	Alfa		
7. VIA: CO, ATKRON 122	11. TIME OF DAY	12. TIME IN FLIGHT	13. FLIGHT CODE	
COMBVCVH-12	X Night	0 + 17	3A3	
COMFATHALAMEDIA	14. CLEARED			
COMNAVATRPAC	FROM NAS Lemoore	TO NAS Lemoore		
	15. TYPE CLEARANCE	16. AIRSPEED	17. A/C WEIGHT	
	Local	145 KIAS	23,800	
18. BRIEF DESCRIPTION OF MISHAP	19. ELEVATION AT TIME OF MISHAP			
Impacted ground after liftoff FMLP Touch & go	S.L. 235'	TERRAIN 0		
20. LIST MODEL BUND, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete Form 3750-1 for each A/C)				
NA				

FACTOR	FACTOR	FACTOR
1. PILOT ERROR IN TECHNIQUE/JUDGMENT	9. SERVICING PERSONNEL	17. WEATHER
2. PILOT DEVIATION FROM NATOPS PROCEDURES	10. LYNCHING SIGNAL OFFICER	18. DESIGN AIRCRAFT
3. PILOT INCORRECT OPERATION OF A/C SYSTEM	11. OTHER PERSONNEL (Specify)	19. DESIGN CREW EQUIPMENT
4. PILOT OTHER (Specify)	12. ADMINISTRATIVE	20. DESIGN OTHER (Specify)
5. CREW	13. FACILITIES-RUNWAY, OVERSUN TAXIWAY, FLIGHT DECK	21. ROLLING/PITCHING DECK ROUGH SEAS
6. MAINTENANCE PERSONNEL	14. FACILITIES-NAV AIDS, LANDING AIDS (SRA, OGA, ILS, MIRROR)	22. MATERIAL FAILURE/MALFUNCTION
7. MAINTENANCE SUPERVISORY PERSONNEL	15. FACILITIES-CATAPULT, ARRESTING GEAR (Ship or field)	23. UNDETERMINED
8. SUPERVISORY OTHER (Specify)	16. FACILITIES OTHER (Specify)	24. OTHER (Specify)

1. NAME (Last, First & Middle Initial)	2. GRADE	3. BRANCH OF SERVICE	4. TYPE OF SERVICE	5. SERVICE OF SERVICE	6. AGE	7. YEARS OF SERVICE	8. RANK	9. POSITION	10. A/C CODE
PILOT (at controls at time of mishap)	JANIS	(b) (6)	USNR	24	1	RP	Pilot	A	
CO-PILOT (Identify & submit separate page 1)									

ITEM	ITEM	ALL	IN MODEL
11. ALL MODELS	17. CV LANDINGS DAY/NIGHT	10 / 0	0 / 0
12. ALL MODELS IN LAST 12 MONTHS	18. FCLP LANDINGS LAST 6 MONTHS DAY/NIGHT	20 / 2	20 / 2
13. ALL MODELS IN LAST 3 MONTHS	19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	2.6 / 3.4	2.2 / 3.4
14. ALL SERIES THIS MODEL	20. NIGHT HOURS LAST 3 MONTHS	16.1 / 13.8	
15. ALL SERIES THIS MODEL LAST 12 MONTHS	21. TOTAL HOURS IN JETS (if jet mishap) HELOS (if helo mishap)	371	
16. ALL SERIES THIS MODEL LAST 3 MONTHS	22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL	DATE 6 May 69	DURATION 2.2
23. DATE/GRADE LAST NATOPS STANDARDIZATION / CHECK	24. TYPE INSTRUMENT CARD	Standard	

25. NAME (Last, First & Middle Initial)	26. GRADE	27. BRANCH OF SERVICE	28. TYPE OF SERVICE	29. SERVICE OF SERVICE	30. AGE	31. YEARS OF SERVICE	32. RANK	33. POSITION

PART II MAINTENANCE, MATERIAL, AND FACILITIES DATA										
A. A/C HISTORY	1. DATE OF MANUFACTURE	2. FLIGHT HRS. SINCE ACCEPTANCE	3. NO. OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLT HRS. SINCE LAST PAR/OVERHAUL	6. LAST/PAR OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK	
B. ENGINE HISTORY	1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS. SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR. REQUESTED?	6. FLT HRS. SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK
	(1)									
	(2)									
	(3)									
	(4)									
C. COMPONENT HISTORY	1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURER'S PART NUMBER	3. TOTAL HRS. ON PART	4. NO. OF OVERHAULS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR. REQUESTED?	8. SER. NO. FOR/AMPEUR		
	(1)									
	(2)									
	(3)									
	(4)									
D. INCIDENTS & GROUND ACCIDENTS	1. PARTS REPAIRED		3. DIRECT MANHOURS INVOLVED		2. PARTS REPLACED					
	PART NUMBER	NOMENCLATURE			PART NUMBER	NOMENCLATURE				
E. ENGINE FAILURES	JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)									
	AT TIME OF FLAMEOUT	1. ALTITUDE	2. WS	3. RPM	4. EGT	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ALTITUDE		
	H. & G. FORCES	9. RELIGHT <input type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED	10. ALTITUDE	11. WS	12. MAX EGT	13. FUEL CONTROL <input type="checkbox"/> PRIMARY <input type="checkbox"/> MANUAL	14. NO. RELIGHT ATTEMPTS			
	INTENTIONAL SECURE	15. ENGINE SYMPTOMS			16. CAUSE OF SYMPTOMS					
	RECIPROCATING ENGINE FAILURE									
F. OTHER REPORT	17. ALTITUDE	18. WS	19. ALTITUDE	20. RPM	21. MSP	22. TORQUE/BMEP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE		
	INTENTIONAL SECURE	25. ENGINE SYMPTOMS			26. CAUSE OF SYMPTOMS					
	IDENTIFY OTHER REPORTS CONCERNING THIS MISUP									
1. AMPFUR SERIAL NUMBER										
2. OR MESSAGE REQUEST DATE-TIME-GROUP										
3. OTHER PRELIM REPORT OF ACCIDENT VA-122 071237Z May 1969										
4.										

JPMAY FORM 3750-1A (Rev. 3-63) Page 3

Page 66, OPNAV INSTRUCTION 3750.6, effective edition

3. SHIPS DATA

File

26-253

PART V

THE ACCIDENT

NJ 209, A7A BUONO 152664, pilot BACHEMEIER, launched from runway 32 right at NAS Lemoore at 0111T on 7 May 1969 on an authorized night field mirror landing practice (FMLP) flight (enclosure (1)). Fuel quantity at start was 8,100 pounds requiring the pilot to climb out to a minimum altitude of 6000 feet, dump excess fuel in order to be at a maximum of 6000 pounds on his first practice landing, and to report the initial for pattern entry on the primary FMLP runway, 32 left.

Preflight, post start checks, taxi and launch were normal and the pilot reported Westhaven initial for FMLP at 0116 (enclosure (2)). Lemoore tower advised NJ 209 to call the break, and advised him that runway lights were off, flight deck lights on. The pilot made a normal break, taking interval on an A3 already established in the pattern. He called the abeam position on his first pass, did not have external lights set up correctly abeam, adjusted his lights, flew an angling approach, was not set up on the ball and executed his own wave off (enclosure (3)). He turned downwind for his second approach, called the Ball at 0124, fuel weight 6000 pounds, and continued in for a touch and go landing. During the final seconds of his approach radio traffic began to increase with two more A7s calling initial and a technique discussion took place between the LSC and the A3 pilot. NJ 209 turned downwind for his third pass, his interval still the A3, and was approaching the abeam position when the flight of the two A7s broke behind him. A second section of A7s entered the break as he flew his third approach to a successful touch and go landing. His touchdown, power application, rotation and climb were normal and tower advised him after lift off that his interval was a flight of two breaking upwind. He did not acknowledge the transmission and was observed to transition from a climb to a dive and his aircraft impacted the ground at 0128 in a wings level attitude just off the left hand edge of the runway (enclosure (4)). The aircraft exploded on impact and burned (enclosures (4), (5) and (6)). The fires were extinguished by the NAS Lemoore crash crew and the pilot died in the crash. No ejection attempt was observed.

PART VI

DAMAGE TO THE AIRCRAFT

NJ 209 A7A BUONO 152664 impacted the ground 50 feet to the left of runway 32 left on a heading of 310 \pm 2° at NAS Lemoore (enclosure (7) and (8)). Aircraft attitude at impact was approximately 6° nose down, 10° right wing down. Airspeed was 145 kts true. The aircraft was in the landing configuration, landing gear and flaps down. The nose gear made first contact and sheared followed by the right main gear, then the left. All struts exploded on impact. The lower empennage and arresting hook assembly were torn away and the aft fuel cell ruptured. An explosion and fire ensued which demolished the entire aft fuselage section, separating vertical and horizontal stabilizers. The wings, forward fuselage and engine, strewn parts, continued to a final resting place 430 feet from the initial impact point and burned intensely (enclosure (9)). The canopy unlocked on impact and flew clear of the main wreckage, sustaining only minor damage. Wings separated from the fuselage and the forward fuselage section from frame 346 forward tumbled and burned, leaving windshield plexiglass, portions of the ejection seat and pilot's equipment in its path. The NAS Lemoore hard stand crash crew observing the crash and having only a short distance to go, were on the scene very quickly and through their efforts it was possible to salvage cockpit instruments for investigation purposes. All parts, with the exception of the cockpit canopy, suffered impact and fire damage.

PART VII

INVESTIGATION AND ANALYSIS

1. General

The Board proceeded with the investigation on the assumption that a material failure or malfunction existed at the time of the accident. On the day following the accident, the Board was joined by a Safety Center investigator whose technical knowledge was of great value during the course of the investigation.

Three failure areas; engine, controls, and electrical, were selected as possible causes and were subjected to minute investigation. A discussion of findings follows:

(a) Engine failure: The TF 30 P6 engine and components were examined at the crash site and later removed to IMA to be **disassembled**. The engine's N1 compressor first stage was stripped of half its blades and indicated at least one turn after impact against strong resistance. All blades showed bending counter to the normal direction of rotation and severe FOD. Inlet guide vanes were all cracked at their bases indicating sudden stoppage and severe torque on the forward part of the engine. The N1 compressor second stage was also bent counter to normal direction of rotation and was damaged by first stage blades and a mixture of dirt and gravel. Disassembly of the engine showed similar damage and dirt ingestion to extend through all N1 compressor stages but no further. The hot section and burner cans showed no damage nor did the turbine. The number six bearing and scavenge pump were undamaged and had no signs of wear. Samples of clean, amber oil were taken and proved negative on analysis. The accessory gear case was broken open on impact and its parts strewn over 400 feet indicating the dissipation of energy that should be expected if it was operating normally. The lower shaft gear and its meshing main accessory drive gear indicated normal N2 rotation prior to, and for a time after, impact. Engine instruments recovered indicated 1950 PPH fuel flow and 630° turbine inlet temperature.

The final opinion of the assembled experts was that the engine was operating normally at 83 ± 2% RPM at impact.

(b) Control failure: due to the location of the crash site near the edge of the runway and the nose down, near wings level altitude at impact, (confirmed by witnesses, ground scars, damage, and instruments), control malfunction in pitch was suspect. UHT actuators and the pitch trim motor were disassembled. The actuators were in good condition, bleed plugs secure and properly wired. The two cylinders had an ample quantity of hydraulic fluid on both PC1 and PC2 sides. Both UHTs were in the same relative position at impact. The pitch trim motor was intact and functioned normally after it was removed and power applied to it. Pitch trim was set at 5° nose up, a trim setting that is "Hands off" at about 140 KIAS, level flight in the dirty configuration. The cockpit trim indicator was showing about 4° nose up.

Further discussion on the control system will be found under pilot factors. No discrepancies were found in any of the components.

(c) Electrical System failure: The possibility of an electrical system or cockpit lighting failure was examined closely. Eye witnesses confirmed aircraft exterior lights up to impact. The emergency power package was not deployed, therefore the main generator was on the line. Cockpit lighting controls were in the expected position, with flight instrument, non-flight instrument, console and dim flood lights on. Critical flight instrument lights were intact and operated on bench checks. All warning, caution and advisory bulb filaments were inspected and determined to be off at impact. Console light bulb filaments showed evidence of being on at impact. Agreement of the main and standby attitude indicators precluded the failure of either instrument, and their agreement with witness accounts indicated proper operation.

The Board found no evidence of electrical system malfunction or failure.

2. Pilot Factors

LTJG BACHMEIER was designated a Naval Aviator August 1968. His flight grades throughout basic and advanced training were generally above average. Minor difficulties were noticed in instrument navigation phases but he did very well in the basic instrument stages. After reporting to VA-122 he completed VA-122's instrument course in the T-4 with a grade of 2.94 (2.96 average RP grade) and was described as "middle of the road" in instrument ability. His progress in the A7 was smooth. The VA-122 instrument stage was completed with a 2.96 grade. Minor scan difficulties were indicated on two flights but nothing that could be considered serious.

LTJG BACHMEIER had recently returned from a two week weapons deployment to Yuma Arizona on which he flew regularly at night and showed average ability. He had two low pullouts on night bombing runs but not dangerously low. He had reached the stage in A7 training, with 82 hours in type, where all that remained in the R-3 syllabus was FCLP, Carqual and three other advanced stage flights.

At 1500 on the afternoon of 6 May 1969, LTJG BACHMEIER reported for his first scheduled activity of the day, briefing for a PNR-3 hop. The PNR-3 is a very demanding low level full systems flight flown solely on instruments under the hood, or, in the case of the A7, under the radiation shield. Generally, most Replacement Pilots feel that successful completion of the PNR-3 is "Graduation Day" in the A7. The flight demands extensive and meticulous planning and a great deal of study. LTJG BACHMEIER was well prepared and the flight, of 2.2 hours duration, was well flown. They launched at 1620 and returned at 1830. After a debrief LTJG BACHMEIER went home for dinner and some rest prior to his next scheduled activity. His sojourn at home, however, could not be considered too restful (enclosure (13)). At 2330 he was picked up by a fellow RP and returned to the squadron for his first night FCLP period. The LSO gave a 15-20 minute detailed brief on procedures which stressed the importance of the instrument scan in the night FCLP pattern.

LTJG BACHMEIER, after the brief, preflighted and manned NJ 209. According to his plane captain, the preflight, start and taxi evolutions were routine. His aircraft had an ASN-50 (attitude and heading reference system) gripe that had been repaired by replacement of the main gyro unit and ground checked. The indicator had spun on the previous flight while the pilot was doing overhead maneuvers but gave normal indications at all other times. The accident board checked out the indicator, and in spite of damage it functioned properly. The board also retrieved the replaced gyro and found that although defective it would not have produced the failure described by the pilot. Therefore it is surmised that the discrepancy was not actually corrected and could have recurred had the aircraft been subjected to stress in high "G" maneuvering. The policy of assigning an aircraft with a previous primary flight instrument discrepancy, even through the discrepancy has been written off, to a night or instrument flight is questioned. The acceptance of such an aircraft by the pilot is also questioned. The board feels, however, that the gripe was not a factor in this accident. A failure of this type would be induced by a loss of any one of three phases supplying power to the system. The phase loss could stem from a number of areas if the aircraft was subjected to stretching under stress. The very nature of LTJG BACHMEIER's flight precludes sustained high "G" maneuvering and he should have had normal operation. As mentioned earlier, agreement of the ASN-50 and the standby gyro indicated proper operation of both instruments, as did the absence of erratic maneuvers.

LTJG BACHMEIER launched at 0111 from runway 32 right. Excess fuel on board (8000 lbs) required him to dump fuel to landing weight (6000 lbs) and enter the initial for 32 left the primary PMLP runway. This phase was accomplished without incident and LTJG BACHMEIER called the initial at 0117. The night could best be described as black. There was a half moon, but a high thin layer of clouds obscured it most of the time and during these periods the horizon was not visible. LTJG BACHMEIER broke downwind over the lighted field carrier deck and entered the PMLP pattern. Runway lights were not lighted because an A3 was already established in the pattern and it was LTJG BACHMEIER's interval. He was admonished by the LSO, after calling ahead, for not having his exterior lights properly set up. Through a combination of being slightly wide ahead and adjusting his lights he overbanked and flew an angling approach to the runway. Picking up a late ball and not set up, he executed his own wave off and turned downwind to take interval on the A3. His next approach to a touch and go was without incident. He was a little rough and went low in the middle but responded to an LSO call. At this point the situation became a little hectic in the pattern. A flight of two A7s called the initial, the tower

gave them break information, and a dissertation between the A3 pilot and the LSO took place, cluttering the air. However LTJG BACHMEIER's interval was still the A3 and his turn downwind after lift off was accomplished with no difficulty. On his third approach he called the ball with 5800 pounds fuel, completed his touch and go and rotated to a normal climb. Just prior to his touchdown a second flight of two A7s entered the break and were given interval on the A3. The attention of both LSOs was diverted at this point to an aircraft low at the abeam position and the controlling LSO called a warning to him. The tower operator's attention was on LTJG BACHMEIER's aircraft and he called out BACHMEIER's interval as a flight of two A7s breaking upwind. At the time of the interval transmission the flight of two A7s was directly ahead of BACHMEIER and opening so that all he had to do was look straight ahead to sight them. The tower operator and one of the hard stand crash crew personnel observed NJ 209 to transition from the climb to a nose down wings level attitude until it impacted the ground. The tower operator had no time to broadcast a warning (the transmission to the A7 low at the 180 was equally important) but called "Crash" as he realized that the aircraft was not going to recover. Two other witnesses observed the aircraft in its descent and stated that the aircraft added power prior to impact, but analysis of distance and sound travel proved that the power application they heard was the power applied on the touch and go.

The crash crew operator near the runway stated that the only power change after application on the touch and go was the "usual" reduction made as aircraft transition to a level-off. After the accident board had reached the conclusion that the aircraft had not suffered a failure the Safety Officer member of the board launched in a similarly weighted aircraft for reconstruction of the accident. With an investigator on the ground timing, and the same control tower operator in the tower, the approach, landing, rotation and power application, reduction of power and transition to a nose down wings level attitude pointing at the initial impact point 5500 feet up the runway was duplicated. The tower operator corrected the pilot's transitioning altitude until satisfied that the pattern was exact. The flight profile substantiated evidence found in the wreckage and in witness' statements very closely. The time from initial touch down to final impact was 23 seconds. Adjusted for the speed of sound in the existing calm wind situation the time agrees with the power application heard "just prior to impact" by the witnesses approximately 1 1/2 miles away. The altitude reached by the aircraft in the climb/live transition was 500 feet MSL or 265 feet AGL. Normal pattern altitude is 700 feet MSL. The transition from an optimum angle of attack climb to the 5.5 degrees nose down attitude required to reach the impact point can be completed with ease and once the attitude is reached it takes only 4-5 seconds for the aircraft to impact. Airspeed in the nose down attitude was 145 kts true. LTJG BACHMEIER's true airspeed

indicator was frozen at 145 kts. Aircraft heading was 308 degrees, 12 degrees left of runway heading. Both BACHMEIER's ADI and HSI were on 308. Gyros from the stricken aircraft agreed with eye witness accounts and ground scars.

In view of the above the board feels that LTJG BACHMEIER flew his aircraft into the ground under controlled conditions and further that he was totally unaware of impending disaster. The aircraft broke up almost immediately and caught fire, main portions slid for 400 feet. The undamaged cockpit canopy detached almost immediately due to impact "G" unlocking the handle exposing the pilot to fire. The canopy gas actuator showed heavy heat damage prior to its extension indicating that it was "cooked off" rather than deliberately fired. As the fuselage and wings separated, pieces of the ejection seat were torn loose and the pilot was exposed to forces strong enough to tear the boot sole from his right flight boot. The cockpit area was engulfed in fire and tumbled to its final resting place, inverted. The pilot and the remainder of the ejection seat were thrown clear of, but within 15 feet of, the forward fuselage. The pilot's helmet, with oxygen mask fittings badly damaged by fire, was 30 feet from the pilot's body with all straps burned away. The pilot's oxygen mask showing flash fire damage, oxygen supported, was thrown clear of the fire area 50 feet from the pilot's body. The oxygen hose detached below the mask and was partially consumed by fire 130 feet short of the pilot's body. There was no possibility of an attempted ejection.

Inattention to flight instruments for a brief 5-6 seconds while transitioning was sufficient to cause LTJG BACHMEIER to crash his aircraft. Searching for his interval or interpreting their relative movement, distraction induced by extraneous transmissions during his three approaches, disruption of his interval with the arrival of additional aircraft, fatigue after a long day and a very demanding earlier flight all could have combined to cause a scan breakdown. The lack of a visible horizon made it a necessity to fly primarily on instruments throughout the majority of the approach. Failure to maintain his instrument scan in a critical transition phase proved fatal to the pilot.

3. Material Failures or Malfunctions. None

4. Facilities.

(a) NAS Lemoore's hard stand crash truck, due to the alertness of it's civilian crew, was on the roll instantly and should be commended.

(b) The NAS Lemoore Tower Controller's actions could not be criticized. The elapsed time between the NJ 209 transition to a nose down attitude and impact was no more than ten seconds, and the interposition of an important LSO call at the crucial moment cut this time to about two seconds. His decision not to interrupt the LSO's transmission to the aircraft low at the 180, for a situation he was unsure of, is considered sound.

5. NATOPS is not considered a factor.

10

6. Maintenance, Servicing, and Ground Handling Personnel Factors.
None.
7. Supervisory Factors.

(a) The Board feels that LTJG BACHMEIER was overscheduled. In view of the complexity of the PNR-3 Low Level Flight it is felt that the flight itself constitutes a full day's work. It is noted that the Flight Schedule, as written, commits LTJG BACHMEIER to a 15 hour work day. However, it is misleading in that the FMLP period is a block time from 0155 to 0600 and there is no breakdown for individual periods. Dependent upon aircraft availability, priority is established for assignment of aircraft by the Operations Duty Officer according to the severity of the working day for the pilots concerned. LTJG BACHMEIER was assigned his aircraft early and launched 10 minutes prior to the remainder of the flight. Had he completed his required one FMLP period he would have been on deck 11 hours after reporting for work, well within the framework of a maximum 12 hour day established by the Commanding Officer. The Board feels that, in spite of the inconsistencies of deck time and aircraft availability, the schedule should not reflect a working day in excess of 12 hours for any one pilot, RP or IP. Consideration must also be given to the types of flights flown if more than one is scheduled.

(b) Although there is no established policy on the subject it is an accepted practice on the part of most squadrons to direct that an aircraft, after a primary flight instrument failure, be flown in day VFR conditions before being scheduled for a night/instrument flight after corrective actions has been taken. The practice is sound and should be adopted in the squadron although it was not a factor in this accident.

PART VIII
CONCLUSIONS

The Board concludes that:

1. The aircraft was mechanically sound.
2. LTJG BACHMEIER was adequately prepared for the flight.
3. LTJG BACHMEIER unintentionally flew into the ground while in control of his aircraft.
4. LTJG BACHMEIER died instantly on impact with no ejection attempted.
5. The primary cause of the accident was pilot error in that LTJG BACHMEIER allowed his instrument/visual scan to break down at a point where an accelerated scan was demanded.
6. Possible causes of the scan breakdown are:
 - (a) Searching for interval and their relative movement
 - (b) Distraction caused by communications traffic
 - (c) Fatigue

PART IX

RECOMMENDATIONS

The Board Recommends that:

1. The daily Flight Schedule be closely monitored to preclude the possibility of pilot fatigue through either the length of the working day or the complexity of scheduled events.
2. A firm Maintenance Department Policy be adopted prohibiting night or Instrument Flight prior to a day/VFR flight in an aircraft which has undergone work for correction or a primary flight instrument discrepancy.
3. The importance of maintaining an instrument scan during night flights under VFR conditions cannot be overstressed. Pilots must be constantly reminded that they are subject to fatal error in a fatigue condition and should not fly if in doubt.

LIST OF ENCLOSURES

1. Copy of VA-122 Flight Schedule for 6 May 1969
2. Copy of Tower Tape Transcription
3. Statement of LT (b) (6) LSO
4. Statement of (b) (6), AC2, Control Tower Operator
5. Statement of (b) (6), Civilian Crash Crew Operator
6. Statement of (b) (6) AN, A3 crewman
7. Photograph of crash site and witness locations
8. Photograph of initial impact point
9. Photograph of wreckage (overhead)
10. Wreckage diagram
11. Photograph of wreckage showing mid fuselage, fwd fuselage and engine
12. Statement of LTJG (b) (6) A7 pilot
13. Fire/Rescue report
14. 5 year summary of pilot experience
15. Medical Officer's Report

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

(1) 0730-1845 (2) 11-11-11

11-00000-1000 K-12 GRADE SCHOOL, 10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68-69-70-71-72-73-74-75-76-77-78-79-80-81-82-83-84-85-86-87-88-89-90-91-92-93-94-95-96-97-98-99-100-101-102-103-104-105-106-107-108-109-110-111-112-113-114-115-116-117-118-119-120-121-122-123-124-125-126-127-128-129-130-131-132-133-134-135-136-137-138-139-140-141-142-143-144-145-146-147-148-149-150-151-152-153-154-155-156-157-158-159-160-161-162-163-164-165-166-167-168-169-170-171-172-173-174-175-176-177-178-179-180-181-182-183-184-185-186-187-188-189-190-191-192-193-194-195-196-197-198-199-200-201-202-203-204-205-206-207-208-209-210-211-212-213-214-215-216-217-218-219-220-221-222-223-224-225-226-227-228-229-230-231-232-233-234-235-236-237-238-239-240-241-242-243-244-245-246-247-248-249-250-251-252-253-254-255-256-257-258-259-260-261-262-263-264-265-266-267-268-269-270-271-272-273-274-275-276-277-278-279-280-281-282-283-284-285-286-287-288-289-290-291-292-293-294-295-296-297-298-299-300-301-302-303-304-305-306-307-308-309-310-311-312-313-314-315-316-317-318-319-320-321-322-323-324-325-326-327-328-329-330-331-332-333-334-335-336-337-338-339-340-341-342-343-344-345-346-347-348-349-350-351-352-353-354-355-356-357-358-359-360-361-362-363-364-365-366-367-368-369-370-371-372-373-374-375-376-377-378-379-380-381-382-383-384-385-386-387-388-389-390-391-392-393-394-395-396-397-398-399-400-401-402-403-404-405-406-407-408-409-410-411-412-413-414-415-416-417-418-419-420-421-422-423-424-425-426-427-428-429-430-431-432-433-434-435-436-437-438-439-440-441-442-443-444-445-446-447-448-449-450-451-452-453-454-455-456-457-458-459-460-461-462-463-464-465-466-467-468-469-470-471-472-473-474-475-476-477-478-479-480-481-482-483-484-485-486-487-488-489-490-491-492-493-494-495-496-497-498-499-500-501-502-503-504-505-506-507-508-509-510-511-512-513-514-515-516-517-518-519-520-521-522-523-524-525-526-527-528-529-530-531-532-533-534-535-536-537-538-539-540-541-542-543-544-545-546-547-548-549-550-551-552-553-554-555-556-557-558-559-560-561-562-563-564-565-566-567-568-569-570-571-572-573-574-575-576-577-578-579-580-581-582-583-584-585-586-587-588-589-590-591-592-593-594-595-596-597-598-599-600-601-602-603-604-605-606-607-608-609-610-611-612-613-614-615-616-617-618-619-620-621-622-623-624-625-626-627-628-629-630-631-632-633-634-635-636-637-638-639-640-641-642-643-644-645-646-647-648-649-650-651-652-653-654-655-656-657-658-659-660-661-662-663-664-665-666-667-668-669-670-671-672-673-674-675-676-677-678-679-680-681-682-683-684-685-686-687-688-689-690-691-692-693-694-695-696-697-698-699-700-701-702-703-704-705-706-707-708-709-710-711-712-713-714-715-716-717-718-719-720-721-722-723-724-725-726-727-728-729-730-731-732-733-734-735-736-737-738-739-740-741-742-743-744-745-746-747-748-749-750-751-752-753-754-755-756-757-758-759-760-761-762-763-764-765-766-767-768-769-770-771-772-773-774-775-776-777-778-779-780-781-782-783-784-785-786-787-788-789-790-791-792-793-794-795-796-797-798-799-800-801-802-803-804-805-806-807-808-809-810-811-812-813-814-815-816-817-818-819-820-821-822-823-824-825-826-827-828-829-830-831-832-833-834-835-836-837-838-839-840-841-842-843-844-845-846-847-848-849-850-851-852-853-854-855-856-857-858-859-860-861-862-863-864-865-866-867-868-869-870-871-872-873-874-875-876-877-878-879-880-881-882-883-884-885-886-887-888-889-890-891-892-893-894-895-896-897-898-899-900-901-902-903-904-905-906-907-908-909-910-911-912-913-914-915-916-917-918-919-920-921-922-923-924-925-926-927-928-929-930-931-932-933-934-935-936-937-938-939-940-941-942-943-944-945-946-947-948-949-950-951-952-953-954-955-956-957-958-959-960-961-962-963-964-965-966-967-968-969-970-971-972-973-974-975-976-977-978-979-980-981-982-983-984-985-986-987-988-989-990-991-992-993-994-995-996-997-998-999-1000-1001-1002-1003-1004-1005-1006-1007-1008-1009-1010-1011-1012-1013-1014-1015-1016-1017-1018-1019-1020-1021-1022-1023-1024-1025-1026-1027-1028-1029-1030-1031-1032-1033-1034-1035-1036-1037-1038-1039-10

0000-1000 PLANT CHARACTERISTICS (PF-7) LT (b) (6)

1000-1130	3.1 BTI, SURVIVAL EQUIP.	(FF-3)	LT
1130-1200	1200		

1230-1530 AIRBORNE C. PRODUCTIONS (PP-6) LT

1530-1600 HATERS REVIEW

REVIEW TO 7-127 FOR H.H.P.S./STANDARDIZATION TEST AND
CHECK HOP.

1200-1600 W.O.D., 3100, 004 (WFO), FOR CLASS 2-69 AND LITC (b) (6)

(b) (6) (b) (6) (b) (6)

0730-0900 (b) (6) WST-3 1000-1100 12 (b) (6) 1100-1200 (b) (6)

0900-1000 7-11-93 OPT- 200-400 LI (B) LEAD (B) (S) STANDARDIZATION/WATOPS CHECK

1500-1200 VA-56 OPT-5 1630-1800 (b) (6) WST-1
O.D. BANCORP, THE FUNCTION OF THE ADJUTANT GENERAL SYSTEM

Page 1 K-104 STA 3; ROAD 1 D ST. 6; ROAD CP 741 SYS; IP 30,000; P/H 23,700. CONT

4. WWT 120.2001 TRX 3-16; TOT P-4. 341.0; Call AS "WWT 120.2001" ISSUED.

Q	AFC	A/C	STD	AST/	POPU	STD/A..
100%	80-90%	80-90%	80-90%	80-90%	80-90%	80-90%

NO	FLY IN	FLY OUT	FLY DURATION	FLY PILOT	FUEL TIME	CH	TEMP	REMARKS
1.	3/1-7	0630	1-1 2:00	(b) (6)	8000	4.7	19	2537

0830 PTT-2 17 CAPTIVE

1/a=7 1000 1L2 1+30 278 67 SIDWINDER 8000# 2.5 17 016 16 10

9900 F.C.F. [REDACTED] [REDACTED]

(b) (6)

0901
18/00

DO-175 TO VTL

901 27 420 1015 240 110 2745 277 (b) (6) 743 98004 6.0 2013/1/29

4-7 1215 260 CS 3/ 2-15 2-15 11500/ — NOV 1

2/11-7 1030 1:2 2-30 (b) (6) 95006 1:2 20

1230 PWT-3

1/T-28 1530 174 1+00 (b) 3+30 2.2 16/6/87 71125

1630
1730

DD-175 TO HQZ
PAGE TWO

7. 2/4-7 1500 1x2 2x30 2x2 (b) 9500# 2.2 20 16x7/7 1/2

1700	PITK-3	<u>2.1</u>	(b) (6)	<u>2.2</u>	
1930					

1/TA-4 1500 141 2+00 (b) (6) 8400/ 18 12/1/1A

1/4-7	1700	PTT-3	(b) (6)	* CAPTIVE
	1900		(b) (6)	SID BINDER

1/TA-4	1500	1.1	2+00	12.2	3400#	1.7	19	12.2/12.4
--------	------	-----	------	------	-------	-----	----	-----------

1700	PTT-1		* CAPTIVE
1/4-7	1900	25	3000# / 6 SID NUMBER

11. 2/1-7 1830 3.2 2+15 25 3000# 2.1 18 25/15

2030	PFL-5	<u>2.2</u>	<u>2.3</u>
2245			

11. 2/4-7 1900 34.2 2+15 37.1 8000# 19 FEB

2315

2. 8/4-7 0100 343 0+50 (b) (6) 6000# 0.7 17 13.67

DATE	0600	TIME	0600	DATE	0600	TIME	0600
------	------	------	------	------	------	------	------

$\frac{2.2}{1.97}$
 $\frac{0.8}{1.97}$
 LSO: POLLY
 H: ELY
 H: LD

128 126 120

THIRLED (b) (6) NECESSARY

..-7 SYL LABS SORTING SCHED. L.D. 23 /LOWN 17 ..-7 TEST SORTING SCHED. 1 /LOWN

1-4 SORTIES SCHEDULED 2 T-28 SORTIES SCHEDULED 2
SUBMITTED: 1 APPROV. D: Special Handling Required in A

[Faint handwritten notes at the bottom of the page]

ENCLOSURE (1) | With OPNAVINST 9300.2

MASTER TO B-11 FLIGHT SCHEDULE

NO.	DATE	TO	FROM	TYPE	PILOT	FUEL	TIME	REMARKS	STATUS
1	1/11	11:00	14:00	14:00	(b) (6)	8000'	1.9	6-10	SL
2	1/11	11:00	14:00	14:00	(b) (6)	8000'	1.9	6-10	SL
B-7 SYLLABUS HOURS									
SCHEDULED		410		FLOWN		227			
B-7 TEST HOURS									
SCHEDULED		1.5		FLOWN		29			

A-7 HOURS SCHED: _____
 A-7 HOURS FLOWN: _____
 A-7 SORTIES SCHED: _____
 A-7 SORTIES FLOWN: _____
 A-7 SORTIES LOSS WX: _____

T-28 HOURS SCHED: _____
 T-28 HOURS FLOWN: _____
 T-28 SORTIES SCHED: _____
 T-28 SORTIES FLOWN: _____
 T-28 SORTIES LOSS WX: _____

NIGHT HOURS SCHED: _____

NIGHT HOURS FLOWN: _____

Operations Duty Officer shall add totals and deliver to Squadron's Schedules Office upon completion of flights ops. The completed Master Schedule shall then be retained for a period of six months by the Operations Dept. following its approval by the Commanding Officer.

Special Handling Required in Accordance

TRANSCRIPTION OF VOICE RECORDING

FACILITY PREPARING TRANSCRIPTION: Lemoore Radar Air Traffic Control Center

SUBJECT: Radio Communications concerning accident of November Juliett 209,
A-7, VA-122 of 7 May 1969.

DATE AND TIME COVERED BY TRANSCRIPTION: 7 May 1969, 0116½ to 0129 Local

AGENCIES MAKING TRANSCRIPTIONS:

ABBREVIATION:

1. NJ 209	209
2. Lemoore Tower	Tower
3. 102, A-3	102
4. VA-122 LSO	LSO
5. NE 305	305
6. NJ 278	278

CERTIFICATION:

I HEREBY CERTIFY that the following is a true transcription of the recorded conversation pertaining to the subject accident.

(b) (6)

(b) (6)

CDR, USN

RAIIC OFFICER

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPMVINST 3750.6 SERIES

Enclosure (2)

TIME	AGENCY	TRANSCRIPTION
0116½	209	Tower, November Juliett 209's at Westhaven.
	Tower	209 call the Break, the runway lights are off. Flight Deck's on.
	209	09.
	102	PADDLES, here we are again, high ball, we're inside, we followed your instructions.
	LSO	Roger.
	Tower	102 Tower, what's your speed around the pattern?
	102	Say again.
	Tower	What's your speed around the pattern?
	102	whatever you want it to be, what do you want?
	Tower	I just wanted to make sure that the A-7 is compensated.
	102	About a hundred and thirty.
118½	Tower	209 your interval is 10 o'clock, low, downwind, an A-3, cleared downwind on him.
	209	209 Roger.
	209	09's Breaking.
	Tower	09 Roger Left Break approved.
0120	102	Paddles 102 Skywarrior Ball, 74.
	LSO	Roger Ball.
0120½	209	209's at the 180, Pilot Bachmeier.
	LSO	Roger.
0120:3/4	LSO	Ok 209 let's get your lights set up there and you'r too wide abeam.
	209	09.
	102	102 Downwind.
0121	Tower	Interval's at the 180.
	LSO	Light's bright and steady 09.
0121½	209	209's Clara.
	LSO	Roger you'r angling in, keep flying over to the center line.
	209	Roger, Ball.
0121:3/4	209	09's waving off
	LSO	Start your turn.
0122	Tower	09 interval 9 o'clock.
	209	09 Roger.
	102	102 Skywarrior Ball, seven thousand.

TIME	AGENCY	TRANSMISSION
	LSO	Roger Ball. Garbled Transmission.
0124	209	09 Corsair Ball, Six Zero.
	LSO	Roger Ball.
0124½	LSO	Going low.
	NE 305	Lemoore Tower NE 305 westhaven with two for FOLP's.
	Tower	305 and flight report the Break for 32L, your number one reported to the break, runway lights are off, Flight Decks on.
	305	05
	LSO	102 Paddles
	LSO	Roger 102 Paddles.
	102	Go Ahead.
	LSO	Roger, time to make a correction for that fast start is early in the approach so that you don't get that decell all the way coming down in close.
	102	Roger.
0125:3/4	WJ 278	Lemoore Tower November Juliett 278 Westhaven, flight of two, FOLP's.
	Tower	278 call the Break, Flight deck's on, runway lights are off.
	778	78 Roger.
	Tower	305 your interval is approaching the 180, downwind at your 10 o'clock, Left Break approved on him. Number 3 & 4.
	305	05
	102	Paddles, 102, Skywarrior Ball, 6 point 8.
	LSO	Roger Ball.
	LSO	Ok you'r a little low, you need to come left for line up.
	LSO	Attitude.
0127	Tower	102 your interval breaking 12 o'clock high upwind.
	102	02.
	102	I appreciate the interest there paddles but that was one hell of a late wave-off. I touched down anyway.
	LSO	Roger, you hit the Ramp for the second time in a row, How about flying the glide slope with power and airspeed with the nose south that it would get on the glide slope with a set up early.

TIME	AGENCY	TRANSMISSION
	102	I'm trying Paddles, I'm not asleep up here, I'm just telling you that's a hell of a late wave-off.
0127 $\frac{1}{2}$	LSO	Roger, I know it.
	209	209 Corsair Ball 58
	LSO	Roger Ball.
	Tower	278 Your interval's 12 o'clock upwind.
	278	78 Roger.
	Tower	An A-3.
0127:3/4	305	305, 180 gear down, 62, Funderup
	Tower	209 your flight, correction, your traffic a flight of two, breaking upwind A7's.
0128 $\frac{1}{4}$	LSO.	At the 180 check your altitude.
0128 $\frac{1}{4}$	Tower	Crash, Crash.
	Tower	Paddles, Tower, wave everything off, Delta the Pattern.
	LSO	Roger, all aircraft in the Pattern, Pattern Delta.

Statement of (b) (6), LT, USNR, (b) (6) LSO, concerning VA-122 aircraft accident 15-69A, A7A, BUNO 152604 occurring 7 May 1969, pilot BACHMEIER

On the night of 6 May 1969 at approximately 2400 hours, I briefed LTJG BACHMEIER, plus the other replacement pilots in the class, on night FMLP procedures. Reference was the VA-122 LSO briefing guide and topics discussed included the following:

1. Night Lighting-aircraft & field lighting
2. Carrier Deck Lighting
 - a. Feeling of being high with no other visual peripheral aids
3. Pattern Techniques
 - a. Same as day pattern but you can't see
 - b. Must fly instruments
4. IFR/VFR Scan
 - a. Emphasis was placed on the fact that night MLP flying required maximum pilot skills and attention; Basic instrument scan must include outside of cockpit. Night FMCP demands the maximum of pilot effort.

At approximately 0045 7 May 1969, I arrived at the LSO platform on runway 32L. Charlie time was 0100. I was informed by LTJG (b) (6) VA-27 LSO, that a K43 was in the pattern and desired MLP. I told him he could work the A3 until the A7's filled the pattern.

At approximately 0115, LTJG BACHMEIER entered the pattern via the break. He was the first A7 in the pattern along with the A3. On his first pass he undershot the runway, abandoned the approach and made a low pass flying up the runway. My comment was: OWO-PATT. His second pass was well set up and he flew the ball and touched down long. My comment: B→RUF P TMPIC B. His third and final pass was recorded: B→OCP LO FIC BAR.

While LTJG BACHMEIER was making his third pass, two more A7's entered the break. About 10-15 seconds after NJ 209 lifted, the other LSO told me to check the 180. I did, observed an aircraft appearing to be low and transmitted, "At the 180, check your altitude". At that moment I saw a flash of light and heard the tower say, "Crash, crash". My conversation with the tower after that is as follows:

Me: Tower, paddles, what aircraft was that ?

Tower: 209 sir

Me: Did you observe an ejection sequence ?

Tower: No sir

Me: What happened?

Tower: I don't know sir. He climbed to pattern altitude then dove into the ground.

I then left the platform and went to the crash site.

I believe that looking west, i.e., towards the downwind leg, the cockpit visibility would necessitate IFR flight.

I have been a designated Naval Aviator since 26 October 1965, and have a total of 1314 flight hours, 117 hours in the A7 aircraft. I have 2 years experience as an LSO.

(b) (6)

Enclosure (3)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

Statement of (b) (6) AC2, USN, (b) (6), concerning
VA-122 aircraft accident 15-69A, involving A7A BUNO 152664,
pilot BACHMEIER

I was monitoring the MLP pattern on runway 32L on the morning of 7 May 1969. I saw NJ 209 climb from his touch and go, reach pattern altitude, and suddenly nose over and dive into the ground abeam the first high speed turn-off north of the CPN-4 site. The aircraft was in a wings level attitude during the entire time.

I yelled "crash, crash!" on the air, AC2 (b) (6) activated the crash phone, and the hardstand truck, 32L rolled all about the same time.

The aircraft exploded on impact. I did not see the pilot attempt to pull the aircraft out of it's dive just prior to impact, I saw no ejection sequence, and I did not notice any change to indicate the plane had flamed out.

I did not really realize something was wrong until it was too late. Everything appeared so normal that it wasn't until just before impact that I saw that the pilot was not going to pull out. Even when the aircraft nosed over in it's dive, the angle of descent was not unusually steep so as to cause immediate alarm. Judging from the impact point next to the runway, the pilot had not started his turn crosswind.

I have been a Tower Controller five years and hold a FAA Senior rating for the Lemoore area.

(b) (6) AC2
(b) (6)

Enclosure (4)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

Statement of R. L. BASSET, civilian, NAS Crash Crew Operator,
OS-3, concerning VA-122 aircraft accident 15-69A, A7A, BUNO 152664,
pilot BACHMEIER

On May the 7th, 1969, at approximately 0130, I was observing
MLP's on runway 32L when the A-7 in question crashed.

The aircraft made his touchdown and was started back up when
I seemed to notice a change in sound of the aircraft as if he were
throttling back. At this time he leveled out and started to descend.

I was standing outside of the assigned truck. I turned to run
for my truck and upon entering I looked up to see him touch down
and the aircraft catch fire and skid to a stop.

R L Basset
R. L. BASSET

This Board considers R. L. BASSET a credible witness.

Enclosure (5)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

Statement of (b) (6) AN, USN B (b) (6) concerning
VA-122 aircraft accident 15-69A, involving A7A BUNO 152664, which
occurred on 7 May 1969, pilot BACHMEIER

On the morning of May 7 at about 0130 I was standing at VA-125
hot refuel pit when I witnessed the crash of an A-7 on the left
runway 32 L.

Our aircraft, an KA-3B/B was in the MLP pattern at the time
and was due in for refueling. Our aircraft was making his approach
when two A-7s flew over the numbers and broke downwind. Following
that our aircraft bounced, climbed to altitude and turned downwind.
Then two more A-7s followed our aircraft. When our aircraft got to
about the 180, the first A-7 was at this time descending to the
runway. This is about 200 feet. At about 50 to 100 feet the A-7
added power but was still descending fairly fast. On impact there
was a burst of flame. It was not an explosion. I could see the
outline of the aircraft because of the flame. It looked to me as
though the plane was in a left skid and on impact, it looked as
though either the right main mount tire blew or the gear collapsed.
Then the plane went into a cartwheel down the runway for about
1000 to 2000 feet. About three fourths of the way down his wings
were separated from the aircraft. The flame was following the plane
down the runway. Then there was a large explosion.

To the best of my knowledge this statement is true.

I have been in the Navy for two years and five months and have
been associated with aircraft every since. I have been an aircrewman
for 13 months now. I have made two cruises to WESTPAC, the first
with spads and the second with the A-3.

(b) (6)


This Board considers (b) (6) a credible witness.

Certified True Copy

(b) (6)

Enclosure (6)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES




PHOTOGRAPH (7) IS VA-122 AIR SER 15-69A BUHO 152664
PHOTOGRAPH OF CRASH SITE AND WITNESS LOCATIONS
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3



ENCLOSURE (B) TO VA-122 AAR SER 15-50A BUNO 152661 PILOT BACHMAYER
PHOTOGRAPH OF INITIAL IMPACT POINT
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES



ENCLOSURE (9) TO VA-122 MAR 25-64
PHOTOGRAPH OF WRECKAGE (OVERHEAD VIEW)
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 1750.6 SERIES 1



VA-122 AAR 15-69A
WRECKAGE DIAGRAM

32L

WITNESS
(b)
5000 FT.

WITNESS
BASSETT
1000 FT.

WITNESS
(b) (6)
4500 FT.

N

SPECIAL HANDLING REQUIRED
IN ACCORDANCE WITH
OPNAVINST 3750.6 SERIES
ENCL (10)



ENCLOSURE (11) TO VA-122 AAR SER 15-69A BOMB 15000L PILOT BACHMEIER
PHOTOGRAPH OF WRECKAGE SHOWING MID FUSELAGE, FWD FUSELAGE AND ENGINE
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

Statement of (b) (6), LTJG, USN, (b) (6)
concerning aircraft accident 15-69A, A7A, BUNO 152664 occurring
7 May 1969, pilot BACHMEIER

On the night of the accident my wingman, LTJG (b) (6), USNR, and I had taken off at 0100 in order to burn down to FMLP landing weight. We circled the field and entered at Westhaven initial for entry into FMLP pattern about 0125. The runway lights were turned off and only the carrier deck lights were on making runway line-up a problem coming in from initial, since it was also a very dark night. I made a gentle wide turn from Westhaven to runway heading and used two aircraft for line-up, one was an A-3 approaching the ramp, and the other aircraft LTJG James BACHMEIER was flying which was approaching the "in the middle" portion of the glide slope.

As I assumed the proper line-up the A-3 was receiving a wave-off from the LSO and then began to garbage up the air with miscellaneous chatter, words to the effect that the LSO had given him a bad wave-off since he touched down anyway and besides he was taking or initiating his own wave-off to begin with. This chatter continued until he turned crosswind to take interval on the section which broke ahead of my section. It was then that I over flew LTJG BACHMEIER and was waiting for my interval on the A-3 who seemed to be somewhere way above pattern altitude and just below break altitude to commence my break.

It was during this wait for my interval that the LSO called my side number low at the 180 and I responded "Negative 278's at the break". The tower then proceeded to call interval either for LTJG BACHMEIER or aircraft coming from the initial. It was then that I looked into my mirrors and the only aircraft I could see was LTJG BACHMEIER. He seemed to be making an approach or finishing the final portion of the glide slope which he had commenced when I passed overhead. As it turned out he had already made his touch and go and when I caught sight of him in my mirrors he was going down immediately prior to the crash. Since all the runway lights were out I couldn't tell how far down the runway he was and just assumed he was finishing his approach and it was then that I saw a small bright flash just prior to my break. As I broke the fireball erupted and somebody shouted "Crash, crash, crash... .. which aircraft was that?...Answer. 209". I was in my crosswind turn just prior to putting down gear and could directly see the fireball and the plane erupt in a long line as the aircraft was skidding forward on the ground. Shortly thereafter we were first told to Delta and then Bingo to 32 right. Some of the aircraft in the pattern made downwind entries to 32 right and I went back out to the Hall's corner initial and landed.

I have been a designated Naval Aviator since 7 July 1967. I have a total of 389 flight hours, 82 hours in the A-3 aircraft.

(b) (6)

Enclosure (12)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

AIRCRAFT FIRE/RESCUE REPORT
BUWEP FORM 11135/1 (5-60)

NO TRANSMITTAL LETTER REQUIRED

REPORT SYMBOL BUWEP 11135-1

STATION AND LOCATION

Naval Air Station
Lemoore, California

DATE OF REPORT

5-7-69

AFR NO.

06-69

DATE AND TIME OF INCIDENT

5-7-69 - 0128

ON STATION

☒

OFF STATION

REPORTING CUSTODIAN

VA-122

MODEL AIRCRAFT INVOLVED

A7A

BUREAU NO.

152664

TO: **Commander N.A.S.C. (AIR-4232)**
~~Naval Air Station Lemoore, California~~

EXACT LOCATION OF INCIDENT

**Approximately 7300 Ft
 from approach end of 32L**

MILITARY COMMAND

COMFALANED

VIA

(b) (6)

TYPE OF INCIDENT

FIRE INVOLVED

ESTIMATED CASE

TAKE-OFF	LINE OR LOADING	FUELING	YES	<input checked="" type="checkbox"/>
LANDING	<input checked="" type="checkbox"/> PARKED	MAINTENANCE	NO	<input type="checkbox"/>
TAXIING	DEFUELING	INFLIGHT	IMPACT	<input checked="" type="checkbox"/>
OTHER (Specify)		DELAYED	LESION	<input type="checkbox"/>

CONDITIONS AT TIME OF INCIDENT

GENERAL WEATHER PICTURE

**H1 scattered - visibility
 12 miles**

WIND DIRECTION **300° T**
 WIND VELOCITY (mph) **2 Knots**
 TEMPERATURE (°F) **54°**

NATURE OF TERRAIN AT AND IN APPROACH TO INCIDENT

Concrete Runway

LIQUID FUEL QUANTITY

ESTIMATED ON BOARD BEFORE INCIDENT (lbs) **6000 lbs**
 ESTIMATED ON BOARD AFTER INCIDENT (lbs) **none**
 ESTIMATED SPILL AREA (Size in feet) **75' by 300' slide area (approx)**

OTHER FUEL

PERSONNEL RESCUE

NO. PERSONNEL ON BOARD AIRCRAFT	1
NO. PERSONNEL SURVIVED	0
NO. PERSONNEL ESCAPED UNAIRED	0
NO. PERSONNEL RESCUED	0

DESCRIBE RESCUE METHODS USED

**None - Pilot was thrown from aircraft at time of
 crash - did not survive.**

FIRE FIGHTING

FIRST METHOD OF ALARM USED

TIME RECORD

TWO-WAY RADIO ☐ EMERGENCY INTER-COM. ☐ EMERGENCY PHONE ☒

TIME ALARM RECEIVED **0128**

OTHER METHOD (State)

TIME EQUIPMENT ARRIVED **0129**

STATION EQUIPMENT

EACH EQUIPMENT AVAILABLE AT INCIDENT		NO. PERSONNEL MANNING EQUIPMENT		QUANTITY EXTINGUISHING AGENTS USED	
TYPE	NO. LOADS USED	MIL.	CIV.	FORM (gals. conc. used)	OTHER TYPES AND QUANTITIES
2 MD-1		3	6	95 Gal Foam	1800 Gal Water
1 MD-5		1	3	20 Gal Light H2O	600 Gal Water
1 Nurse T.		-	2	-	1800 Gal Water
1 Runway Foamer		-	2	-	1400 Gal Water
1 F. E.		-	2	-	

STATION EQUIPMENT OUT OF SERVICE

TYPE	DEFICIENCY	NO. OF DAYS	EXPLAIN DELAYS TO REPAIR
	None		

FULL DESCRIPTION OF FIREFIGHTING OR PROTECTION AT INCIDENT

- 0128 Notified via primary Emergency Crash Phone stating A-7 Crash on 32-L. All crash equipment responded.
- 0128 Secondary Phone stated same.
- 0129 Hardstand truck at scene.
- 0130 All other crash equipment at scene.
- 0141 MB-1 Lamore 8 reported that pilots body had been found.
- 0201 All crash equipment secured excepting Nurse Truck, 1 MB-1, F. E. and Pick-up remained at scene as precautionary standby and cleanup.
- 0230 All crash equipment in quarters from scene.




RECEIVED
NAVY SAFETY
CENTER

16 MAR 69 10 47 AM

135-5

DIAGRAM OF INCIDENT SHOWING WIND, DIRECTION, APPROACH OF
EQUIPMENT, POSITION OF AIRCRAFT, DISTANCES, ETC.
(Maps and photographs should be included, if significant)

300-T
WIND



32-L
WINDSTAND



Approx 125' From
edge of R/W

A/c engine

* Pilot's Body

SLIDE AREA

A/c Stopped Approx 7500' From Approach End

Approach End
R/W 32-L

**DESCRIPTION OF DIFFICULTIES IN FIRE CONTROL AND
EXTINGUISHMENT DUE TO UNUSUAL CONDITIONS OR EQUIPMENT
AND/OR AGENT INADEQUACIES**

None

**RECOMMENDATIONS FOR IMPROVEMENTS IN EQUIPMENT
AND/OR PROCEDURES TO INCREASE EFFICIENCY**

None

MONETARY LOSSES (Estimated)

PERCENT DAMAGE BY IMPACT		PERCENT DAMAGE BY FIRE		LOSS TO SURROUNDING PROPERTY	
100%				None	
DATE	PREPARED BY (Name and title)	SIGNATURE			
5-7-69	(b) (6) Platoon Captain	(b) (6)			
5-7-69	(b) (6) Platoon Capt				
DATE	STATION COMMANDING OFFICER	SIGNATURE			
5/9/69	L. B. CORNELL, Captain, USN	L.B. Cornell			

LTJG J. F. BACHMEIER'S RESUME OF FLIGHT EXPERIENCE

COMMAND ATTACHED	PERIOD ASSIGNED	MODEL AIRCRAFT	FLIGHT HOURS	CV LANDINGS DAY/NIGHT	OPERATIONAL/ PROFICIENCY
VT-7	JUN 67-JUL 67	T-34	27.6	0/0	OPERATIONAL
VT-4	AUG 67-MAR 68	T2A/B	123.5	4/0	OPERATIONAL
VT-24	APR 68-AUG 68	AF9J/TF9J	137.5	6/0	OPERATIONAL
(VA-127 A/C VA-122	NOV 68-MAY 69	T44F	29.2	0/0	OPERATIONAL
VA-122	NOV 68-MAY 69	T28B	2.0	0/0	OPERATIONAL
VA-122	NOV 68-MAY 69	A7A/B	82.0	0/0	OPERATIONAL

ENCLOSURE (14)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

MEDICAL OFFICER'S REPORT OF A CASUALTY, INCIDENT OR GROUND ACCIDENT
IDENTIFICATION, FLIGHT AND NARRATIVE DATA
 OPNAV FORM 3750/8A (REV. 4-68) S/N 0107-731-8101

REPORT SYMBOL 3750-7

See Section H of OPNAVINST 3750.6

I. IDENTIFICATION

1. FROM (Name and mailing address of activity) ATCRON 122, NAVAL AIR STATION, LEMOORE, CALIFORNIA 93245		2. MOR NUMBER 15-69A	3. DAMAGE CODE ALFA
4. TYPE OF MISHAP <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT	5. NO. OF OCCUPANTS ONE	6. DATE 7 MAY 69	7. MODEL A/C A-7A
8. MODEL OTHER A/C IF INVOLVED NONE	10. BUNO NA	11. NO. OF OCCUPANTS NA	12. DAMAGE CODE NA
13. INDIVIDUALS INVOLVED (Use Additional Sheets if Required) NAME (Last, First and Middle Initial) A. BACHMEIER, James Florian		14. RANK/RATE LTJG	15. BRANCH OF SERVICE USN
16. DUTY BILLET Replacement Pilot		17. INJURY CODE A	18. DISPOSITION F
19. PILOT AT CONTROLS AT TIME OF MISHAP A. BACHMEIER, James Florian			
20. CO-PILOT B.			
C.			
D.			

II. FLIGHT DATA (At Time of Emergency)

1. TERRAIN CLEARANCE zero FEET	2. CABIN ALTITUDE 235 FEET	3. TIME AT CABIN ALTITUDE 0 HOURS 17 MIN	4. AMBIENT ALTITUDE 235 FEET	5. TIME AT AMBIENT ALTITUDE 0 HOURS 17 MIN
6. PLACE IN FORMATION <input type="checkbox"/> A - SINGLE AIRCRAFT <input type="checkbox"/> L - LEAD <input type="checkbox"/> W - WING Y - OTHER (SPECIFY) Night mirror landing pattern -- 6 aircraft.		7. HORIZON <input type="checkbox"/> 1 - DISTINCT <input type="checkbox"/> 2 - OBSCURED 8 - OTHER (SPECIFY) Night -- no visible horizon.		
8. CLOUD CONDITIONS <input type="checkbox"/> 0 - CLEAR <input checked="" type="checkbox"/> 1 - OVERCAST Thin cloud layer. <input type="checkbox"/> 2 - UNDERCAST <input type="checkbox"/> 3 - IN CLOUDS <input type="checkbox"/> 4 - IN AND OUT OF CLOUDS 9 - OTHER (SPECIFY)		9. DURATION OF FLIGHT HOURS 0 MIN 17		

III. NARRATIVE ACCOUNT OF MISHAP (Continue on Reverse Side if necessary) LTJG James Florian BACHMEIER, III was a fleet replacement pilot with VA-122 who had 400 total flight hours and 82 A-7 hours, having completed all of the A-7 syllabus except night mirror landing practice, carrier qualifications, and three advanced syllabus flights.

He launched directly into the night mirror landing practice pattern from runway 32 Right at 0111T 7 MAY, 1969. Initial fuel quantity on board was 8,100 lbs. necessitating a climb to 6,000 feet to dump fuel to 6,000 lbs. to be at maximum fuel weight for his first mirror landing. Preflight, start and take-off had all been normal. At 0116½ LTJG BACHMEIER called the initial point to 32 Left (the primary night mirror landing practice runway.) He was told that runway lights were off and "deck lights" were on. LTJG BACHMEIER's first pass was improper, angling in and he took a technique wave-off. This can be partially attributed to runway lights being off causing difficulty with runway line-up. The LSO states that LTJG BACHMEIER looked a little "shaky" on this pass. The pattern was a "mixed" pattern at this time containing an A-3, 2 A-7's and expecting the arrival of more A-7's to fill the pattern.

At 0124 LTJG BACHMEIER called the ball on his second pass and completed a "touch-and-go." Again, he looked unsure. The pattern was becoming hectic at this time.

At 0127½ LTJG BACHMEIER called the ball on his third pass. He was noted to touch down, add full power and climb. He was given his interval, by the tower, as "flight of 2 A-7's breaking upwind" as he lifted off. These aircraft were at 1700 feet. LTJG BACHMEIER climbed, reduced power to 89% and transitioned into a nose down attitude, instead of level flight, at 265 feet AGL. Pattern altitude is 450 feet AGL. He was noted to fly nearly wings level, into the ground impacting at 0128. No ejection attempt was observed. The plane exploded and burned violently on impact. The pilot was thrown from the aircraft and came to rest just short of the cockpit in the fireball. No power loss, explosions, fires or violent maneuvers of the aircraft were noted prior to impact.

Enclosure (15)

MEDICAL OFFICER'S REPORT OF A/C INCIDENT, INCIDENT OR GROUND ACCIDENT

MEDICAL INFORMATION

OPNAV FORM 3750/88 (REV. 4-68) 5/N-0107-731-8201

REPORT SYMBOL 3750.7

See Section II of OPNAVINST 3750.6

1. DEGREE OF INJURY <input type="checkbox"/> 1 - NONE <input checked="" type="checkbox"/> 4 - FATAL <input type="checkbox"/> 7 - MISSING, UNKNOWN <input type="checkbox"/> 2 - MINOR <input type="checkbox"/> 5 - MISSING, LAND <input type="checkbox"/> 3 - MAJOR <input type="checkbox"/> 6 - MISSING, WATER		2. DAYS HOSPITALIZED <u>Dead on arrival</u> 3. DAYS IN QUARTERS <u>N/A</u> 4. DAYS GROUNDED <u>N/A</u> 5. UNCONSCIOUS <u>on ground</u> HOURS <u>impact</u> MIN.	
--	--	--	--

8a. DISPOSITION <u>P</u>	8b. EXPOSURE <input type="checkbox"/> 1 - MILD <input type="checkbox"/> 2 - MODERATE <input checked="" type="checkbox"/> 3 - SEVERE	8c. SHOCK <u>Death</u> <input type="checkbox"/> 1 - MILD <input type="checkbox"/> 2 - MODERATE <input type="checkbox"/> 3 - SEVERE
------------------------------------	---	---

9. INJURIES INCURRED DURING MISHAP
 (Use Standard DOD Terminology for Body Part, Diagnosis and Cause of Injury.) (See DDDHC, NAVMED P5082.)

INJURIES INCURRED DURING MISHAP		LEAVE THESE COLUMNS BLANK	
A. BODY PART	DIAGNOSIS	P	
B. BODY PART	DIAGNOSIS	D	
C. BODY PART	DIAGNOSIS	C	
D. BODY PART	DIAGNOSIS	P	
E. BODY PART	DIAGNOSIS	D	
F. BODY PART	DIAGNOSIS	C	
G. BODY PART	DIAGNOSIS	P	
H. BODY PART	DIAGNOSIS	D	
I. BODY PART	DIAGNOSIS	C	
J. BODY PART	DIAGNOSIS	P	
K. BODY PART	DIAGNOSIS	D	
L. BODY PART	DIAGNOSIS	C	

7. LABORATORY TESTS	A. TISSUE TESTED	B. METHOD USED	C. LABORATORY REPORT TEST	D. RESULT
CARBON MONOXIDE	All body fluids and tissues sent to AFIP for analysis.			
ALCOHOL				
LACTIC ACID				
OTHER (SPECIFY)				

8. X-RAY RESULTS ☒ CHECK IF PERFORMED. SUBMIT RESULTS ON SEPARATE SHEET. See Enclosure (9)

DISEASES/DEFECTS PRESENT AT TIME OF MISHAP	METHOD OF DISCOVERY				WITNESS (AS APPLICABLE)	
	ANNUAL PHYSICAL	SICK CALL	AUTOPSY	OTHER	AUTHORITY	DATE
None						

10. AUTOPSY CONDUCTED BY: <input checked="" type="checkbox"/> M - MILITARY PATHOLOGIST <input checked="" type="checkbox"/> F - FLIGHT SURGEON <input type="checkbox"/> C - CIVILIAN PATHOLOGIST <input type="checkbox"/> Y - OTHER <input type="checkbox"/> PROTOCOL ATTACHED <input type="checkbox"/> WILL BE FORWARDED	11. MATERIAL SUBMITTED TO AFIP: <input checked="" type="checkbox"/> 1 - AUTOPSY REPORT <input checked="" type="checkbox"/> 3 - PICTURES <input checked="" type="checkbox"/> 2 - FROZEN TISSUE <input checked="" type="checkbox"/> 4 - FIXED TISSUE
--	---

12. LIST ADDITIONAL INJURIES RECEIVED AS A RESULT OF THE MISHAP, AND ADD ANY PERTINENT REMARKS.

See Autopsy report (enclosure 8) and x-ray reports (enclosure 9) for complete listings of injuries.

NAME <u>BACHMEIER, James P. Jr.</u>	SERIAL NO. <u>(b) (6)</u>	A/C <u>A-7A</u>	BRNO <u>152664</u>
--	------------------------------	--------------------	-----------------------

**MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT OR GROUND ACCIDENT
PSYCHOPHYSIOLOGICAL AND ENVIRONMENTAL FACTORS
OPNAV FORM 3750/3C (REV. 4-68) 5/14-8187-721-4301**

REPORT SYMBOL 3750-7
See Section II of OPNAVINST 3750.6
PAGE 1 OF 2

INSTRUCTIONS: Complete on all occupants of aircraft, all injured persons, and all persons possibly contributing to the cause of the mishap. Supervisory factors attributed to persons not in the aircraft and such factors as design or weather should be reported only for the person in primary control of the aircraft. Factors contributing to injury during mid-air collisions, crash landings, ditchings, etc., are to be considered part of survival phase. Use codes as right to show only those factors present or contributing in each phase.

PHASES OF MISHAP
A - Accident
E - Escape
S - Survival (includes parachute landings)
R - Rescue

FACTOR IMPORTANCE
D - Definitely contributed
S - Suspected factor
P - Condition present but did not contribute to accident or injury

FACTORS		A E S R				FACTORS		A E S R			
1. SUPERVISORY FACTORS						D. SLEEP DEPRIVATION 607					
A. INADEQUATE BRIEFING	101					H. FATIGUE, OTHER	608	S			
B. ORDERED/LED ON FLIGHT BEYOND CAPABILITY	102					I. MISSED MEALS	609				
C. POOR CREW COORDINATION	103					J. DRUGS PRESCRIBED BY MEDICAL OFFICER	610				
D. OTHER (SPECIFY)	199					K. DRUGS, OTHER	611				
						L. ALCOHOL	612				
2. PRE-FLIGHT FACTORS						M. VISUAL ILLUSIONS	613	S			
A. FAULTY FLIGHT PLAN	201					N. UNCONSCIOUSNESS	614				
B. FAULTY PRE-FLIGHT OF AIRCRAFT	202					O. DISORIENTATION/VERTIGO	615				
C. FAULTY PREPARATION OF PERSONAL EQUIPMENT	203					P. HYPOXIA	616				
D. HURRIED DEPARTURE	204					Q. HYPERVENTILATION	617				
E. DELAYED DEPARTURE	205					R. DYSBARISM	618				
F. INADEQUATE WEATHER ANALYSIS	206					S. CARBON MONOXIDE POISONING	619				
G. OTHER (SPECIFY)	299					T. BOREDOM	620				
						U. INATTENTION	621	S			
3. EXPERIENCE/TRAINING FACTORS						V. CHANNELIZED ATTENTION	622				
A. INADEQUATE TRANSITION	301					W. DISTRACTION	623	S			
B. LIMITED TOTAL EXPERIENCE	302	S				X. PREOCCUPATION WITH PERSONAL PROBLEMS	624				
C. LIMITED RECENT EXPERIENCE	303					Y. EXCESSIVE MOTIVATION TO SUCCEED	625				
D. FAILURE TO USE ACCEPTED PROCEDURES	304					Z - OVERCONFIDENCE	626				
E. OTHER (SPECIFY)	399					AA. LACK OF SELF-CONFIDENCE	627				
						BB. LACK OF CONFIDENCE IN EQUIPMENT	628				
4. DESIGN FACTORS						CC. APPREHENSION	629	S			
A. DESIGN OF INSTRUMENTS, CONTROLS	401					DD. PANIC	630				
B. LOCATION OF INSTRUMENTS, CONTROLS	402					EE. OTHER (SPECIFY)	699				
C. FAILURE OF INSTRUMENTS, CONTROLS	403					7. ENVIRONMENTAL FACTORS					
D. COCKPIT LIGHTING	404					A. ACCELERATION FORCES, IN-FLIGHT	701				
E. RUNWAY LIGHTING	405					B. ACCELERATION FORCES, IMPACT	702		D	D	
F. LIGHTING OF OTHER AIRCRAFT	406					C. DECOMPRESSION	703				
G. PERSONAL EQUIPMENT INTERFERENCE	407					D. VIBRATION	704				
H. WORKSPACE INCOMPATIBLE WITH MAN	408					E. GLARE	705				
I. OTHER (SPECIFY)	499					F. SMOKE, FUMES, ETC.	706				
						G. HEAT	707				
5. COMMUNICATION PROBLEMS						H. COLD	708				
A. MISINTERPRETED COMMUNICATIONS	501					I. WINDBLAST	709				
B. DISRUPTED COMMUNICATIONS	502					J. VISIBILITY RESTRICTION-WEATHER, HAZE, DARKNESS	710	S			
C. LANGUAGE BARRIER	503					K. VISIBILITY RESTRICTION-GLASS, WINDOWS FOGGED, ETC.	711				
D. NOISE INTERFERENCE	504					L. VISIBILITY RESTRICTION-DUST, SMOKE, ETC. IN ACFT	712				
E. OTHER (SPECIFY)	599					M. WEATHER, OTHER THAN VISIBILITY RESTRICTION	713				
						N. OTHER (SPECIFY)	799				
6. PSYCHOPHYSIOLOGICAL FACTORS						8. OTHER FACTORS TO BE CONSIDERED					
A. FOOD POISONING	601					A. HABIT INTERFERENCE; USED WRONG CONTROL	801				
B. MOTION SICKNESS	602					B. CONFUSION OF CONTROLS, OTHER	802				
C. OTHER ACUTE ILLNESS	603					C. MISREAD INSTRUMENT(S)	803				
D. OTHER PRE-EXISTING DISEASE/DEFECT	604					D. MISINTERPRETED INSTRUMENT READING	804				
E. GET-HOME-ITIS	605										
F. HANGOVER	606										

CONTINUED ON REVERSE SIDE

NAME **BACHMEIER, James P. Jr.**

SERIAL NO.

(b) (6)

A/C

A-7A

SUNG

152664

FACTORS		A	E	S	R	FACTORS		A	E	S	R
B. OTHER FACTORS TO BE CONSIDERED (Cont.)											
E. MISLEAD BY FAULTY INSTRUMENTS	805					K. DELAY IN TAKING NECESSARY ACTION	811	D			
F. VISUAL RESTRICTION BY EQUIPMENT STRUCTURES	806					L. VIOLATION OF FLIGHT DISCIPLINE	812				
G. TASK OVERSATURATION	807					M. NAVIGATIONAL ERROR	813				
H. INADEQUATE COORDINATION OR TIMING	808					N. INADVERTENT OPERATION, SELF-INDUCED	814				
I. MISJUDGED SPEED OR DISTANCE	809					O. INADVERTENT OPERATION, MECHANICALLY INDUCED	815				
J. SELECTED WRONG COURSE OF ACTION	810					P. OTHER (SPECIFY)	819				

REMARKS: (Indicate item and describe circumstances in detail as necessary.)

- 3B: 400 total flight hours, 82 A-7 hours, 16.1 night hours previous 3 months; first night mirror landing carrier practice.
- 6H: Very demanding afternoon flight. Continuously awake 15½ hours without real rest.
- 6M: Dark night, runway not lighted (deck lighting only for night mirror landing practice - therefore no ready ground reference). Doing night VFR/IFR flight. A/C at 265 feet (BACHMEIER) taking interval on flight. Two A-7's breaking overhead at 1700 feet - visual illusion of climbing causing pilot to transition to descending attitude.
- 6U: Night IFR/VFR flight. Scan probably broke down and pilot did not read altimeter.
- 6W: Taking interval on 2 A/C breaking overhead - possibly gazed at them too long causing instrument scan to break down.
- 6CC: First night mirror landing practice - would be apprehensive.
- 7B: Violent ground impact and A/C explosion precluded escape attempt or survival.
- 7J: Dark night - no ground reference - no horizon.
- 8K: Delay in taking attention off A/C breaking overhead and resuming instrument scan. Did not transition to nose up attitude in time to avoid ground impact (if at all).

I. ROLE OF THIS INDIVIDUAL IN THE CAUSE OF THE MISHAP:

A. PRIMARY			B. CONTRIBUTING			C. NONE			D. UNKNOWN		
<input checked="" type="checkbox"/> 1. DEFINITE	<input type="checkbox"/> 2. PROBABLE	<input type="checkbox"/> 3. POSSIBLE	<input type="checkbox"/> 4. DEFINITE	<input type="checkbox"/> 5. PROBABLE	<input type="checkbox"/> 6. POSSIBLE	<input type="checkbox"/> 7. NONE	<input type="checkbox"/> 8. UNKNOWN	<input type="checkbox"/> 9. UNKNOWN	<input type="checkbox"/> 10. UNKNOWN	<input type="checkbox"/> 11. UNKNOWN	<input type="checkbox"/> 12. UNKNOWN

II. BACKGROUND (Complete for all pilots and others who possibly contributed to mishap)

A. DATE LAST LEAVE ENDED <u>4 Jan 1969</u>		B. DAYS DURATION LAST LEAVE <u>13 days</u>	
C. TYPE OF LEAVE LAST TAKEN			
<input checked="" type="checkbox"/> 1. ORDINARY	<input type="checkbox"/> 2. EMERGENCY	<input type="checkbox"/> 3. REENLISTMENT	<input type="checkbox"/> 4. GRADUATION
<input type="checkbox"/> 5. SICK OR CONVALESCENT	<input type="checkbox"/> 6. DELAY ENROUTE	<input type="checkbox"/> 7. UNKNOWN	
D. DATE OF LAST PREVIOUS FLIGHT <u>7 May 1969</u>			
E. IN LAST 24 HOURS <u>2</u> MIN <u>29</u>		F. IN LAST 48 HOURS <u>2</u> MIN <u>29</u>	
G. IN LAST 24 HOURS <u>2</u>		H. IN LAST 48 HOURS <u>2</u>	
I. IN LAST 24 HOURS <u>5</u> MIN <u>28</u>		J. IN LAST 48 HOURS <u>5</u> MIN <u>28</u>	
K. IN LAST 24 HOURS <u>7</u>		L. IN LAST 48 HOURS <u>18 1/2</u>	
M. CONTINUOUS DUTY PRIOR TO MISHAP <u>1</u> HOURS <u>28</u> MIN		N. HOURS CONTINUOUSLY AWAKE PRIOR TO MISHAP <u>15</u>	
O. DURATION OF LAST SLEEP PERIOD <u>7</u> HOURS <u>0</u> MIN		P. TIME IN COCKPIT PRIOR TO FLIGHT <u>0</u> HOURS <u>10</u> MIN	

III. PHYSIOLOGICAL, LOW PRESSURE CHAMBER AND VERTIGO TRAINING (For all personnel)

TYPE TRAINING ACCOMPLISHED	PLACE TRAINING ACCOMPLISHED	COMPLETED		ROLE* IN MISHAP	*For role in mishap, use following code: 0 - NO IMPORTANCE 1 - TRAINING DEFINITELY HELPED 2 - TRAINING POSSIBLY HELPED 3 - LACK OF TRAINING DEFINITELY A FACTOR 4 - LACK OF TRAINING POSSIBLY A FACTOR 9 - UNKNOWN
		Month	Year		
PHYSIOLOGICAL	NAS Lemoore	Sept	68	0	
Low Pressure Chamber	NAS Lemoore	Sept	68	0	
Vertigo	NAS Lemoore	Sept	68	4	

IV. ANTHROPOMETRIC DATA

a. DATE OF BIRTH: (b) (6)	b. HEIGHT: (b) (6)	c. WEIGHT: (b) (6)
d. SITTING HEIGHT: (b) (6)	e. TRUNK HEIGHT: (b) (6)	f. FUNCTIONAL REACH: (b) (6)
g. BUTTOCK-KNEE LENGTH: (b) (6)	h. LEG LENGTH: (b) (6)	i. SHOULDER WIDTH (BIDELTOID): (b) (6)

V. GENERAL

1. NUMBER AND TYPE OF PRIOR MISHAPS (Complete for all pilots, copilots, and/or other persons in control of aircraft)

a. No. None b. DESCRIBE TYPE(S):

2. TOTAL YEARS OF FORMAL EDUCATION: 16

3. CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PREVIOUS 72 HOURS (For all pilots, copilots, and/or persons possibly contributing to mishap)

See Following Attached Sheets.

NAME <u>BACHMEIER, James F. Jr.</u>	SERIAL NO. <u>(b) (6)</u>	A/C <u>A-7A</u>	BUONO <u>152664</u>
--	------------------------------	--------------------	------------------------

CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PILOT JAMES FLORIAN BACHMEIER, III
FOR 72 HOURS PRECEDING THE ACCIDENT.

SUNDAY, 4 MAY, 1969

- 0130 - 0830 Sleeping soundly. Had out-of-town house guests for the weekend, relaxed but probably some added burden.
- 0830 - 0930 Arose, showered, dressed etc.; noted to really "take his time" and be happy and relaxed.
- 0930 - 0945 Relaxing with house guests.
- 0945 - 1020 Breakfast of fried bacon, fried potatoes, scrambled eggs, English muffins, orange juice and milk.
- 1020 - 1100 Going to Catholic Mass.
- 1100 - 1200 Attended Mass and received communion.
- 1200 - 1315 Trying to help wife calm down fussy baby. Anxious due to possibly missing the Air Show at NAS Lemoore that day. (Quite a tense situation.)
- 1315 - 1330 Taking baby (they have one 6-week-old child) to the babysitter.
- 1330 - 1345 Driving to NAS for Air Show.
- 1345 - 1400 Back gate to NAS Lemoore closed. LTJG BACHMEIER very angry about delay, the wife was angry that Jim was angry and a heated argument ensued.
- 1400 - 1500 Driving all the way around to the front gate (21 miles) angry and arguing. Argument settled.
- 1500 - 1800 At Lemoore NAS Air Show, now relatively relaxed and enjoying the show.
- 1800 - 2100 Drove home, retrieved child from babysitter, invited friends over and had social get-together. Ate portion of pizza and had one or two beers.
- 2100 - 2300 Wife sleeping on couch, Jim reading and watching T.V. (All harmonious by this time -- family situation.)
- 2300 - 1300 Sound, relatively uninterrupted sleep. (Yes, he slept until 1 PM.)

MONDAY, 5 MAY, 1969

- 1300 - 1400 Arose, showered, shaved and dressed in a leisurely fashion.
- 1400 - 1415 Consumed several hot dogs and buns; beans, potato chips and milk.

CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PILOT JAMES FLORIAN BACHMEIER, III
FOR 72 HOURS PRECEDING THE ACCIDENT. (Continued:)

MONDAY, 5 MAY, 1969 (Continued:)

- 1415 - 1600 Working around the house, drove to Post Office and visited with LCDR (b) (6) for awhile.
- 1600 - 1630 Driving to Hanford with friends to have dinner.
- 1630 - 1800 Had 2-3 beers before dinner, relaxing and visiting.
- 1800 - 1930 Large dinner of ice tea, BBQ steak, potato salad and tossed salad. Jim was noted to be in excellent spirits and to eat heartily.
- 1930 - 2130 Played two hands of bridge; then watched L.A.-BOSTON basketball game on T.V. while eating cheese cake.
- 2130 - 2200 Driving home with wife. Noted to feel great, excellent spirits, no ill or problems apparent.
- 2200 - 2300 Relaxing at home and talking to wife.
- 2300 - 2400 Went to bed with wife, couldn't sleep so arose again when wife fell asleep.

TUESDAY, 6 MAY, 1969

- 2400 - 0130 Reading and relaxing and trying to become tired enough to go to bed and sleep. (All the reading in this 72 hour statement is apparently flight preparations.)
- 0130 - 0830 Sleep, interrupted briefly at 0330-0400 by crying child.
- 0830 - 0900 Awake -- in bed with wife (b) (6)
(b) (6)
- 0900 - 1000 Arose with wife, shaved, showered, dressed in leisurely fashion.
- 1000 - 1030 Hearty breakfast of orange juice, milk, French toast and bacon.
- 1030 - 1300 Working around house and washing the car and watching the baby outside while washing the car, etc.
- 1300 - 1330 Dressed and got ready for work. No dinner that day due to large, late breakfast.
- 1330 - 1500 Left for work, stopped to see LCDR (b) (6) for awhile.

CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PILOT JAMES FLORIAN BACHMEIER, III
FOR 72 HOURS PRECEEDING THE ACCIDENT. (Continued)

TUESDAY, 6 MAY 1969 (Continued)

- 1500-1545 Noted to be in ready room in full flight gear at 1500. Brief lasted 1500-1545 for PNR-3 flight with IP chase LCDR (b)(6).
(b)(6) This is a low level, hooded, full systems navigation flight at 1,000 feet AGL going in valley and near ridges. It is the most difficult flight in the syllabus. It is noted to be very anxiety provoking for all. Requires much preparation and study. The brief was thorough and complete. LTJG BACHMEIER was "ready and up" for the flight.
- 1545-1610 Checking out aircraft, preflight, etc.
- 1610-1618 Manned aircraft and prepared for take-off.
- 1618-1830 Flew the above mentioned very difficult PNR-3 flight (2.2 flight hours.) Flew with the added burden of an improper ASN-50 gyro (the ADI) which malfunctioned. Completed the hop, doing well, despite this malfunction. Please note this gyro failure. (Afternoon before accident.)
- 1830-1900 De-briefed the hop. Noted to be exhuberant, happy and in apparent excellent health. Very proud to have completed the "graduation hop" of the syllabus under very adverse (but safe) conditions.
- 1900-1930 Getting out of flight gear and driving home.
- 1930-2000 Told wife he was pleased, happy and proud of the afternoon flight. He and his wife played with the 6-week-old baby.
- 2000-2030 Had dinner of spaghetti, stew, tossed salad and baking powder biscuits. Ate very well - was exhuberant.
- 2030- Trying to relax and read in the living room while wife cleaned kitchen and called LCDR (b)(6) for ride to squadron.
- 2030-2330 Trying to relax - trying to sleep in preparation for night flight. In the words of his wife, "Oh hell, he couldn't sleep knowing he was going to have to get up again to fly."
- 2330-2350 Riding to squadron with LCDR (b)(6). Spoke only of the difficult afternoon hop. Noted to be very proud of it and very "pumped up" (words of LCDR (b)(6)) about afternoon hop and flying in general - did not even mention the upcoming night flying (his first night mirror landing carrier practice.)
- 2350-2400 Getting into flight gear.

CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PILOT JAMES FLORIAN BACHMEIER, III
FOR 72 HOURS PRECEDING THE ACCIDENT. (Continued)

WEDNESDAY, 7 MAY 1969

- 2400-0025 Relaxing in ready room and "shooting the breeze."
- 0025-0040 Refresher brief on night mirror landing practice. The extensive (greater than two hours and thorough) brief had been held several days prior to this and was thought to be very adequate by all pilots briefed.
- 0040-0100 Checking out aircraft, preflight, etc., manning aircraft and taxi - all normal according to plane captain questioned.
- 0111 Take-off.
- 0116½ BACHMEIER reaches the initial to 32 Left, the primary mirror landing runway.
- 0119 BACHMEIER calls the break.
- 0120¼ Pilot, BACHMEIER, at the 180 - three other aircraft in the pattern at this time.
- 0120-3/4 LSO tells pilot, BACHMEIER, to illuminate his aircraft properly and that he is wide abeam.
- 0121½ Pilot, BACHMEIER, calls the ball "Clara" told by LSO he is angling in.
- 0121-3/4 Pilot, BACHMEIER, waves off (technique) noted to be "shaky" on this pass.
- 0124 Pilot, BACHMEIER, calls ball on second pass.
- 0124½ Called by LSO for being low. Two more aircraft call at the initial point at this time. During all this BACHMEIER flight time, the two LSO's are talking to an A-3 in the pattern who is having near extreme difficulty; they are trying to instruct him.
- 0126-0127½ LSO and A-3 engaged in verbal radio battle. (Nearly all A-3, little from LSO.)
- 0127½ Pilot, BACHMEIER, calls the ball on his third pass.
- 0127-3/4 Tower gives pilot BACHMEIER who has touched-down and climbed to 150-200 feet his interval as "flight of two breaking upwind A-7's." Tower operator notes pilot BACHMEIER climb to 265 feet, level off and gently arch down to ground impact - calling "Crash" just prior to the impact and again just after impact.

MOR 15-69A VA-122

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6F SERIES.

CHRONOLOGICAL ACCOUNT OF ACTIVITIES OF PILOT JAMES FLORIAN BACHMEIER, III
72 HOURS PRECEEDING THE ACCIDENT. (Continued)

WEDNESDAY, 7 MAY 1969 Continued:

- 0128½ Tower operator calls, "Crash, crash!" as both LSO's are watching and instructing aircraft who appears to be low (he was actually wide) at the 180.
- 0128½ Ground impact - no ejection attempt, no survival; plane explodes on impact. Pilot thrown from aircraft and burned severely where he impacted in intense fire near cockpit.

NOMENCLATURE AND MODEL DESIGNATION		REQUIRED	AVAILABLE	USED	NEEDED	PROBLEMS <i>Indicate by code from list on reverse side.</i>
1. CLOTHING (SUITS, HEADGEAR, SHOES, GLOVES, VISOR, UNDERWEAR, ETC.)						
Flight Suit (Nomex)		Y	AE	AE	AE	09
Helmet APH - 6		Y	A	A	AE	09
Flight Gloves (Nomex)		Y	N	N	Y	03 not worn; in-cockpit
Helmet Face Visor (tinted/clear)		Y	A	A	AE	09
Flight Boots (steel toe)		Y	AE	AE	AE	09
Anti G Suit (MK-2A)		Y	AE	A	AE	09
2. OXYGEN MASK A-13 A		Y	A	A	AE	04, 07
3. OXYGEN REGULATOR Robert-Shaw-Fulton		Y	A	A	A	09
4. LIFE VEST None		N	N	N	N	not required this flight
5. LIFE RAFT PK-2		Y	A	N	N	09
6. SURVIVAL RADIO None		Y	N	N	N	01 none in squadron
7. SIGNALLING DEVICES						
SEEK-2 Kit		Y	A	N	N	09
Strobe Light		N	A	N	N	09
Pencil Flares		N	A	N	N	09
8. SURVIVAL KIT (CONTAINER) RSSK-8A		Y	A	N	N	09
9. OTHER SURVIVAL GEAR						
Survival Knife		Y	A	N	N	08
SV-2 Survival Vest (complete)		N	AE	N	N	09
10. RESTRAINTS (LAP BELTS, SHOULDER HARNESS, LEG RESTRAINTS)						
Torso Harness MA-2 Cutaway		Y	AE	A	AE	09
11. PARACHUTE-TYPE NB-10		Y	AE	A	AE	09
12. PARACHUTE CANOPY RELEASE Konh Pittings		Y	AE	N	AE	09
13. PARACHUTE OPENING/DEPLOYMENT DEVICES 1000-D		Y	AE	N	AE	09
14. SEAT TYPE ESCAPAK 1-C2		Y	A	N	AE	09
15. OTHER (SPECIFY)						

16. EXPLAIN PROBLEMS (USE REVERSE SIDE IF NECESSARY)

All evidence points to the pilot not recognizing his danger and flying into the ground unaware of his difficulties. Egress consisted of being thrown from wreckage. Killed instantly on ground impact - essentially no survival or rescue phase.

CONTINUED ON REVERSE SIDE

NAME	SERIAL NO.	A/C	GRID
BACHMEIER, James F. Jr.	(b) (6)	A-7A	152664

- | | |
|--|--|
| <ul style="list-style-type: none">81 - NOT AVAILABLE-SUPPLY PROBLEM82 - NOT AVAILABLE-LEFT BEHIND83 - DISCARDED84 - LOST85 - DAMAGED-MINOR86 - DAMAGED-MAJOR87 - BURNED-MINOR88 - BURNED-MAJOR89 - DESTROYED BY EXTREME FORCE/FIRE90 - FAILED TO OPERATE (RADIO, ACTUATOR, ETC.)91 - OPERATED PARTIALLY92 - DIFFICULTY LOCATING93 - BEYOND REACH94 - CONNECTION/CLOSURE DIFFICULTY95 - CONNECTION/CLOSURE FAILURE96 - RELEASE/DISCONNECT DIFFICULTY97 - RELEASE/DISCONNECT FAILURE98 - INADVERTENT RELEASE/DISCONNECT99 - INADVERTENT ACTUATION100 - ACTUATION DIFFICULTY101 - ACTUATION FAILURE102 - ACTUATED BY OTHER PERSON103 - RESTRAINT/ATTACHMENT INADEQUACY104 - RESTRAINTS/ATTACHMENTS NOT USED PROPERLY FOR MAXIMUM PROTECTION105 - IMPROPER USE (OTHER)106 - UNFAMILIAR WITH USE107 - COLD HAMPERED USE | <ul style="list-style-type: none">108 - INJURY HAMPERED USE109 - WATER HAMPERED USE110 - OTHER EQUIPMENT INTERFERED111 - DOING/REMOVAL PROBLEM112 - DISCOMFORT/BULKINESS113 - POOR FIT114 - LEAKED115 - MATERIEL DEFICIENCY116 - DESIGN DEFICIENCY117 - HANGUP/ENTANGLEMENT (WITH A/C OR OTHER EQUIPMENT)118 - ENTANGLEMENT (PARACHUTE SUSPENSION LINES ONLY)-MAJOR119 - ENTANGLEMENT (PARACHUTE SUSPENSION LINES ONLY)-MINOR120 - DRAGGING (PARACHUTE ONLY)121 - NON-STANDARD CONFIGURATION122 - AIDED IN LOCATION/RESCUE123 - NOT EFFECTIVE IN LOCATION/RESCUE (USED IN AREA OF SAR VEHICLES)124 - PREVENTED/MINIMIZED INJURY125 - EQUIPMENT PROBLEM (LOSS, FAILURE, ETC.) A FACTOR IN PRODUCING INJURY126 - EQUIPMENT PRODUCED INJURY (HIT BY EJECTION SEAT, ETC.)127 - FAILURE/DELAY IN USING COMPROMISED SURVIVAL/RESCUE128 - ALL CREW EQUIPMENT (CODE ONLY ONCE)129 - MAINTENANCE/INSTALLATION ERROR130 - PROBLEM EXPERIENCED BY OTHERS IN ACTUATION/RELEASE OF EQUIPMENT131 - EQUIPMENT DAMAGE-SELF INDUCED132 - EQUIPMENT FAILURE-SELF INDUCED133 - OTHER (SPECIFY) |
|--|--|

<p>8. COMMUNICATIONS PRIOR TO ESCAPE</p> <p><input type="checkbox"/> 1. DISTRESS SIGNAL TRANSMITTED</p> <p><input type="checkbox"/> 2. POSITION FIX TRANSMITTED</p> <p><input type="checkbox"/> 3. EMERGENCY IFF (MANUAL)</p> <p><input type="checkbox"/> 4. EMERGENCY IFF (AUTOMATIC)</p> <p><input type="checkbox"/> 5. UNKNOWN</p> <p><input checked="" type="checkbox"/> 6. NONE</p> <hr/> <p>9. NUMBER OF PREVIOUS:</p> <p>EJECTIONS <u>0</u> EMERGENCY BAILOUTS <u>0</u></p> <p>OTHER PARACHUTE JUMPS (TRAINING, SKYDIVING, ETC.) <u>0</u></p> <hr/> <p>10. TERRAIN OF PARACHUTE LANDING OR CRASH SITE</p> <p>(More than one may be applicable) Thrown out of aircraft.</p> <table style="width: 100%;"> <tr> <td><input type="checkbox"/> A - OPEN SEA</td> <td><input type="checkbox"/> K - BUILDING</td> </tr> <tr> <td><input type="checkbox"/> B - LARGE LAKE</td> <td><input type="checkbox"/> L - FLIGHT DECK</td> </tr> <tr> <td><input type="checkbox"/> C - RIVER</td> <td><input type="checkbox"/> M - DENSE WOODS</td> </tr> <tr> <td><input type="checkbox"/> D - DEEP WATER, OTHER</td> <td><input type="checkbox"/> N - IN TREES</td> </tr> <tr> <td><input type="checkbox"/> E - SHALLOW WATER</td> <td><input type="checkbox"/> T - THROUGH TREES</td> </tr> <tr> <td><input type="checkbox"/> F - DEEP SNOW</td> <td><input type="checkbox"/> P - RAVINE/STEEP SLOPE</td> </tr> <tr> <td><input type="checkbox"/> G - THICK ICE</td> <td><input type="checkbox"/> Q - ROCKS</td> </tr> <tr> <td><input type="checkbox"/> H - MARSH/SWAMP/MUD</td> <td><input type="checkbox"/> R - IN/NEAR FIREFALL</td> </tr> <tr> <td><input type="checkbox"/> U - HARD GROUND</td> <td><input type="checkbox"/> S - DESERT</td> </tr> <tr> <td><input type="checkbox"/> J - SOFT GROUND</td> <td><input type="checkbox"/> Y - UNKNOWN</td> </tr> <tr> <td></td> <td><input type="checkbox"/> Z - OTHER _____</td> </tr> </table>	<input type="checkbox"/> A - OPEN SEA	<input type="checkbox"/> K - BUILDING	<input type="checkbox"/> B - LARGE LAKE	<input type="checkbox"/> L - FLIGHT DECK	<input type="checkbox"/> C - RIVER	<input type="checkbox"/> M - DENSE WOODS	<input type="checkbox"/> D - DEEP WATER, OTHER	<input type="checkbox"/> N - IN TREES	<input type="checkbox"/> E - SHALLOW WATER	<input type="checkbox"/> T - THROUGH TREES	<input type="checkbox"/> F - DEEP SNOW	<input type="checkbox"/> P - RAVINE/STEEP SLOPE	<input type="checkbox"/> G - THICK ICE	<input type="checkbox"/> Q - ROCKS	<input type="checkbox"/> H - MARSH/SWAMP/MUD	<input type="checkbox"/> R - IN/NEAR FIREFALL	<input type="checkbox"/> U - HARD GROUND	<input type="checkbox"/> S - DESERT	<input type="checkbox"/> J - SOFT GROUND	<input type="checkbox"/> Y - UNKNOWN		<input type="checkbox"/> Z - OTHER _____	<p>11. AIRCRAFT ATTITUDE AT TIME OF ESCAPE</p> <p>(Either in flight or after crash, ditching, etc.)</p> <table style="width: 100%;"> <tr> <td><input type="checkbox"/> NOSE UP</td> <td><input type="checkbox"/> NOSE DOWN <u>5</u> DEGREES</td> </tr> <tr> <td><input checked="" type="checkbox"/> RIGHT BANK <u>10°</u></td> <td><input type="checkbox"/> LEFT BANK _____ DEGREES</td> </tr> <tr> <td><input type="checkbox"/> A. NOSE DOWN SPIN</td> <td><input checked="" type="checkbox"/> F. DISINTEGRATION</td> </tr> <tr> <td><input type="checkbox"/> B. FLAT SPIN</td> <td><input type="checkbox"/> G. INVERTED</td> </tr> <tr> <td><input type="checkbox"/> C. OSCILLATING SPIN</td> <td><input type="checkbox"/> H. MUSHING</td> </tr> <tr> <td><input type="checkbox"/> D. ROLLING</td> <td><input type="checkbox"/> Z. UNKNOWN</td> </tr> <tr> <td><input type="checkbox"/> E. TUMBLING</td> <td><input type="checkbox"/> Y. OTHER (DESCRIBE) _____</td> </tr> </table> <hr/> <p>12. EJECTION SEAT/PARACHUTE TRAINING</p> <p>(Not required for passengers who had an opportunity to escape)</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>TYPE OF TRAINING</th> <th>TOTAL HOURS IN TRAINING</th> <th>DATE OF LAST TRAINING</th> <th>ROLE*</th> </tr> </thead> <tbody> <tr> <td>LECTURES/DEMONSTRATIONS</td> <td>10</td> <td>SEP 68</td> <td>0</td> </tr> <tr> <td>TRAINING FILMS</td> <td>6</td> <td>SEP 68</td> <td>0</td> </tr> <tr> <td>UNARMED EJECTION SEAT</td> <td>2</td> <td>SEP 68</td> <td>0</td> </tr> <tr> <td>ARMED SEAT ON TOWER</td> <td>30 min.</td> <td>SEP 68</td> <td>0</td> </tr> <tr> <td>JUMP SCHOOL</td> <td>None</td> <td></td> <td></td> </tr> <tr> <td>PARASAIL TRAINING</td> <td>None</td> <td></td> <td></td> </tr> <tr> <td>OTHER (SPECIFY)</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>*Use codes below to indicate role training played in this mishap.</p> <table style="width: 100%;"> <tr> <td>0 - NO IMPORTANCE</td> <td>3 - LACK OF TRAINING FACTOR</td> </tr> <tr> <td>1 - TRAINING DEFINITE HELP</td> <td>4 - LACK OF TRAINING POSSIBLE FACTOR</td> </tr> <tr> <td>2 - TRAINING POSSIBLE HELP</td> <td>9 - TRAINING ROLE UNKNOWN</td> </tr> </table>	<input type="checkbox"/> NOSE UP	<input type="checkbox"/> NOSE DOWN <u>5</u> DEGREES	<input checked="" type="checkbox"/> RIGHT BANK <u>10°</u>	<input type="checkbox"/> LEFT BANK _____ DEGREES	<input type="checkbox"/> A. NOSE DOWN SPIN	<input checked="" type="checkbox"/> F. DISINTEGRATION	<input type="checkbox"/> B. FLAT SPIN	<input type="checkbox"/> G. INVERTED	<input type="checkbox"/> C. OSCILLATING SPIN	<input type="checkbox"/> H. MUSHING	<input type="checkbox"/> D. ROLLING	<input type="checkbox"/> Z. UNKNOWN	<input type="checkbox"/> E. TUMBLING	<input type="checkbox"/> Y. OTHER (DESCRIBE) _____	TYPE OF TRAINING	TOTAL HOURS IN TRAINING	DATE OF LAST TRAINING	ROLE*	LECTURES/DEMONSTRATIONS	10	SEP 68	0	TRAINING FILMS	6	SEP 68	0	UNARMED EJECTION SEAT	2	SEP 68	0	ARMED SEAT ON TOWER	30 min.	SEP 68	0	JUMP SCHOOL	None			PARASAIL TRAINING	None			OTHER (SPECIFY)				0 - NO IMPORTANCE	3 - LACK OF TRAINING FACTOR	1 - TRAINING DEFINITE HELP	4 - LACK OF TRAINING POSSIBLE FACTOR	2 - TRAINING POSSIBLE HELP	9 - TRAINING ROLE UNKNOWN
<input type="checkbox"/> A - OPEN SEA	<input type="checkbox"/> K - BUILDING																																																																										
<input type="checkbox"/> B - LARGE LAKE	<input type="checkbox"/> L - FLIGHT DECK																																																																										
<input type="checkbox"/> C - RIVER	<input type="checkbox"/> M - DENSE WOODS																																																																										
<input type="checkbox"/> D - DEEP WATER, OTHER	<input type="checkbox"/> N - IN TREES																																																																										
<input type="checkbox"/> E - SHALLOW WATER	<input type="checkbox"/> T - THROUGH TREES																																																																										
<input type="checkbox"/> F - DEEP SNOW	<input type="checkbox"/> P - RAVINE/STEEP SLOPE																																																																										
<input type="checkbox"/> G - THICK ICE	<input type="checkbox"/> Q - ROCKS																																																																										
<input type="checkbox"/> H - MARSH/SWAMP/MUD	<input type="checkbox"/> R - IN/NEAR FIREFALL																																																																										
<input type="checkbox"/> U - HARD GROUND	<input type="checkbox"/> S - DESERT																																																																										
<input type="checkbox"/> J - SOFT GROUND	<input type="checkbox"/> Y - UNKNOWN																																																																										
	<input type="checkbox"/> Z - OTHER _____																																																																										
<input type="checkbox"/> NOSE UP	<input type="checkbox"/> NOSE DOWN <u>5</u> DEGREES																																																																										
<input checked="" type="checkbox"/> RIGHT BANK <u>10°</u>	<input type="checkbox"/> LEFT BANK _____ DEGREES																																																																										
<input type="checkbox"/> A. NOSE DOWN SPIN	<input checked="" type="checkbox"/> F. DISINTEGRATION																																																																										
<input type="checkbox"/> B. FLAT SPIN	<input type="checkbox"/> G. INVERTED																																																																										
<input type="checkbox"/> C. OSCILLATING SPIN	<input type="checkbox"/> H. MUSHING																																																																										
<input type="checkbox"/> D. ROLLING	<input type="checkbox"/> Z. UNKNOWN																																																																										
<input type="checkbox"/> E. TUMBLING	<input type="checkbox"/> Y. OTHER (DESCRIBE) _____																																																																										
TYPE OF TRAINING	TOTAL HOURS IN TRAINING	DATE OF LAST TRAINING	ROLE*																																																																								
LECTURES/DEMONSTRATIONS	10	SEP 68	0																																																																								
TRAINING FILMS	6	SEP 68	0																																																																								
UNARMED EJECTION SEAT	2	SEP 68	0																																																																								
ARMED SEAT ON TOWER	30 min.	SEP 68	0																																																																								
JUMP SCHOOL	None																																																																										
PARASAIL TRAINING	None																																																																										
OTHER (SPECIFY)																																																																											
0 - NO IMPORTANCE	3 - LACK OF TRAINING FACTOR																																																																										
1 - TRAINING DEFINITE HELP	4 - LACK OF TRAINING POSSIBLE FACTOR																																																																										
2 - TRAINING POSSIBLE HELP	9 - TRAINING ROLE UNKNOWN																																																																										

13. EGRESS DIFFICULTIES (Place X in appropriate column)

B - Before; D - During; A - After

No attempt made. Thrown from aircraft by ground impact.

		GROUND			WATER			AIR			
		B	D	A	B	D	A	B	D	A	
1. SUFFETING	01										
2. G FORCES	02										
3. WINDBLAST	03										
4. SEAT PINS NOT REMOVED	04										
5. DIFFICULTY LOCATING CANOPY JETTISON MECHANISM	05										
6. HAMPERED BY CLOTHING	06										
7. HAMPERED BY EQUIPMENT (INCLUDE BODY ARMOR)	07										
8. HAMPERED BY INJURIES	08										
9. DIFFICULTY RELEASING CANOPY/HATCH	09										
10. FAILURE TO RELEASE CANOPY/HATCH	10										
11. DIFFICULTY LOCATING/REACHING NORMAL EJECTION MECHANISM	11										
12. DIFFICULTY LOCATING/REACHING ALTERNATE EJECTION MECHANISM	12										
13. FACE CURTAIN FAILED TO ACTIVATE SEAT	13										
14. FACE CURTAIN PROBLEM (LOCATING, REACHING, ETC.)	14										
15. SEAT PAN FIRING HANDLE FAILED TO ACTIVATE SEAT	15										
16. SEAT PAN FIRING HANDLE PROBLEM (LOCATING, ETC.)	16										
17. CANOPY JETTISON PROBLEM	17										
18. CANOPY JETTISON FAILURE (AUTOMATIC MEANS)	18										

CONTINUED ON NEXT PAGE

13. EGRESS DIFFICULTIES (Place X in appropriate column) (Continued)

B - Before; D - During; A - After

		GROUND			WATER			AIR		
		B	D	A	B	D	A	B	D	A
19. COULD NOT OPEN CANOPY/HATCH	19									
20. DIFFICULTY RELEASING RESTRAINTS	20									
21. DIFFICULTY REACHING HATCH/EXIT-OBSTRUCTIONS	21									
22. DIFFICULTY REACHING HATCH/EXIT-INJURIES	22									
23. DIFFICULTY REACHING HATCH/EXIT-A/C ATTITUDE	23									
24. DIFFICULTY REACHING HATCH/EXIT-EQUIPMENT HANDUP	24									
25. PINNED DOWN IN A/C (OTHER THAN EQUIPMENT HANDUP)	25									
26. CONFUSION/PANIC/DISORIENTATION	26									
27. DARKNESS-NO VISUAL REFERENCE	27	X								
28. FIRE/SMOKE/FUPL	28									
29. ANTHROPOMETRIC PROBLEM	29									
30. PERSONAL EQUIPMENT FACTOR (OTHER THAN HANDUP)	30									
31. UPPER EXTREMITIES HIT COCKPIT STRUCTURES	31									
32. LOWER EXTREMITIES HIT COCKPIT STRUCTURES	32									
33. MAN STRUCK CANOPY/CANOPY BOW	33									
34. STRUCK EXTERNAL SURFACE OF AIRCRAFT	34									
35. FLAILING - UPPER EXTREMITIES	35									
36. FLAILING - LOWER EXTREMITIES	36									
37. DROGUE SLUG SWINGING AT MAN	37									
38. DROGUE SLUG STRUCK MAN	38									
39. MAN STRUCK BY OTHER EQUIPMENT	39									
40. MAN STRUCK BY SEAT	40									
41. SEAT SEPARATION DIFFICULTY	41									
42. SEAT/PARACHUTE ENTANGLEMENT	42									
43. MAN TANGLED IN CHUTE RISERS-MAJOR	43									
44. MAN TANGLED IN CHUTE RISERS-MINOR	44									
45. PARACHUTE LINE ON 2R	45									
46. MAN HELD ON TO SEAT	46									
47. TUMBLING/SPINNING	47									
48. PARACHUTE DID NOT OPEN	48									
49. PARACHUTE STREAMED	49									
50. UNADVERTENT OPENING OF LAP BELT	50									
51. FAILURE OF LAP BELT TO OPEN	51									
52. INRUSHING WATER	52									
53. COLD	53									
54. UNCONSCIOUS/DIAZED	54									
55. OTHER	55									

REMARKS OR CONTINUATION: (Indicate each remark with code from above)

All evidence points to the pilot not recognizing his difficulty and making no attempt at ejection. He was thrown a short distance free of the aircraft by tremendous ground impact forces. The pilot, with all safety/survival gear, demolished and very severely burned, impacted just short of the cockpit area.

NAME BACHMEIER, James F. Jr.	SERIAL NO. (b) (6)	A/C A-7A	SUNG 152664
---------------------------------	-----------------------	-------------	----------------

(Complete for all in-flight escapes and ejections)

1. TIME FROM EMERGENCY UNTIL ESCAPE ATTEMPT WAS INITIATED
HOURS 0 MINUTES 0 SECONDS 0

2. DELAY IN INITIATING ESCAPE DUE TO: **No escape attempted**

- | | |
|--|--|
| <input type="checkbox"/> 1. ATTEMPTING TO OVERCOME PROBLEM | <input type="checkbox"/> 3. LOSING ALTITUDE |
| <input type="checkbox"/> 2. AVOIDING POPULATED AREA | <input type="checkbox"/> 6. LOSING AIRSPEED |
| <input type="checkbox"/> 3. AVOIDING UNSUITABLE TERRAIN | <input checked="" type="checkbox"/> 8. OTHER Didn't recognize problem |
| <input type="checkbox"/> 4. GAINING ALTITUDE | <input type="checkbox"/> 9. UNKNOWN |

3. TERRAIN CLEARANCE AT TIME OF: **No ejection**

- A. 1. ESCAPE (FEET) Zero 2. PARACHUTE OPENING (FEET) None
- B. 1. AIRSPEED AT TIME OF ESCAPE None KIAS
2. GROUND/FORWARD SPEED (IF NOT AIRBORNE) 145 K
- C. ☐ 1. PARACHUTE DID NOT OPEN ☐ 2. PARACHUTE STREAMED

4. PROTECTIVE HELMET:

	CHIN STRAP FASTENED			HELMET VISOR LOWERED		
	YES	NO	UNK	YES	NO	UNK
1. BEFORE EMERGENCY	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. DURING EGRESS	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. DURING CHUTE LANDING	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. CHIN STRAP FASTENED SNUGLY ?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. NAPE STRAP FASTENED SNUGLY ?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

5. ZERO LANYARD:

- | | |
|---|---|
| A. WHEN CONNECTED | B. SURVIVAL FACTOR |
| <input type="checkbox"/> 1. AVAILABLE, NOT CONNECTED | <input checked="" type="checkbox"/> 4. NOT A FACTOR IN SURVIVAL |
| <input checked="" type="checkbox"/> 2. PRIOR TO EMERGENCY | <input type="checkbox"/> 5. FACTOR IN SURVIVAL |
| <input type="checkbox"/> 3. DURING EMERGENCY | <input type="checkbox"/> 6. NOT A FACTOR IN NON-SURVIVAL |
| <input type="checkbox"/> 4. TIME UNKNOWN | <input type="checkbox"/> 7. FACTOR IN NON-SURVIVAL |
| <input type="checkbox"/> 5. NA/NOT AVAILABLE | <input type="checkbox"/> 8. UNKNOWN IF FACTOR |
| <input type="checkbox"/> 6. UNKNOWN | |

6. AUTOMATIC LAP BELT RELEASE **No chance**

- | | |
|--|--|
| <input type="checkbox"/> 1. DID NOT OPEN OR RELEASE | <input type="checkbox"/> 3. OPENED INADVERTENTLY |
| <input type="checkbox"/> 2. RELEASED AUTOMATICALLY AS DESIGNED | <input type="checkbox"/> 4. UNKNOWN HOW RELEASED |
| <input type="checkbox"/> 3. OPENED MANUALLY | <input type="checkbox"/> 5. UNKNOWN IF RELEASED |

7. REMOVAL OF AIRCRAFT CANOPY

- | | |
|--|---|
| A. INTENT | B. INITIATED BY: |
| <input type="checkbox"/> 1. INTENTIONAL | <input type="checkbox"/> 1. THIS INDIVIDUAL |
| <input type="checkbox"/> 2. UNINTENTIONAL, SELF-INDUCED | <input type="checkbox"/> 2. ANOTHER INDIVIDUAL |
| <input checked="" type="checkbox"/> 3. UNINTENTIONAL, MECHANICAL | <input type="checkbox"/> 3. UNKNOWN Thrown off at impact |
| <input type="checkbox"/> 4. UNKNOWN | |

7. REMOVAL OF AIRCRAFT CANOPY (Continued)

- | | |
|---|--|
| C. REMOVAL | D. METHOD |
| <input type="checkbox"/> 1. DEFINITELY NOT ATTEMPTED | <input type="checkbox"/> 1. ARM REST/LEG BRACE |
| <input checked="" type="checkbox"/> 2. ACCOMPLISHED Impact | <input type="checkbox"/> 2. FACE CURTAIN |
| <input type="checkbox"/> 3. ATTEMPTED (UNSUCCESSFUL) | <input type="checkbox"/> 3. SEAT PAN HANDLE |
| <input type="checkbox"/> 4. UNKNOWN IF ATTEMPTED | <input type="checkbox"/> 4. MANUALLY UNLOCKED |
| | <input checked="" type="checkbox"/> 5. EXTERNAL FORCE Probable impact |
| | <input type="checkbox"/> 6. CANOPY JETTISON HANDLE |
| | <input checked="" type="checkbox"/> 7. UNKNOWN |
| | <input type="checkbox"/> 8. OTHER (DESCRIBE) |

8. EJECTION **Evidently not attempted**

- | | |
|---|--|
| A. INTENT | C. METHOD |
| <input type="checkbox"/> 1. INTENTIONAL | <input type="checkbox"/> 1. ARM REST/LEG BRACE |
| <input type="checkbox"/> 2. UNINTENTIONAL | <input type="checkbox"/> 2. FACE CURTAIN |
| <input checked="" type="checkbox"/> 3. UNKNOWN | <input type="checkbox"/> 3. SEAT PAN HANDLE |
| | <input type="checkbox"/> 4. SEAT SEQUENCER |
| B. INITIATED BY | <input checked="" type="checkbox"/> 5. IMPACT |
| <input type="checkbox"/> 1. THIS PERSON | <input type="checkbox"/> 6. FIRE |
| <input type="checkbox"/> 2. ANOTHER PERSON | <input type="checkbox"/> 7. MECHANICAL FAILURE |
| <input checked="" type="checkbox"/> 3. EXTERNAL FORCE | <input type="checkbox"/> 8. OTHER EXTERNAL FORCE |
| <input type="checkbox"/> 4. UNKNOWN | <input type="checkbox"/> 9. UNKNOWN |

9. BODY POSITION AT EJECTION (As compared to optimal)

No ejection

	A. HEAD	B. NECK	C. FEET	D. ELBOWS
OPTIMAL 1				
FORWARD 2				
UPWARD 3				
LATERAL 4				
UNKNOWN 5				

10. POSITION OF EJECTION SEAT

- | | |
|--|---|
| <input type="checkbox"/> 1. FULL UP | <input type="checkbox"/> 3. INTERMEDIATE POSITION |
| <input checked="" type="checkbox"/> 2. FULL DOWN | <input type="checkbox"/> 4. UNKNOWN |

11. METHOD OF SEPARATING MAN FROM SEAT

- | | |
|--|---|
| <input type="checkbox"/> 1. DID NOT SEPARATE | <input type="checkbox"/> 4. PERSONNEL PARACHUTE |
| <input type="checkbox"/> 2. SEAT SEPARATOR | <input checked="" type="checkbox"/> 5. OTHER Impact forces |
| <input type="checkbox"/> 3. SPONTANEOUS/TUMBLING | <input type="checkbox"/> 6. UNKNOWN |
| <input type="checkbox"/> 4. PUSHED SELF AWAY | |

CONTINUED ON REVERSE SIDE

NAME
BACHMEIER, James F. Jr.

SERIAL NO.
(b) (6)

A/C
A-7A

ROUND
152664

12. TYPE OF SEAT SEPARATION

- ☐ 8. NONE
☐ 1. ROTARY
☐ 2. BLADDER
☐ 3. PARACHUTE
☐ 4. SHUSING LANYARD

**Impact forces and
fire on ground**

13. METHODS OF DEPLOYING PARACHUTE

- ☒ 8. NOT DEPLOYED
☐ 1. AUTOMATIC TIMER
☐ 2. ANEROID
☐ 3. BALLISTIC DEVICE
☐ 4. ZERO LANYARD
☐ 5. STATIC LINE
☐ 6. MANUAL
☐ 9. OTHER
☐ 9. UNKNOWN

14. PARACHUTE OPENING SHOCK **None - not activated**

- ☐ 8. NEGLIGIBLE
☐ 1. MODERATE
☐ 3. SEVERE
☐ 9. UNKNOWN

15. OSCILLATIONS

8-NEGLIGIBLE 1-MODERATE 2-SEVERE 9-UNKNOWN

- A. DURING DESCENT
 B. DURING LANDING

No descent

16. PARACHUTE DAMAGE (Give number of)

1. SEVERED SHROUD LINES
 2. MISSING PANELS
 3. TORN PANELS-MAJOR
 4. TORN PANELS-MINOR

All destroyed in fire

17. CAUSE OF PARACHUTE DAMAGE

- ☐ 1. OPENING SHOCK
☐ 2. FOULED ON EJECTION SEAT
☐ 3. FOULED ON A/C
☐ 4. FIRE
☐ 5. ON LANDING
☐ 6. IN TREES
☐ 7. DRAGGING
☐ 8. OTHER (DESCRIBE)
☐ 9. UNKNOWN

**Intense ground
fire**

18. FOUR LINE CUT DISREGARD, (Air Force Item only)

19. DIRECTION FACED AT CHUTE LANDING **No chute landing**

- ☐ 1. DIRECTLY FACING
☐ 2. FACING AWAY
☐ 3. QUARTERING, FACING
☐ 4. QUARTERING, BACK
☐ 5. DIRECTLY SIDWAYS
☐ 9. UNKNOWN

20. LANDING CONDITIONS

- A. TOTAL WEIGHT UNDER PARACHUTE: **210** LBS
 B. SURFACE WINDS _____ KNOTS
 C. DRAGGED BY CHUTE ☐ 1. YES ☐ 2. NO
 D. DISTANCE DRAGGED: _____ YARDS

21. PARACHUTE LANDING POSITION TECHNIQUES **None**

- A. ☐ 8. COULD NOT SEE
☐ 1. LOOKING AHEAD
☐ 2. LOOKING DOWN
☐ 8. OTHER
☐ 9. UNKNOWN
 B. ☐ 1. FELL OBLIQUELY
☐ 2. FELL BACKWARD
☐ 3. FELL FORWARD
☐ 8. OTHER
☐ 9. UNKNOWN
 C. ☐ 1. MUSCLES TENSED
☐ 2. MUSCLES TOO TENSE
☐ 3. TOO RELAXED
☐ 8. OTHER
☐ 9. UNKNOWN
 D. ☐ 1. PROPER POSITION
☐ 2. KNEES LOCKED
☐ 3. ARMS IN POOR POSITION
☐ 8. OTHER
☐ 9. UNKNOWN

22. DEPLOYED BEFORE LANDING **None**

	1 - YES	8 - NO	9 - UNKNOWN
A. SURVIVAL KIT		<input checked="" type="checkbox"/>	
B. LIFE RAFT		<input checked="" type="checkbox"/>	
C. LIFE VEST		<input checked="" type="checkbox"/>	

23. CANOPY DEFLATION POCKETS

- ☐ 8. NOT EFFECTIVE IN COLLAPSING CHUTE
☐ 1. AIDED IN COLLAPSING CHUTE
☐ 7. NOT INSTALLED
☐ 8. UNKNOWN IF INSTALLED
☐ 9. UNKNOWN IF EFFECTIVE

Chute didn't open

REMARKS: **No ejection, no bailout, no parachute deployment, no survival.**

Pilot thrown from aircraft on impact and (b) (6)

(b) (6)

1. SURVIVAL TRAINING

*Use Code at right to indicate the role this person's training played in survival.

2 - NOT A FACTOR
1 - DEFINITELY HELPED
2 - POSSIBLY HELPED

3 - LACK OF TRAINING DEFINITE FACTOR
4 - LACK OF TRAINING POSSIBLE FACTOR
9 - ROLE UNKNOWN

TYPE TRAINING	COURSE AND SPONSOR	PLACE ACCOMPLISHED	COMPLETED		ROLE
			Start	Year	
A. WATER SURVIVAL:					
1. MAINTENANCE SWIM	NAS Lemoore	NAS Lemoore	Aug	68	0
2. DILBERT DUNKER	USNAVSCOLAVMED	Pensacola, Florida	Aug	67	0
3. PARACHUTE DRAG	USNAVSCOLAVMED	Pensacola, Florida	Aug	67	0
4. IMMERSED COCKPIT	None				0
5. IMMERSED SEAT	None				0
B. JUNGLE SURVIVAL	None				0
C. ARCTIC SURVIVAL	None				0
D. DESERT SURVIVAL	None				0
E. MOUNTAIN SURVIVAL	None				0
F. SURVIVAL (GENERAL)	D WEST Fastupac	San Diego, Calif.	Oct	68	0

2. CONDITIONS PREVAILING AT SURVIVAL/RESCUE SITE (If widely variable, give range)

A. WATER TEMPERATURE <u>N/A</u> °F	F. TERRAIN	G. WEATHER
B. AIR TEMPERATURE <u>54</u> °F	<input checked="" type="checkbox"/> 1. OPEN GROUND	<input checked="" type="checkbox"/> 1. CLEAR
C. SURFACE WINDS <u>0</u> KNOTS	<input type="checkbox"/> 2. WOOD/JUNGLE	<input type="checkbox"/> 2. OVERCAST
D. WAVE HEIGHT <u>N/A</u> FEET	<input type="checkbox"/> 3. MOUNTAINS	<input type="checkbox"/> 3. FOG
E. WAVE FREQUENCY <u>N/A</u> PER MIN.	<input type="checkbox"/> 4. DESERT	<input type="checkbox"/> 4. RAIN
	<input type="checkbox"/> 5. WATER	<input type="checkbox"/> 5. SHOW
	<input type="checkbox"/> 6. ICE/SNOW	<input type="checkbox"/> 6. BREEZ
	<input type="checkbox"/> 7. SWAMP	<input type="checkbox"/> 7. HAIL
	<input checked="" type="checkbox"/> 8. OTHER	<input checked="" type="checkbox"/> 8. OTHER
	<input type="checkbox"/> 9. UNKNOWN	<input type="checkbox"/> 9. UNKNOWN
	Beside Runway	Pitch black night

3. TIME LAPSE SEQUENCE FOR RESCUE EVENTS (Give time lapse in hours and minutes from time of mishap)

For actual rescue vehicle and personnel and others who took an active part in the rescue sequence but did not actually recover this individual. See Instructions for details.

	ACTUAL	OTHER ASSIST	OTHER ASSIST	LIGHT CONDITIONS			
				Day	Night	Dark	Dark
A. RESCUE PERSONNEL NOTIFIED THAT MISHAP HAD OCCURRED	0128	SAR	helo		X		
B. RESCUE VEHICLE DEPARTED	0128+	on standby			X		
C. THIS INDIVIDUAL LOCATED BY RESCUE PERSONNEL	0130				X		
D. THIS INDIVIDUAL PHYSICALLY REACHED BY RESCUE VEHICLE PERSONNEL	0140	Ground units			X		
E. THIS INDIVIDUAL ACTUALLY ABOARD RESCUE VEHICLE OR RESCUE ATTEMPT ABANDONED	0210	on standby					
F. RESCUE COMPLETED (PERSON RETURNED TO STATION, HOSPITAL, ETC.)	0215						

4. A. TIME THIS INDIVIDUAL SPENT IN WATER None HRS. 0 MIN. B. TIME THIS INDIVIDUAL SPENT IN LIFE RAFT 0 HRS. 0 MIN.

5. AT TIME OF RESCUE ALERT, DISTANCE IN MILES FROM MISHAP SITE TO:

A. ACTUAL RESCUE VEHICLE 1 1/2 miles B. NEAREST ASSIST RESCUE VEHICLE 1 1/2 miles

6. PERSONNEL/VEHICLES PARTICIPATING IN RESCUE

A. VEHICLE PERFORMING ACTUAL RECOVERY OF THIS PERSON

1. TYPE/MODEL: Lemoore Ambulance 2. LOCATION WHEN ALERTED: Ops Dispensary 3. DUTY WHEN ALERTED: SAR

B. DID RESCUE PERSONNEL LEAVE VEHICLE TO ASSIST IN RESCUE?

IF SO, HOW?

- ☒ 1. YES ☐ 2. NO ☐ 3. UNKNOWN
- ☐ A. PARACHUTED ☐ C. DESCENDED LINE/LADDER/NET ☒ E. NORMAL GROUND/WATER
- ☐ B. JUMPED WITHOUT PARACHUTE ☐ D. LOWERED BY HOIST ☐ F. OTHER

C. LIST OTHER VEHICLES PARTICIPATING IN RESCUE EFFORT: (OTHER ASSIST IN ITEM 3)

OTHERS WHO STOOD BY READY TO RENDER ASSISTANCE IF REQUIRED: MB-5 fire fighting unit
SAR helo, Ground units

D. NUMBER SEARCH AND RESCUE HOURS 47 minutes

CONTINUED ON REVERSE SIDE

NAME BACHMEIER, James F. Jr.	SERIAL NO. (b) (6)	A/C A-7A	DUINO 152664
---------------------------------	-----------------------	-------------	-----------------

7. RESCUE EQUIPMENT USED (Use numbers to show sequence)

- | | |
|---|--|
| <input type="checkbox"/> A - SLING | <input type="checkbox"/> M - GRAPNEL |
| <input type="checkbox"/> B - SEAT | <input type="checkbox"/> N - BOARDING LADDER |
| <input type="checkbox"/> C - CARGO NET | <input type="checkbox"/> P - KNIFE/AXE/SAW |
| <input type="checkbox"/> D - ROPE | <input type="checkbox"/> Q - MAKESHIFT CARRIER/SUPPORT |
| <input type="checkbox"/> E - LIFE RING | <input type="checkbox"/> R - FIRST AID EQUIPMENT |
| <input type="checkbox"/> F - BASKET | <input type="checkbox"/> S - TREE PENETRATOR SEAT |
| <input type="checkbox"/> G - BOOM NET | <input type="checkbox"/> T - HELICOPTER PLATFORM |
| <input type="checkbox"/> H - DAVIT | <input type="checkbox"/> U - STRETCHER |
| <input type="checkbox"/> J - RAFT | <input type="checkbox"/> V - CABLE CUTTERS |
| <input type="checkbox"/> K - WEBBING CUTTERS | <input type="checkbox"/> W - HELICOPTER RESCUE BOOM |
| <input type="checkbox"/> L - CHICAGO GRIP | <input type="checkbox"/> X - BILLY PUGH NET |
| <input checked="" type="checkbox"/> Y - OTHER (DESCRIBE) <u>ambulance and stretcher</u> | |

8. RESCUE ALERTING MEANS (Use numbers to show sequence)

- | | |
|---|--|
| <input checked="" type="checkbox"/> A - WITNESSED | <input type="checkbox"/> H - RADIO SURVIVAL TYPE |
| <input type="checkbox"/> B - RADAR SURVEILLANCE | <input type="checkbox"/> J - OTHER RADIO REPORT |
| <input type="checkbox"/> C - OVERDUE REPORT TO SAR | <input type="checkbox"/> K - VISUAL SIGNALLING EQUIPMENT |
| <input type="checkbox"/> D - AIRBORNE RAPID RELAY | <input type="checkbox"/> L - AUDIO SIGNALLING EQUIPMENT |
| <input checked="" type="checkbox"/> E - CRASH PHONE | <input type="checkbox"/> M - SURVIVOR REPORT |
| <input type="checkbox"/> F - OTHER TELEPHONE | <input type="checkbox"/> N - LOSS OF RADIO CONTACT |
| <input type="checkbox"/> G - RADIO MAY-DAY CALL | <input type="checkbox"/> P - SMOKE/FIRE-CRASH SCENE |
| <input type="checkbox"/> Y - OTHER (DESCRIBE) _____ | |

9. ALERTING/COMMUNICATIONS PROBLEMS None

- | | |
|--|---|
| <input type="checkbox"/> A - POOR RADIO RECEPTION | <input type="checkbox"/> D - AIRCRAFT RADIO/IFF EQUIPMENT INOPERATIVE |
| <input type="checkbox"/> B - TELEPHONE LINE BUSY | <input type="checkbox"/> E - POOR RADIO PROCEDURES |
| <input type="checkbox"/> C - POOR RADIO DISCIPLINE | <input type="checkbox"/> Y - OTHER _____ |

10. DELAYS IN DEPARTURE OF RESCUE VEHICLES None

- | |
|--|
| <input type="checkbox"/> A - VEHICLE OPERATOR NOT AVAILABLE |
| <input type="checkbox"/> B - VEHICLE NOT READY |
| <input type="checkbox"/> C - VEHICLE CREW NOT AVAILABLE |
| <input type="checkbox"/> D - COMMUNICATIONS BREAKDOWN |
| <input type="checkbox"/> E - COMPLETING PREVIOUSLY ASSIGNED DUTIES |
| <input type="checkbox"/> F - LACK OF INFORMATION ON CRASH SITE |
| <input type="checkbox"/> G - NATURE OF TERRAIN |
| <input type="checkbox"/> H - WEATHER |
| <input type="checkbox"/> Y - OTHER _____ |

11. RESCUE VEHICLE PROBLEMS ENROUTE None

- | | |
|--|--|
| <input type="checkbox"/> A - HEADWIND | <input type="checkbox"/> E - NATURE OF TERRAIN |
| <input type="checkbox"/> B - POOR VISIBILITY | <input type="checkbox"/> F - OTHER OBSTRUCTIONS (FENCES, ETC.) |
| <input type="checkbox"/> C - HIGH SEA STATE | <input type="checkbox"/> G - RESCUERS LOST |
| <input type="checkbox"/> D - MECHANICAL PROBLEMS | <input type="checkbox"/> H - WEATHER |
| <input type="checkbox"/> Y - OTHER _____ | |

12. PROBLEMS IN LOCATING INDIVIDUAL (OR KEEPING IN SIGHT) None

- | | |
|--|---|
| <input type="checkbox"/> A - HEAVY SEAS | <input type="checkbox"/> D - PRECIPITATION |
| <input type="checkbox"/> B - TREES | <input type="checkbox"/> E - DARKNESS |
| <input type="checkbox"/> C - FOG/CLOUDS | <input type="checkbox"/> F - RADIO INTERFERENCE |
| <input type="checkbox"/> G - CONFUSION DUE TO OTHER LIGHTS | |
| <input type="checkbox"/> H - MALFUNCTION OF DIRECTIONAL EQUIPMENT | |
| <input type="checkbox"/> J - LACK OF CORRECT INFORMATION ON LOCATION OF SURVIVOR | |
| <input type="checkbox"/> K - INABILITY TO VISUALLY DISTINGUISH SURVIVOR FROM TERRAIN | |
| <input type="checkbox"/> L - LOSS OF RADIO/RADAR CONTACT | |
| <input type="checkbox"/> M - SURVIVOR'S FAILURE TO USE SIGNALLING EQUIPMENT | |
| <input type="checkbox"/> Y - OTHER _____ | |

13. LOCATOR MEANS

Consult Instructions for listing of specific locator means and enter under appropriate categories. Use numbers to indicate sequence of observance.

GENERAL	PYROTECHNICS	ELECTRONIC SIGNAL DEVICES	BALLISTICS	AUDITORY	VISUAL
Located visually in fireball just to left of runway - no special signalling devices used - used only normal tower and ambulance radios.					

CONTINUED ON NEXT PAGE

- | | | |
|--|--|---|
| <input type="checkbox"/> 81 - INADEQUATE FLOTATION GEAR | <input type="checkbox"/> 89 - PULLED DOWN BY SINKING PARACHUTE | <input type="checkbox"/> 18 - TOPOGRAPHY (SWAMPS, MOUNTAINS, DESERTS, ETC.) |
| <input type="checkbox"/> 82 - INADEQUATE COLD WEATHER GEAR | <input type="checkbox"/> 10 - ENTANGLEMENT (OTHER THAN PARACHUTE) | <input type="checkbox"/> 19 - DARKNESS |
| <input type="checkbox"/> 83 - LACK OF SIGNALLING EQUIPMENT | <input type="checkbox"/> 11 - UNFAMILIAR WITH PROCEDURES/EQUIPMENT | <input type="checkbox"/> 20 - THROWN OUT OF RAFT |
| <input type="checkbox"/> 84 - LACK OF OTHER EQUIPMENT | <input type="checkbox"/> 12 - CONFUSED, DAZED, DISORIENTED | <input type="checkbox"/> 21 - HAMPERED BY HELICOPTER DOWNWASH |
| <input type="checkbox"/> 85 - ENTANGLEMENT (PARACHUTE) | <input type="checkbox"/> 13 - INCAPACITATED BY INJURY | <input type="checkbox"/> 22 - PROBLEM BOARDING RESCUE VEHICLE |
| <input type="checkbox"/> 86 - DRAGGING (PARACHUTE) | <input type="checkbox"/> 14 - POOR PHYSICAL CONDITION | <input type="checkbox"/> 23 - THIRST |
| <input type="checkbox"/> 87 - PARACHUTE HARDWARE PROBLEM | <input type="checkbox"/> 15 - EXPOSURE (HEAT, COLD, SUNBURN, ETC.) | <input type="checkbox"/> 24 - HUNGER |
| <input type="checkbox"/> 88 - ENTRAPMENT IN AIRCRAFT | <input type="checkbox"/> 16 - FATIGUE | <input type="checkbox"/> 25 - INSECTS, SNAKES, ANIMALS, ETC. |
| <input type="checkbox"/> 89 - OTHER _____ | <input type="checkbox"/> 17 - WEATHER | <input type="checkbox"/> 26 - SHARKS |

15. PROBLEMS THAT COMPLICATED RESCUE OPERATIONS

Intense fire

- | | |
|---|---|
| <input type="checkbox"/> 81 - FAILURE OF RESCUE VEHICLE (MECHANICAL PROBLEMS) | <input type="checkbox"/> 15 - PANIC/INAPPROPRIATE ACTIONS OF PERSON BEING RESCUED |
| <input type="checkbox"/> 82 - INADEQUACY/LACK OF RESCUE VEHICLE | <input type="checkbox"/> 16 - RESCUE VEHICLE ACCIDENT |
| <input type="checkbox"/> 83 - FAILURE OF RESCUE EQUIPMENT (HOIST, ETC.) | <input type="checkbox"/> 17 - COMMUNICATIONS PROBLEMS |
| <input type="checkbox"/> 84 - INADEQUACY/LACK OF RESCUE EQUIPMENT | <input type="checkbox"/> 18 - DRAG/ENTANGLEMENT BY DEPLOYED PARACHUTE |
| <input type="checkbox"/> 85 - INADEQUACY OF RESCUE PERSONNEL KNOWLEDGE/TRAINING | <input type="checkbox"/> 19 - TOPOGRAPHY (ROUGH SEAS, MOUNTAINS, ETC.) |
| <input type="checkbox"/> 86 - INADEQUATE MEDICAL EQUIPMENT | <input type="checkbox"/> 20 - INTERFERENCE FROM OTHER VEHICLES |
| <input type="checkbox"/> 87 - INADEQUATE MEDICAL FACILITIES | <input type="checkbox"/> 21 - VICTIM PULLED AWAY BY EXTERNAL FORCES |
| <input type="checkbox"/> 88 - VEHICLE OPERATOR FACTOR (POOR PROCEDURE) | <input type="checkbox"/> 22 - WEATHER |
| <input type="checkbox"/> 89 - RESCUE CREWMAN ASSIST HESITANCY | <input type="checkbox"/> 23 - DARKNESS |
| <input checked="" type="checkbox"/> 10 - FIRE/EXPLOSION | <input type="checkbox"/> 24 - WEIGHT/DRAG PROBLEM NOT DUE TO PARACHUTE |
| <input type="checkbox"/> 11 - ENTRAPMENT IN AIRCRAFT | <input type="checkbox"/> 25 - HAMPERED BY PERSONNEL/SURVIVAL EQUIPMENT OF PERSON BEING RESCUED |
| <input type="checkbox"/> 12 - PHYSICAL LIMITATIONS OF RESCUE PERSONNEL | <input type="checkbox"/> 26 - FLOATING DEBRIS |
| <input type="checkbox"/> 13 - PHYSICAL LIMITATIONS OF PERSON BEING RESCUED | <input type="checkbox"/> 27 - PRIMARY RESCUE DELAYED AWAITING FUTILE ATTEMPTS BY OTHER RESCUERS |
| <input type="checkbox"/> 14 - CARELESSNESS OF RESCUE PERSONNEL | <input type="checkbox"/> 28 - HAMPERED BY HELICOPTER DOWNWASH |
| <input type="checkbox"/> 15 - OTHER _____ | |

16. INDIVIDUAL'S PHYSICAL CONDITION

	DURING RESCUE	AFTER RESCUE		DURING RESCUE	AFTER RESCUE
1. FULLY ABLE TO ASSIST	1 -	A -	5. FATAL ON RECOVERY - DROWNED		E -
2. PARTIALLY ABLE TO ASSIST	2 -	B -	6. RECOVERED - LIVE - DIED FROM INJURIES		F -
3. IMMOBILE OR UNCONSCIOUS	3 -	C -	7. LOST DURING RESCUE ATTEMPT - PRESUMED DROWNED		G -
4. FATAL ON RECOVERY - DUE TO INJURIES	<input checked="" type="checkbox"/>	D -	8. LOST DURING RESCUE ATTEMPT - APPARENTLY INJURED OR DROWNED		H -

17. CHECK CATEGORY OF FACTORS THAT HELPED RESCUE/RECOVERY (FROM RESCUER POINT OF VIEW)

- | | |
|--|--|
| <input checked="" type="checkbox"/> 1 - RESCUE PERSONNEL TRAINING | <input checked="" type="checkbox"/> 4 - AVAILABILITY OF RESCUE EQUIPMENT |
| <input type="checkbox"/> 2 - TRAINING OF PERSON TO BE RESCUED | <input checked="" type="checkbox"/> 7 - SUITABILITY OF RESCUE EQUIPMENT |
| <input type="checkbox"/> 3 - KNOWLEDGE OF AIRCRAFT EMERGENCY ESCAPE MEANS | <input type="checkbox"/> 8 - SURVIVOR'S TECHNIQUES |
| <input type="checkbox"/> 4 - KNOWLEDGE OF PERSONNEL EQUIPMENT RELEASES/ACTUATORS | <input type="checkbox"/> 9 - COORDINATION OF RESCUE EFFORTS |
| <input checked="" type="checkbox"/> 5 - RESCUE PROCEDURES/PRE-ACCIDENT PLANS | |

**In recovering the
body expeditiously**

NAME BACHMEIER, James F. Jr.	SERIAL NO. (b) (6)	A/C A-7A	BUND 152664
--	------------------------------	--------------------	-----------------------

See addendum I CONCLUSIONS AND ANALYSIS

See addendum II Recommendations

FLIGHT SURGEON PARTICIPATED FULLY IN INVESTIGATION	NO. OF HOURS SPENT	DATE OF REPORT
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	40	27 MAY 1969
FLIGHT SURGEON PARTICIPATED FULLY IN BOARD PROCEEDINGS	NO. OF HOURS SPENT	NO. REPORTS PREPARED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	20	ONE (MOR)
FLIGHT SURGEON'S NAME AND GRADE	DUTY STATION	
(b) (6) LCDR MC USN	ATKRON - 122	(b) (6)

ADDENDUM I

CONCLUSIONS AND ANALYSIS

1. The accident board concluded that the primary cause of this accident was the failure of the pilot, LTJG BACHMEIER, who had 400 flight hours, 82 A-7 hours, and was beginning his first night mirror landing practice, to monitor his flight instruments (night IFR/VFR flight) sufficiently to maintain a proper flight attitude to remain airborne.
2. Materiel failure/malfunction was ruled out after an exhaustive study of the wreckage. This study was greatly aided by a safety center investigator who joined the accident investigation team.
3. The possibility of an inflight fire in the oxygen mask was initially considered due to the pattern of burning inside the oxygen mask (see Enclosure 10.) This was discarded as a possibility due to lack of erratic motions of the aircraft and failure to find a similar burn pattern on the pilot's face. It is felt that this fire occurred after the impact and after the mask had been forced from the pilot's face.
4. The board concluded on the basis of consistent witness statements, ground impact scars, an exhaustive study of the flight controls and instruments and a reconstruction of the flight path using a similar aircraft, that the pilot flew the aircraft into the ground in controlled flight and unaware of his danger. See AAR Part 7, "INVESTIGATION AND ANALYSIS" for complete details.
5. Factors contributing to the pilot's break-down in scan include: 1) taking interval on aircraft breaking overhead, 2) unnecessary radio transmissions by other aircraft making the pattern more hectic than

-2-
(ADDENDUM I, Continued:)

necessary (see Enclosure 1,) 3) fatigue -- see 72 hour statement.

6. It is concluded by the board that the pilot did not recognize his difficulty and made no attempt at ejection. He was killed instantly by violent ground impact and burned severely by the fireball. The pilot came to rest 15 feet short of the cockpit.
7. The pilot was observed to be somewhat "shaky" on his first two passes (by the LSO's.) On his third pass he was noted to touch-down, add full power, then reduce power normally (at 265 feet AGL) in a transition which should have been to level flight. He instead transitioned to a nose down attitude and impacted the ground at 145 knots in controlled nearly wings level flight 4-5 seconds following the transition. The tower operator observed the entire sequence (see Enclosure 3) but was unable to warn the pilot in time as the LSO was instructing a plane in apparent trouble at the 180° position and the tower operator did not want to break in on this as he did not know for sure that BACHMEIER was in trouble until the time for action had passed. He merely called "crash" an instant before the aircraft impacted. The very gentle transition to a nose down attitude added to the tower operator not realizing that an emergency existed until it was too late.
8. In conclusion, the board feels that the pilot flew his aircraft into the ground under controlled conditions, totally unaware of his danger and that no ejection attempt was made, the pilot being thrown clear of the aircraft by impact forces. The ejection system was totally destroyed by forces of impact and intense fire. Inattention to flight instruments

for the brief 4-5 seconds while transitioning following climb, while

MOR 15-69A VA-122

SPECIAL HANDLING REQUIRED IAW OPNAVINST. 3750.6F SERIES.

-3-
(ADDENDUM I, Continued:)

distinctly


looking for his interval, caused the accident. Searching for his interval and interpreting their relative movement, distraction induced by spurious radio transmissions during his three approaches, disruption of his interval with the arrival of additional aircraft, fatigue after a long day and a demanding earlier flight, plus a mid-air collision that had occurred in the squadron a few hours earlier (and may have caused him to look outside the cockpit too long for other aircraft,) as well as having had an instrument failure on an earlier flight that day and flying an aircraft that had a gyro "gripe" fixed that day (which may have caused him to momentarily mistrust his instruments at a critical time;) all could have combined to cause a scan breakdown. The lack of a visible horizon made it a necessity to fly primarily on instruments. LTJG BACHMEIER was noted to have minor scan and instrument navigation difficulties on previous flights. He was noted to be "shaky" and possibly apprehensive on his earlier passes on this flight. Any or all of these conditions may have combined to cause scan breakdown and proved fatal to the pilot.

MOR 15-69A VA-122

SPECIAL HANDLING REQUIRED LAW OPNAVINST. 3750.6F SERIES.

ADDENDUM II

RECOMMENDATIONS

1. That the importance of adequate rest before demanding flights be re-emphasized. That pilots accordingly structure their private activities to allow for adequate rest, as schedules cannot reasonably be expected to schedule around personal habits/activities.
2. That the importance of a good scan be re-emphasized, especially as regards night IFR/VFR flying.
3. That the importance of all planes in such a pattern maintaining proper radio discipline be re-emphasized.
4. That the special danger of disorientation resulting from fixating on moving lights in a dark sky be re-emphasized.
5. That tower operators and LSO's who work night mirror landing practice meet periodically to discuss problems/dangers in the pattern to gain a clearer understanding of mutual capabilities, responsibilities and means of avoiding disasters.
6. (b) (5)

7. That aircraft with gyro "gripes" which have been fixed not be sent on night missions until they have been proven under actual flight condition on a day flight.
8. This flight involved a pilot who had experienced gyro failure on an afternoon flight. He was given an aircraft for his first night mirror landing practice flight which had had a gyro gripe on its previous flight. This gripe had been corrected by replacing a "black box" (See AAR for details) but had not been tested in actual flight.

MOR 15-69A

VA 122

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6F SERIES

INDEX OF ENCLOSURES

<u>Enclosure Number</u>	<u>Enclosure Title</u>
1.	Transcript of tower tape during the accident flight (see AAR Enclosure 2.)
2.	Statement of LSO LT (b) (6) concerning accident (see AAR Enclosure 3.)
3.	Statement of control tower operator (b) (6) AC2/USN (b) (6) witness of entire accident evolution (see AAR Enclosure 4.)
4.	Statement of civilian crash crew member R. L. BASSET (see AAR Enclosure 5.)
5.	Statement of witness (b) (6) AN/USN.
6.	Statement of pilot witness in the break at the time of the accident LTJG (b) (6) USN (see AAR Enclosure 12.)
7.	AEROMEDICAL FINDINGS.
8.	AUTOPSY REPORT.
9.	POST-MORTEM X-RAY RESULTS ON pilot BACHMEIER.
10.	Photograph of oxygen mask showing over-all pattern of burning.
11.	Photograph of oxygen mask showing inside pattern of burning.

MOR 15-69A VA-122
SPECIAL HANDLING REQUIRED IAW OPNAVINST. 3750.6F SERIES.

SUMMARY AND AEROMEDICAL CONCLUSIONS FROM SOCIOPSYCHOLOGICAL INTERVIEWS
AND ANALYSIS OF PHYSIOPATHOLOGICAL FINDINGS.

LTJG BACHMEIER was a dedicated, conscientious, very highly motivated, studious Naval Aviator. Friends and his wife agree that "he just lived for flying." Flying "was his whole life -- not just an avocation." He enjoyed flying thoroughly and gave his greatest effort to it. He was dedicated and safety oriented. He was noted by nearly all IP's questioned to be the most attentive person at nearly all briefs which he attended. He had 400 total flight hours of which 82 were in the A-7 aircraft. He had arrived directly from the training command and had completed all of the A-7 replacement pilot syllabus with the exception of field mirror landing practice, carrier qualifications and three advanced stage flights. He had done well throughout the syllabus. He was designated a Naval Aviator in August, 1968. He had above average flight grades through basic and advanced training. He had minor difficulties in instrument training, being a somewhat compulsive individual, but "basic Instruments" here at Lemoore went very well although his performance was very slightly below average. He progressed smoothly in the A-7 program. Minor scan difficulties were noted but were not of a serious nature. He had recently returned from a Yuma, Arizona weapons deployment associated with night flying where he experienced minor difficulties with night low pull-outs. IP's made this problem abundantly clear to him. Generally he showed average ability. So problems were slight and consisted of: 1) slightly slow scan, 2) slightly below average instrument work, 3) low pull-out at night; all of which were carefully and forcefully discussed with IP's prior to the accident flight.

MOR 15-69A VA-122
SPECIAL HANDLING REQUIRED IAW OPNAVINST. 3750.6F SERIES.

Enclosure (7)

SUMMARY AND AEROMEDICAL CONCLUSIONS FROM SOCIOPSYCHOLOGICAL INTERVIEWS AND ANALYSIS OF PHYSIOPATHOLOGICAL FINDINGS. (Continued:)

LTJG BACHMEIER was noted to be a very confident aviator but not a chance-taker. He did know the difference between professionalism and foolhardy chance-taking. He would accept nearly any reasonable challenge.

LTJG BACHMEIER was in excellent physical and emotional health prior to and during the flight on which the accident occurred. He had studied hard and prepared well for the evening flight. His attention was perhaps concentrated on his past success of that afternoon (see 72 hour statement) rather than being concerned primarily with the flight at hand (night MLP.) He was noted to be very "pumped up" for flight in general the evening of the accident. He was not operating under the added burdens of inadequate diet, or anxiety. He may have suffered from lack of sleep as he was unable to sleep or relax between his very demanding and exhausting afternoon (1618-1830) flight and the following early morning flight. He had been continuously awake for 15½ hours prior to the accident. He was quite anxious having just flown the most demanding flight in the syllabus and being faced with his first NMLP. There was no unwise dietary intake of food or alcohol. All who saw him stated that the pilot looked rested, confident, proud and ready for flight.

No persistent factors of social, psychiatric or human significance were operative in causing the accident. The cause would appear to be as stated in "CONCLUSIONS AND DISCUSSION," this report.

LTJG BACHMEIER's adjustment to family, peer group, community position and vocational role were above reproach. He was the head of a happy, well adjusted family and loved his work.

SUMMARY AND AEROMEDICAL CONCLUSIONS FROM SOCIOPSYCHOLOGICAL INTERVIEWS AND
ANALYSIS OF PHYSIOPATHOLOGICAL FINDINGS. (Continued:)

The best summary is given in the words of his wife. "In conclusion, Jim's last hours were normal. He ate well, slept well and loved well. He loved the Navy and his flying and wouldn't have been happy doing anything else."

MOR 15-69A VA-122

SPECIAL HANDLING REQUIRED IAW OPNAVINST. 3750.6F SERIES.

Enclosure (7)

CLINICAL RECORD**AUTOPSY PROTOCOL**

DATE AND HOUR DIED		A. M.	DATE AND HOUR AUTOPSY PERFORMED		A. M.	CHECK ONE		
May 7, 1969 0128		P. M.	May 7, 1969 1230		P. M.	FULL AUTOPSY	HEAD ONLY	TRUNK ONLY
PROSECTOR		ASSISTANT						
(b) (6) CDR MC USN		None				X		

CLINICAL DIAGNOSES (Including operations)

Aircraft Accident

WITNESSES: LCDR (b) (6)
NAS Lemoore
Flt. Surg., VA-122**GROSS PROVISIONAL**

(b) (6)

PATHOLOGICAL DIAGNOSES

(b) (6)

CAUSE OF DEATH: Aircraft accident resulting in multiple extreme injuries including:

(b) (6)

AUTOPSY SURGEON:

APPROVED BY		CDR MC USN				
MILITARY ORGANIZATION (When required)		AGE	SEX	RACE	IDENTIFICATION NO.	AUTOPSY NO.
MAY 8 1969		24	M	C	(b) (6)	A69-49
PATIENT'S IDENTIFICATION (For typed or written entries give: Name—last, first, middle; grade; date; hospital or medical facility)				REGISTER NO.		WARD NO.
				DE-662		DE-662

BACHMEIER, JAMES FLORAIN LTJG USNR ACT
NAVHOSP, Oakland, Calif.

A69-49

AUTOPSY PROTOCOL
Standard Form 503
503-104

Enclosure (8)

MOR 15-69A VA 122

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6F SERIES

AIRCRAFT ACCIDENT AUTOPSY REPORT

(Attach additional sheets of 8 x 10 1/2 paper, as required)

Date
7 May 69

1. LAST NAME - FIRST NAME - MIDDLE NAME

BACHMEIER, James Florian

2. GRADE

LT(jg)

3. SERVICE NUMBER

(b) (6)

4. AGE

24

5. TIME (Date, Day, Hour)

LAST REPORT FROM PILOT

0127

CRASH

0128

CASUALTY SURVIVED

No

DEATH

0128

AUTOPSY

A-6949

6. ALTITUDE AT TIME OF
SUSSENY (Estimated)

Zero

7. AIRCRAFT

TYPE

A-7A

NUMBER

152664

8. CRASH SITE

Runway 32 left, Naval Air Station, Lemoore, California

MEDICAL MEMBER OF BOARD

9. NAME
(b) (6)

10. RANK/GRADE

LCDR

11. SERVICE NO.

(b) (6)

12. ORGANIZATIONAL UNIT

VA-122

13. MAJOR INJURIES (List anatomical findings in order of importance stating probable cause of death and if possible, check which injuries were incurred ante- or post-mortem.) (Attach additional sheets of paper, if required.)

INJURIES

(b) (6)

14. CHECK APPROPRIATE NUMBER TO INDICATE WHICH INJURIES WERE SUSTAINED: 1- In aircraft interior; 2- In aircraft on ground; 3- On ejection; 4- Other: (Indicate in which area)

out of aircraft on ground

15. GIVE BRIEF DESCRIPTION OF FACTS AND EVENTS LEADING TO ACCIDENT AND OTHER PERTINENT INFORMATION OR SUGGESTIONS. Pilot in high mirror landing pattern. Touched down on runway and added power-climbed to 265 feet AGL. Then nosed over and flew into ground in nearly level flight attitude. No ejection; explosion and fire on impact.

16. STATE BRIEFLY POSITION AND DISTANCE OF BODY OR FRAGMENTS WITH RESPECT TO AIRCRAFT WRECKAGE. Found in midst of burning wreckage 15 feet proximal to cockpit and main fuselage beside ejection seat which was fragmented and so badly charred as to be nearly unrecognizable as an ejection seat.

17. CONDITION OF WEARING APPAREL

ITEM	PRESENT	MODIFIED	TORN	DYS-COLORED	BURNED	IN-PLACE	OFF-BODY	OTHER
HARNESS					X		X	almost entirely burned off body
PROTECTIVE HELMET		X		X	X		X	smashed and burned
VISOR		X					X	no fragmented, burning
OXYGEN MASK		X	X		X		X	
GLOVES								not worn
CLOTHING					X			burned off body
SHOES OR BOOTS					X			burned off body - completely burned
Other (Specify)								

CONDITION AND EXPOSURE OF BODY AT SITE OF CRASH

18. CONDITION (Group description, extent of fragmentation and details of exposure of fragments.)

(b) (6)

19. EXPOSURE to ground impact
(X) none and intense fire

FIRE PRIOR TO CRASH

WATER

X FIRE AFTER CRASH

DIRT, MUD, ETC.

X RUL

OTHER (Specify)

SPECIFY TIME AND DEGREE Intense fire after being thrown from aircraft. (Evidently post-mortem)

20. COULD THE DECEASED HAVE TAKEN SEVERAL BREATHS BETWEEN TIME OF CRASH AND TIME OF DEATH? YES ☐ NO ☒

CONDITION AT AUTOPSY

21. BODY		22. REMARKS	23. PRESERVATION	
<input checked="" type="checkbox"/> COMPLETE <input type="checkbox"/> RIGHT ARM AMPUTATED <input type="checkbox"/> LEFT ARM AMPUTATED <input type="checkbox"/> RIGHT LEG AMPUTATED <input type="checkbox"/> LEFT LEG AMPUTATED <input type="checkbox"/> DECAPITATED <input type="checkbox"/> DISINTEGRATED		Severe 90% carbonization	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> ADVANCED POST MORTEM CHANGES <input type="checkbox"/> EARLY POST MORTEM CHANGES <input type="checkbox"/> PUTREFACTION	<input type="checkbox"/> ADVANCED POST MORTEM CHANGES <input type="checkbox"/> PUTREFACTION
			24. STATE OF NUTRITION	
			<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> OBSE <input type="checkbox"/> SLIMDER	
			THICKNESS OF SKIN AND SUBCUTANEOUS TISSUE OF ABDOMINAL WALL (CM)	
			5.7 centimeters	
			WEIGHT OF BODY	LENGTH OF BODY
			205 pounds	72 inches

25. EXTERNAL/SKELETAL EXAMINATION

(Supplement with photographs where possible. Attach additional sheets of 8 x 10 1/4 paper, as required.)

In each instance during External Examination specify exact location of the injury, abrasion, amputation, burn and degree, contusion, discoloration, hemorrhage, whether pre-existing or acquired. Also give opinion as to possible cause of injury.

In each instance during Skeletal Examination specify exact location and type of fracture or dislocation. X-rays to be used where possible. Give opinion as to probable direction and magnitude of force causing injury. Available skeletal diagrams should be used.

(b) (6)

INTERNAL

(The degree of injury should be assessed as Mild; Moderate; Severe; or Extramortal; Organs showing significance pathologic changes should be preserved. Attach additional sheets of paper, as required.)

16. BRAIN

(The whole brain should be preserved in 10% N. Formalin after tissue is removed for toxicology.)

<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	<input type="checkbox"/> AIR <input type="checkbox"/> EMBOLISM	RIGHT (b) (6)	PRE-EXISTING LESIONS (b) (6)	CONTUSION (b) (6)	(b) (6)
LACERATION None			CONDITION OF CEREBRAL VESSELS (Especially basilar) (b) (6)		

27. SPINAL CORD

(Spinal cords are important, remove at all times)

<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	PRE-EXISTING LESIONS (b) (6)	DAMAGE SUSTAINED (b) (6)
<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM NOT EXAMINED	OTHER (b) (6)
28. SINUSES		29. GLOTTIS
<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM NOT EXAMINED	<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING (b) (6)
		MEMORANDUM None

30. MIDDLE AND INNER EAR

31. EYES

<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM (Degree)	OTHER (Specify)	<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM (Degree)	OTHER (Specify)
RIGHT	NOT EXAMINED		RIGHT	(b) (6)	(b) (6)
LEFT			LEFT		

32. ORAL CAVITY

<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	OTHER LESIONS (b) (6)
--	--------------------------

33. LARYNX

<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM (b) (6)	FRACURE OF CRICOID BONE	FRACURE OF THYROID BONE	MEMORANDUM (Degree)	OTHER (Specify)
					(b) (6)

34. PLEURAL SPACE

<input type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	PRELUNGS	HEMOTHORAX (CC)	OTHER (Specify)
RIGHT		(b) (6)	
LEFT			

LESIONS OF PLEURA

(b) (6)

35. TRACHEA

<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	MEMORANDUM (b) (6)	BLOOD (b) (6)	OTHER None	EVIDENCE OF ANTE-MORTEM BURNING (b) (6)
--	-----------------------	------------------	---------------	--

36. LUNGS

(Specify lesions by lobes when indicated)

		RIGHT	LEFT	37. GREAT VESSELS	
		(b) (6)		<input checked="" type="checkbox"/> NORMAL <input type="checkbox"/> MISSING	PRE-EXISTING LESIONS None
NORMAL				TRACHEA (Describe) (b) (6)	
WEIGHT				38. PERICARDIUM	
MISSING				<input type="checkbox"/> NORMAL (b) (6)	<input type="checkbox"/> MISSING
ATELECTASIS				PRE-EXISTING LESIONS (b) (6)	
EDEMA				HEMOPERICARDIUM (CC) (b) (6)	
OLD TUBE				PETECHIAE ON VISCERAL SURFACE (b) (6)	
FAT EMBOLISM				EVIDENCE OF BURNING No	
HEMORRHAGE	(b) (6)			OTHER (Specify)	
EMPHYSEMA					
NOTTING	OLD BURNING NO OLD BURNING				
EVIDENCE OF BURNING No					
OTHER (Specify)					

INTERNAL (Continued)

19. HEART

☐ NORMAL ☐ MISSING
None of the above

☐ EVIDENCE OF
AIR EMBOLISM

 HEIGHT
380 Gm

 PATENT FORAMEN Ovale (21-2100)
Closed

 PRE-EXISTING LESIONS (Describe)
(b) (6)

INJURIES (Describe)

GRADE

 INVOLVEMENT (b) (6)
Mild (b) (6)

CAUSE (b) (6)

 ENDOCARDIAL RUPTURE
(b) (6)

 FULL THICKNESS RUPTURE
None

 STATE OF CORONARY VESSELS (Describe)
(b) (6)

40. PERITONEUM

☒ NORMAL ☐ MISSING

 PRE-EXISTING LESIONS
(b) (6)

 OTHER LESIONS (b) (6)
(b) (6)

 TYPE & AMOUNT
OF FLUID (b) (6)

41. STOMACH

☒ NORMAL ☐ MISSING

 PRE-EXISTING LESIONS
(b) (6)

DISTENTION

RUPTURE

NATURE OF CONTENTS (b) (6)

42. INTESTINES

☒ NORMAL ☐ MISSING

 PRE-EXISTING LESIONS
(b) (6)

 DISTENTION (Describe)
(b) (6)

HEMORRHAGE (Describe)

 OTHER LESIONS (b) (6)
(b) (6)

43. LIVER

☐ NORMAL ☒ MISSING

 PRE-EXISTING LESIONS
(b) (6)

TRAUMA (Degree and cause)

(b) (6)

OTHER LESIONS (Describe) (b) (6)

44. SPLEEN

☒ NORMAL ☐ MISSING

 WEIGHT PRE-EXISTING LESIONS
(b) (6)

 TRAUMA (Degree and Cause)
(b) (6)

 OTHER LESIONS
(b) (6)

45. PANCREAS

☒ NORMAL ☐ MISSING

 WEIGHT PRE-EXISTING LESIONS
(b) (6) (b) (6)

TRAUMA (Degree and Cause)

(b) (6)

OTHER LESIONS

(b) (6)

46. KIDNEY

☒ NORMAL

(b) (6)

MISSING

WEIGHT

 TRAUMATIC
LESIONS
(Describe)
OTHER
LESIONS
(Describe)

RIGHT

LEFT

47. BLADDER

☒ NORMAL ☐ MISSING

 PRE-EXISTING LESIONS
(b) (6)

DISTENTION

(b) (6)

CONTENTS

(b) (6)

RUPTURED (b) (6)

(b) (6)

48. OTHER ORGANS

(Describe any lesions or traumatic changes noted in items listed below.)

THYROID

THYROID

ADRENAL

GALL BLADDER

TESTIS AND PENIS

PROSTATE

PITUITARY

LYMPH NODES

(b) (6)

(b) (6)

(b) (6)

49. BIOCHEMICAL AND TOXICOLOGICAL STUDIES

(In the event studies are not immediately available, please forward)

YES

NO

TISSUE LACTIC ACID FOR HYPONIA

YES

NO

BLOOD SUGAR

BLOOD ALCOHOL

TISSUE CARBON MONOXIDE

TISSUE ALCOHOL

BLOOD CARBON MONOXIDE

OTHER (Specify)

OTHER (Specify)

50. HISTOLOGICAL

(Attach additional sheets giving microscopic description and summary statement as to cause of death, antecedent causes or other significant conclusions.)

51. PATHOLOGIST PERFORMING GROSS AUTOPSY

52. ADDRESS

53. PATHOLOGIST PERFORMING MICROSCOPIC STUDY

54. ADDRESS

AIRCRAFT ACCIDENT: PILOT BACHMEIER

RE: POST-MORTEM MICROSCOPIC EXAMINATION ON PILOT LTJG JAMES FLORIAN BACHMEIER III

(b) (6)

M69-40

MICROSCOPIC EXAMINATION

HEART: (b) (6)

LUNGS:

LIVER:

PANCREAS: (b) (6)

SPLEEN: (b) (6)

GASTROINTESTINAL TRACT: (b) (6)

ADRENALS: (b) (6)

KIDNEYS: (b) (6)

PROSTATE:

TESTES: (b) (6)

PITUITARY: (b) (6)

THYROID: (b) (6)

CENTRAL NERVOUS SYSTEM: (b) (6)

TRACHEA; MULTIPLE SECTIONS: (b) (6)

AUTOPSY SURGEON:

(b) (6)

CDR MC USN/cm

CERTIFIED TO BE A TRUE
COPY OF ORIGINAL DOCUMENT.

(b) (6)

(b) (6)

LCDR MC USN

ENCLOSURE (8) MCR 15-69 A VA 122

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST.3750.6F SERIES

X-RAY RESULTS POST-MORTEM ON PILOT JAMES FLORIAN BACHMEIER, III, MOR 15-69A,
VA-122

SKULL SERIES:

(b) (6)

LOWER TRUNK AND UPPER ABDOMEN:

(b) (6)

LEFT ARM:

(b) (6)

RIGHT ARM:

RIGHT FEMUR:

(b) (6)

LEFT FEMUR:

LEFT LEG:

(b) (6)

RIGHT LEG:

AP OF THE PELVIS:

(b) (6)

(b) (6)

LCDR MC USN

Film Number 12486-69 dated 7 MAY 1969

Enclosure (9)

MOR 15-69A

VA-122

SPECIAL HANDLING REQUIRED IAW OPMVINST. 3750.6F SERIES.



MESSAGE DRAFT

5ND 4462 (Rev. 7-68)

REARED FOR MINIMIZE

CLASSIFICATION
UNCLASSIFIED

FROM NAVAL SAFETY
CENTER

DRAFTER
LCDR

(b) (6)

(b) (6)

DEPT.
A.I.

RELEASED
CDR

(b) (6)

(b) (6)

ACTION

ATKRON ONE TWO TWO

V PRECEDENCE V

	Mail	
	Night Message	
X	Routine	X
	Priority	
	Op Immed.	
	Emar.	
	Flash	

INFO

NAVAIRSYSCOMHQ
NAS LENOORE

TEXT

UNCLAS E F T O

3788 A-7A BUNO 152664 ACCIDENT

1. WRECKAGE RELEASED TO SENIOR MEMBER OF BOARD.
2. INSTRUCTIONS CONTAINED IN OPNAVINST 3758.6F, PAGE 28, PARA 32D APPLY.

REFERENCE MESSAGE

TRANSMIT BY
RADIO —

CLASS OF REP.

CWO

FOR COMM. OFFICE

DATE/TIME GROUP

161935Z MAY

A7A/152664

2/A-122

15-69A

5/7/69

700/19388
4828
089

MESSAGE DRAFT

5ND 4462 (Rev. 7-68)

CLASSIFICATION
UNCLASSIFIED

DATE: 17 MAY 1969

FROM NAVAL SAFETY
CENTER

DRAFT (b) (6)
LCDR (D) (D)

DEPT.

RELEASED (b) (6)

A. I.

CDR

ACTION

ATKRON ONE TWO TWO

V	PRECEDENCE	V
	Mail	
	Night Message	
	Routine	X
X	Priority	
	Op. Immed.	
	Emar.	
	Flash	

INFO

CNO
NAVAIRSYS COMHQ
NAVAIRSYS COMREPAC
NAVAIRSYS COMREPLANT
NAVPRO DALLAS
NAS LEMOORE

TEXT

3700 A-7A BUNO 152664 ACCIDENT

1. LCDR (b) (6) USN, (b) (6) CLEARED TOP SECRET, WILL ARR FRESNO, CALIFORNIA VIA UNITED AIRLINES FLT 863 LOCAL 2215, TO CONDUCT NAVSAFECEN INVESTIGATION OF SUBJ ACDT.

2. REQ BOQ BE PROVIDED.

3. INST CONTAINED IN OPNAV 3750.6F, PG 14, PARA 24B, and PG 20, PARA 32A (PRESERVATION OF WRECKAGE) APPLY.

REFERENCE MESSAGE

TOD

427
4769

MAY 071429Z

mf

69

TRANSMIT BY
RADIO —

CLASS OF REF.

CWO

TON COMM. OFFICE

DATE/TIME GROUP

071415Z MAY

A7A/152664 VA-122 15-69A

5/7/69

*make
CI*

**STRIKE
AAR**

NNNNZCZCNASCA121CZCSLA339
PTTUZYUW RUWMHMA0039 1271237-UUUU--RUCILSA.
ZNR UUUUU
P 071237Z MAY 69
FM ATKRON ONE TWO TWO
TO RUENAAA/CNO
RUCILSA/NAVSACFEN
INFO RUHHBRA/CINCPACFLT
RUWJMUA/COMNAVAIRPAC
RUCILMA/COMNAVAIRLANT
RUEBJFA/BUPERS
RUEBBHB/CHNAVMA
RUWISAA/COMTWELVE
RUWMHVA/COMFAIRALAMEDA
RUWJAPA/COMREDATKCARAIRWING TWELVE
RUCLSKA/COMREDATKCARAIRWING FOUR
ZEN/NAS LEMOORE
RUWTATB/NAVPLANTREPO DALLAS
RUWJNDA/NAVPLANTREPO LONG BEACH
RUEBPDA/DIRECTOR ARMED FORCES INSTITUTE OF PATHOLOGY
RUWJABA/DIRECTOR AEROSPACE SAFETY, NORTON AFB
RUWJMRA/ATKRON ONE TWO TWO DET YUMA
RUCLSKA/ATKRON ONE SEVEN FOUR

00	01	011	012	013	014	015	02	02A	023	05	051
1	1		1	1			1			1	
TOR: _____							CHANNEL NUMBER <u>121B</u>				
INIT: <u>Y</u>							DATE _____				
00	10	11	12	13	20	30	40	50	60	70	80
	A	1	1	1				1	1	1	1

PAGE TWO RUWMHMA0039 UNCLAS
RUHGBMU/ATKRON TWO FIVE
ZEN/ATKRON TWO SEVEN
RUMFZFF/ATKRON THREE SEVEN
RUCLSKA/ATKRON FOUR SIX
ZEN/ATKRON FIVE SIX
RUCLSKA/ATKRON SIX SEVEN
RUCLSKA/ATKRON EIGHT TWO
RUCLSKA/ATKRON EIGHT SIX
RUHGBMU/ATKRON EIGHT SEVEN
ZEN/ATKRON NINE SEVEN
RUMFZFF/ATKRON ONE ZERO FIVE
ZEN/ATKRON ONE ONE THREE
RUYNIQM/ATKRON ONE FOUR SIX
RUMFHKG/ATKRON ONE FOUR SEVEN
RUYNIQM/ATKRON TWO ONE FIVE
RUWJATA/AIRDEVROF FIVE
RUWJABA/AIRDEVROF FOUR
RUEBEEA/NATC PAXRIV
RUWJABA/COMNAVMAISCEN PT MUGU

BT A7A/152664 VA-122 15-69A
PAGE NO. 1 OF 2

7 MAY 69 15 22Z

90507103

*5/7/69 MAY
071237Z*

PAGE THREE RUWMHMA0039 UNCLAS

UNCLAS FOR OFFICIAL USE ONLY

NAVY PRELIMINARY MESSAGE REPORT OF AIRCRAFT ACCIDENT

A. OPNAVINST 3750.6F

1. 7 MAY 1969, 0128 T, NIGHT

2. NAS LEMOORE

3. A7A BUNO 152664

4. VA-122, SER 15-69A

5. ALFA

6. BACHMEIER, JAMES F., LTJG, (b)(6) USNR, (b)(6) ACTIVE, ALFA

TOTAL HOURS 397, A7A/B HOURS 80, LAST 90 DAYS 69. NO APPARENT EJECTION ATTEMPTED

7. NONE

8. NONE

9. FCLP, 0.3 HRS, VFR NAS LEMOORE

10. TAKEOFF

11. PILOT LAUNCHED DIRECTLY INTO NIGHT FCLP PATTERN COMPLETED ONE LOW PASS AND TWO TOUCH AND GOS, AFTER THIRD PASS AIRCRAFT CLIMBED TO PATTERN ALTITUDE, NOSED OVER AND CRASHED CLOSE ABOARD RUNWAY. AIRCRAFT BURNED ON IMPACT.

12. HIGH THIN SCATTERED, 12MI VISIBILITY, WIND CALM, TEMP 54, DEW

PAGE FOUR RUWMHMA0039 UNCLAS

POINT 47, REL HUMID, 77, ALTIMETER 2983

13. NONE

14. NONE

15. NONE

16. WRECKAGE AVAILABLE FOR INVESTIGATION

17. T. W. POORE, LCDR, VA-122 ASO, AUTOVON 949-3271

BT

#0039

PAGE NO. 2 OF 2

MAY
071237Z